
WOOD DESTROYING PESTS AND ORGANISMS INSPECTION REPORT

Building No.	Street	City	ZIP	Date	of Inspection	Number of Pages
6320	Vineyard (Guest	Paso Robles	93446		9/06/2021	4
0320	House)	1 aso robics	33440		70072021	7
	riouse)			L		
1	STORY TERMITE & PEST Report #: 13066					
	○477 7		P.O. BOX 2796 Atascadero CA 93423		Registration # : PR 6987	
		Ata			Regist	tration # : PR 6987
		(805) 3	47-4707 (805) 460-0	0650	Escro	<i>N</i> # :
TERMITE &	PEST		ytermite@gmail.con		Псо	RRECTED REPORT
I E K M I I E G		0.01	y torrinto @ grinani.oori	•		TREGIED REFORT
Ordered by:		Property Owner a	and/or Party of Interest:		Report sent to:	
Devon Pitts						
Re/Max Parkside						
711 12th St						
Paso Robles CA 934	146					
COMPLETE REPOR	T 🛮 LIMITED F	REPORT 🔲	SUPPLEMENT	AL REPOR	RT REINSF	PECTION REPORT
GENERAL DESCR	IPTION:				Inspection Tag	Posted:
FURNISHED AND	FURNISHED AND OCCUPIED ONE STORY MODULAR HOME Meter Box					
Other Tags Posted:						
An inspection has been made of the structure(s) shown on the diagram in accordance with the Structural Pest Control Act. Detached porches, detached steps, detached decks and any other structures not on the diagram were not inspected.						
Subterranean Termite	es Drywood Terr	nites Fu	ngus / Dryrot 🔀	Other I	Findings 🔀	Further Inspection
If any of the above boxes are checked, it indicates that there were visible problems in accessible areas. Read the report for details on checked items.						

Diagram Not To Scale



					04-
Inspected By:	Dave Story	State License No.	OPR10259	Signature:	U ·

STORY TERMITE & PEST

Page 2 of 4 inspection report

6320 Vineyard (Guest House) Paso Robles CA 93446

Address of Property Inspected City State ZIP

09/06/2021 13066

Date of Inspection Corresponding Report No. Escrow No.

WHAT IS A WOOD DESTROYING PEST & ORGANISM INSPECTION REPORT? READ THIS DOCUMENT. IT EXPLAINS THE SCOPE AND LIMITATIONS OF A STRUCTURAL PEST CONTROL INSPECTION AND A WOOD DESTROYING PEST & ORGANISM INSPECTION REPORT.

A Wood Destroying Pest & Organism Inspection Report contains findings as to the presence or absence of evidence of wood destroying pests and organisms in visible and accessible areas and contains recommendations for correcting any infestations or infections found. The contents of Wood Destroying Pest & Organism Inspection Reports are governed by the Structural Pest Control Act and regulations.

Some structures do not comply with building code requirements or may have structural, plumbing, electrical, mechanical, heating, air conditioning or other defects that do not pertain to wood destroying organisms. A Wood Destroying Pest & Organism Inspection Report does not contain information on such defects, if any, as they are not within the scope of the licenses of either this company, or it's employees.

The Structural Pest Control Act requires inspection of only those areas which are visible and accessible at the time of inspection. Some areas of the structure are not accessible to inspection, such as the interior of hollow walls, spaces between floors, areas concealed by carpeting, appliances, furniture or cabinets. Infestations or infections may be active in these areas without visible and accessible evidence. If you desire information about areas that were not inspected, a further inspection may be performed at an additional cost. Carpets, furniture or appliances are not moved and windows are not opened during a routine inspection.

The exterior Surface of the roof was not inspected. If you want the water tightness of the roof determined, you should contact a roofing contractor who is licensed by the Contractor's State License Board.

This company does not certify or guarantee against any leakage, such as (but not limited to) plumbing, appliances, walls, doors, windows, any type of seepage, roof or deck coverings. This company renders no guarantee, whatsoever, against any infection, infestation or any other adverse condition which may exist in such areas or may become visibly evident in such area after this date. Upon request, further inspection of these areas would be performed at an additional charge.

In the event damage or infestation described herein is later found to extend further than anticipated, our bid will not include such repairs. OWNER SHOULD BE AWARE OF THIS CLOSED BID WHEN CONTRACTING WITH OTHERS OR UNDERTAKING THE WORK HIMSELF/HERSELF.

If requested by the person ordering this report, a re-inspection of the structure will be performed. Such requests must be within four (4) months of the date of this inspection. Every re-inspection fee amount shall not exceed the original inspection fee.

Wall paper, stain, or interior painting are excluded from our contract. New wood exposed to the weather will be prime painted, only upon request at an additional expense.

This company will reinspect repairs done by others within four months of the original inspection. A charge, if any, can be no greater than the original inspection fee for each reinspection. The reinspection must be done within ten (10) working days of request. The reinspection is a visual inspection and if inspection of concealed areas is desired, inspection of work in progress will be necessary. Any guarantees must be received from parties performing repairs.

NOTICE: Reports on this structure prepared by various registered companies should list the same findings (i.e. termite infestations, termite damage, fungus damage, etc.). However, recommendations to correct these findings may vary from company to company. You have a right to seek a second opinion from another company.

This Wood Destroying Pest & Organisms Report DOES NOT INCLUDE MOLD or any mold like conditions. No reference will be made to mold or mold-like conditions. Mold is not a Wood Destroying Organism and is outside the scope of this report as defined by the Structural Pest Control Act. If you wish your property to be inspected for mold or mold like conditions, please contact the appropriate mold professional.

STORY TERMITE & PEST

Page 3 of 4 inspection report

6320	Vineyard (Guest House)	Paso Robles	CA	93446	
Address of Pro	operty Inspected	City	State	ZIP	
09/06/2021	1306	6			
Date of Inspec	ction Correspond	ling Report No.	Es	crow No.	

SECTION I CONTAINS ITEMS WHERE THERE IS EVIDENCE OF ACTIVE INFESTATION, INFECTION OR CONDITIONS THAT HAVE RESULTED IN OR FROM INFESTATION OR INFECTION.

SECTION II ITEMS ARE CONDITIONS DEEMED LIKELY TO LEAD TO INFESTATION OR INFECTION BUT WHERE NO VISIBLE EVIDENCE OF SUCH WAS FOUND.

FURTHER INSPECTION ITEMS ARE DEFINED AS RECOMMENDATIONS TO INSPECT AREA(s) WHICH DURING THE ORIGINAL INSPECTION DID NOT ALLOW THE INSPECTOR ACCESS TO COMPLETE HIS INSPECTION AND CANNOT BE DEFINED AS SECTION I OR II.

The sub-floor is insulated below the substructure, This insulation could conceal infestations. We assume no responsibility for any infestations concealed by this insulation.

Earth wood contacts noted at the pier pads and skirting. This structure has been commercially pressure treated with a wood preservative. No evidence of active infestation or infection noted.

SECTION I:

3A - Fungus / Dryrot

FINDING-Fungus infection and damage noted at the wood siding and wood trim boards around the structure.

RECOMMENDATION- Remove and replace damaged wood members as necessary. Paint areas to a reasonable match. (Estimate is for the visible damage)

3B - Fungus / Dryrot

FINDING-Fungus infection and damage noted at the door jamb of the rear door.

RECOMMENDATION- Remove and replace approximately 6 to 8 inches of damaged door jamb as necessary.

3C - Fungus / Dryrot

FINDING-Fungus infection and damage noted at the rear step framing.

RECOMMENDATION- Remove and replace damaged wood members as necessary. Paint areas to a reasonable match. (Estimate is for the visible damage)

3D - Fungus / Dryrot

FINDING-Fungus infection and damage noted at the eave framing.

RECOMMENDATION- Remove damaged/infested wood members and replace with new materials. (Estimate is for the visible damage)

3E - Fungus / Dryrot

FINDING-Fungus infection and damage noted at the wood trim boards adjacent and above the rear door.

RECOMMENDATION-Remove and replace damaged wood members as necessary. Paint areas to a reasonable match. (Estimate is for the visible damage)

IF DAMAGE EXTENDS INTO INACCESSIBLE AREAS, A SUPPLEMENTAL INSPECTION WILL BE MADE AND REPORT ISSUED OUTLINING OUR FINDINGS, RECOMMENDATIONS, AND ANY ADDITIONAL COST.

SECTION II:

4A - Other Findings

STORY TERMITE & PEST

Page 4 of 4 inspection report

6320 Vineyard (Guest House) Paso Robles CA 93446

Address of Property Inspected City State ZIP

09/06/2021 13066

Date of Inspection Corresponding Report No. Escrow No.

FINDING- Earth wood contacts noted at the base of the rear steps.

RECOMMENDATION- Lower soil to eliminated earth-wood contacts and install steps on a treated lumber to eliminated earth wood contacts.

Recommendations not being performed by Story Termite & Pest must be inspected during the progress by a licensed Wood-destroying Pest and Organism Inspector. Story Termite & Pest is not responsible for, nor implies any knowledge as to the quality of work performed by others.

BY RELYING ON THIS WOOD DESTROYING ORGANISM REPORT YOU AGREE THAT ANY CONTROVERSY OR CLAIM ARISING OUT OF OR RELATING TO STORY TERMITE & PEST INSPECTION AND/OR THIS REPORT SHALL BE SETTLED BY ARBITRATION IN ACCORDANCE WITH THE CONSTRUCTION INDUSTRY ARBITRATION RULES OF THE AMERICAN ARBITRATION ASSOCIATION, AND JUDGMENT UPON THE AWARD RENDERED BY THE ARBITRATOR(S) MAY BE ENTERED IN ANY COURT HAVING JURISDICTION THEREOF.

THANK YOU FOR CHOOSING STORY TERMITE & PEST. IF YOU HAVE ANY QUESTIONS OR CONCERNS PLEASE CONTACT US AT 805-347-4707



Owner's Agent:

STORY TERMITE & PEST P.O. BOX 2796

Atascadero CA 93423 (805) 347-4707 (805) 460-0650 Storytermite@gmail.com

WORK AUTHORIZATION

Report	#: 1	13066
--------	------	-------

•	ed until a signed copy of this a	igreement has been rec	ervea.		
Address of Property :	6320 Vineyard (Guest House) Paso Robles				
City: State/ZIP:	CA 93446				
The inspection report of the co The company is authorized to	ompany dated, <u>09/06/2021</u> is incor	he items circled below from	the Termite Inspection Report for the prope	erty inspected, for a total sum o	
To guarantee all repair compl ninety (90) days. We assum not to exceed 30 days, to use	leted by this company for one year e no responsibility for work perform reasonable care in the performanc	THE COMPANY AGR from date of completion exceed by others, to be bound to		our cost breakdown for a period	
or to any shrubs, plants, or ro	of.				
month, or portion of any mont Company a security interest i	in any additional services requeste h, annual interest rate of eighteen p	percent (18%) on accounts e um for work and inspection t	ENT AGREES to pay a service charge of one and one-haceeding the ten (10) day full payment schee completed. In case of non-payment by	edule. The Owner grants to The	
		ALL PARTIES AGR	: E		
		g inspector, said work will	not be performed without additional authore the items you wish performed by The C		
other person who helps to im after a court hearing, your propaid your structural pest contraction. To preserve their right to file document entitled "Prelimina	prove your property, but is not paid operty could be sold by a court offic rol company in full if the subcontract a claim or lien against your proper	I for his or her work or supposer and the proceeds of the for, laborers or suppliers rentry, certain claimants such a aborers for wages do not h	icts to do work for you, any contractor, sulies, has a right to enforce a claim against sale used to satisfy the indebtedness. Thain unpaid. s subcontractors or material suppliers are ave to provide this notice. A Preliminary N	your property. This means that is can happen even if you have required to provide you with a	
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	ITEMS			
Prefix	Section I	Section II	Further Inspection	Other	
3A	Refer to Contractor	0.00	0.00	0.00	
3B	Combine w/3A	0.00	0.00	0.00	
3C	Combine w/3A	0.00	0.00	0.00	
3D	Combine w/3A	0.00	0.00	0.00	
3E	Combine w/3A	0.00	0.00	0.00	
4A	0.00	Refer to Contract		0.00	
Total:	0.00	0.00	0.00	0.00	
GRAND TOTAL:	0.00				
Property Owner:		Date: In:	spected By:	Date:	

Date:



INVOICE / STATEMENT

STORY TERMITE & PEST P.O. BOX 2796

Atascadero CA 93423 (805) 347-4707 (805) 460-0650 Storytermite@gmail.com Date: 09/06/2021 Report Number: 13066

Invoice Number: 13066-1

Escrow Number:

Property 6320 Vineyard (Guest House) Inspected: Paso Robles, CA 93446

Bill To: Devon Pitts

Re/Max Parkside 711 12th St

Paso Robles, CA 93446

(805) 674-3771

devonpitts13@gmail.com

Total Due: \$	50.00
Payments: \$	0.00
Invoice Total: \$	50.00
Inspection fee: \$	50.00

Description of Service

RETAIN THIS COPY FOR YOUR RECORDS

We appreciate your business!

CUT HERE _____ CUT HERE ____ CUT HERE



INVOICE / STATEMENT

STORY TERMITE & PEST P.O. BOX 2796

Atascadero CA 93423 (805) 347-4707 (805) 460-0650 Storytermite@gmail.com Date: 09/06/2021

Report Number: 13066 Invoice Number: 13066-1

Escrow Number:

Property 6320 Vineyard (Guest House) Inspected: Paso Robles, CA 93446

Bill To: Devon Pitts

Re/Max Parkside 711 12th St

Paso Robles, CA 93446

(805) 674-3771

devonpitts13@gmail.com

 Inspection fee: \$
 50.00

 Invoice Total: \$
 50.00

 Payments: \$
 0.00

 Total Due: \$
 50.00

Description of Service