## TO BE ATTACHED TO 2019 HOME INSPECTION – 301 RIVER OAKS DRIVE. TO REFLECT REPAIRS COMPLETED AFTER INSPECTION

From: Scott Munday <smunday\_51@yahoo.com>

Sent: Tuesday, May 10, 2022 1:38 PM

To: Kristi Roberts < kristi@on-point-realty.com>

Subject: Re: 301 River Oaks / Inspection / T-47 for notary

We did get most of it repaired.

- -we unstuck the turbines so they spin
- -we reconnected the dryer vent pipe in the attic so it vents properly out the house
- -we used foam to fill in gaps and cracks around the house
- -we had the front cracked window repaired
- -all deficiencies on the fireplace were fixed including the spark arrester on top
- -main electrical disconnect was added
- -all breaker box deficiencies were repaired and have had a 2nd electrician to look
- -GFCI outlets were added on the outside of the house
- -outlet wiring throughout home was fixed
- -cover was placed on air handler outlet
- -smoke detectors were added in bedrooms
- -drain pan was placed under water heater
- -drain under sink was fixed

That's all that I can think of.

Sent from my iPhone