	4-F 0111t 1115p	ection Form				
Insured/Applicant Name: Falina Selchert		Application / Policy #:				
Address Inspected: 1513 Fenway Ave, St	teinhatchee, FL 32359					
Actual Year Built: 1984		Date Inspected: <u>11/17/2022</u>				
Minimum Photo Requirements ☑ Dwelling: Each side ☑ Roof: Each slop ☑ Main electrical service panel with interio ☑ Electrical box with panel off ☑ All hazards or deficiencies noted in t	or door label					
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.						
Electrical System Separate documentation of any aluminum w	iring remediation must be provi	ded and certified by a lice	ensed electrician.			
Main Panel Type: ☑ Circuit breaker ☐ Fuse Total Amps: 200 Is amperage sufficient for current usage? ☑ Yes ☐ No (explain)		Second Panel Type: ☑ Circuit breaker ☐ Fuse Total Amps: 100 Is amperage sufficient for current usage? ☑ Yes ☐ No (explain)				
Indicate presence of any of the following:						
□ Cloth wiring □ Active knob and tube □ Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring): * If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided. □ Connections repair via COPALUM crimp □ Connections repair via AlumniConn						
Hazards Present						
☐ Blowing fuses ☐ Tripping breakers ☐ Corrosion ☐ Improper grounding ☐ Empty sockets ☐ Loose Wiring ☐ Over fusing		☐ Unsafe wiring ☐ Double taps ☐ Exposed wiring ☐ Improper breaker size ☐ Scoring ☐ Other (explain)				
General condition of the electrical system: ☑ Satisfactory ☐ Unsatisfactory (explain)						
Supplemental information						
Main Panel	Second Panel		Wiring Type			
Panel age: 20 estimat	Panel age: 38		☑ Copper			
Year last updated: 2000	Year last updated: 1984		☑ NM, BX or Conduit			

Brand/Model: Gould

Brand/Model: Cutler Hammer

HVAC System					
Central AC: ☑ Yes ☐ No					
Central heat: ✓ Yes □	No				
If not central heat, indicate	e primary heat source and fue	el type:			
Are the heating, ventilation	n and air conditioning systems	in good working o	rder? ☑ Yes ☐ No (expl	ain)	
Date of last HVAC servicin	ng/inspection:				
Hazards Present					
Wood burning stove or cer	ntral gas fireplace <i>not</i> professio	nally installed? \Box	Yes ☑No		
Space heater used as prin	nary heat source? ☐ Yes 🗹 I	No			
Is the source portable? \Box	lYes ☑No				
Does the air handler/cond ☐ Yes ☑ No	ensate line or drain pan show	any signs of blocka	age or leakage, including	water damage to the surround	ding area?
Supplemental Inform	ation				
Age of system: 13					
Year last updated: 2009	 HVAC equipment, including da	atad manufacturar's	o ploto)		
(Please attacti prioto(s) of	TVAC equipment, including do	aleu manuiaciurei s	s piate)		
Plumbing System					
Is there a temperature pre	ssure relief valve on the water	r heater? ☑ Yes 🏻	□No		
	an active leak? ☐ Yes ☑ No				
Is there any indication of a	prior leak? ∐ Yes ☑ No				
	Crawlspace				
General condition of the	following plumbing fixtures	and connections	to applicances:		
	isfactory Unsatisfactory	N/A		Satisfactory Unsatisfactory	N/A
Dishwasher Refrigerator			Toilets Sinks		
Washing Machine			Sump pump		□
Water Heater			Main shut off valve	oxdot	
Showers/Tubs			All other visible		
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).					
Supplemental Information					
Age of Piping System:		Type of pipes (check all that apply)			
X Original to home		☐ Copper			
Completely re-piped			□ PVC/CPVC		
X Partially re-piped Galvanized					
(Provide year and extent of renovation in the comments below) 2022 some distribution pipes ☐ PEX ☐ PEX ☐ Polyhytylene					
El rolybutylene					
☐ Other (specify)					

Roof (With photos of each roof slope, this section can take the place of the <i>Roof Inspection Form.</i>)							
Predominant Roof Covering material: Metal Panel Roof age (years): 10 estimate Remaining useful life (years): 30 Date of last roofing permit: Date of last update: 2010 appro If updated (check one):		Secondary Roof Covering material: Roof age (years): Remaining useful life (years): Date of last roofing permit: Date of last update: If updated (check one):					
✓ Full Replacement ☐ Partial Replacement % of replacement Overall condition:		☐ Full Replacement ☐ Partial Replacement % of replacement Overall condition:					
☑ Satisfactory		☐ Satisfactory	-				
□ Unsatisfactory (explain below) Any visible signs of damage / deterioration? (check all that apply and explain below) □ Cracking □ Cupping/Curling □ Excessive granule loss □ Exposed asphalt □ Exposed felt □ Missing/loose/cracked tabs or tiles □ Soft spots in decking □ Visible hail damage ☑ N/A □ Rust Any visible signs of leaks □ Yes ☑ No Attic/underside of decking □ Yes ☑ No Interior ceilings □ Yes ☑ No		□ Unsatisfactory (explain below) Any visible signs of damage / deterioration? (check all that apply and explain below) □ Cracking □ Cupping/Curling □ Excessive granule loss □ Exposed asphalt □ Exposed felt □ Missing/loose/cracked tabs or tiles □ Soft spots in decking □ Visible hail damage □ N/A Any visible signs of leaks □ Yes □ No Attic/underside of decking □ Yes □ No Interior ceilings □ Yes □ No					
Additional Comments/Observations (use additional pages if needed): All 4-Point Inspection Formsmust be completed and signed by a verifiable Florida-licensed inspector.							
I certify that the above statements are	e true and correct.						
DAR	Home inspector	HI13874	11/16/2022				
Inspector Signature	Title	License Number	Date				
Inspex Company Name	Home inspector License Type	3523560806 Work Phone	_				

Special Instructions:This sample *4-Point Inspection Form*includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each4-Point Inspection Form. The minimum photo requirements include:

- Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- · Open main electrical panel and interior door
- · Electrical box with the panel off
- Allhazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- A general, residential, or building contractor
- · A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Formmust be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- · Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each *4-Point Inspection Form* before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

Photos, Additional Comments or Observations

Exterior Photos



Electrical System



HVAC System

HVAC Equipment



Plumbing System

Water Heater



Under cabinet plumbing & drains







Exposed Valves





Roof

Photos of Each Slope

