

TEXAS ASSOCIATION OF REALTORS®

SELLER'S DISCLOSURE NOTICE

©Texas Association of REALTORS®, Inc. 2016

Section 5.008, Property Code requires a seller of residential property of not more than one dwelling unit to deliver a Seller's Disclosure Notice to a buyer on or before the effective date of a contract. This form complies with and contains additional disclosures which exceed the minimum disclosures required by the Code.

5652 CR 132

CONCERNING THE PRO	PERTYAL			Ha	llet	SVIIIE	e, IX. 77964		
DATE SIGNED BY SELLI	ER AND IS	S NO	A TC	SUBSTITUTE FOR ANY	INS	SPEC	ITION OF THE PROPERTY AS TIONS OR WARRANTIES THE , SELLER'S AGENTS, OR ANY	BUYER	
Seller is vis not occu	pying the F	rop	erty. or	If unoccupied (by Seller), never occupied the Prope	how rty	/ long	since Seller has occupied the P	roperty?	
				rked below: (Mark Yes (Y to be conveyed. The contract v			or Unknown (U).) ine which items will & will not convey	<i>'</i> .	
Item	YNL	J	Iten	n	Y	NU	Item	YNU	
Cable TV Wiring			Liqu	uid Propane Gas:	1		Pump: sump grinder		
Carbon Monoxide Det.			-LP	Community (Captive)		1	Rain Gutters		
Ceiling Fans		1		on Property	1		Range/Stove		
Cooktop		1		Tub	V		Roof/Attic Vents		
Dishwasher		1	Inte	ercom System			Sauna	1	
Disposal	/	1		rowave	V		Smoke Detector		
Emergency Escape Ladder(s)			Out	door Grill	Ť	1	Smoke Detector - Hearing Impaired	1	
Exhaust Fans	1,/	1	Pat	io/Decking	1		Spa	1/	
Fences		1		mbing System	V		Trash Compactor		
Fire Detection Equip.		1	Poc		1		TV Antenna	V	
French Drain		1	Pod	ol Equipment	V		Washer/Dryer Hookup	1	
Gas Fixtures	1./	1		ol Maint, Accessories		1	Window Screens	V 3	
Natural Gas Lines			Pod	ol Heater		1	Public Sewer System		
		_1							
Item		Y	N	U	Α	dditic	onal Information		
Central A/C			1	electric gas num	nber	of un	its:		
Evaporative Coolers		1	1	number of units:				88 10 10	
Wall/Window AC Units		1		number of units:					
Attic Fan(s)		1	1	if yes, describe:					
Central Heat				electric gas num	nber	of un	its:	52.70	
Other Heat		1./		if yes, describe: 5pm			ate & Electric W	100 Kes	
Oven		1		number of ovens: 1			ctric 🗸 gas other:		
Fireplace & Chimney		V		wood gas logs	mo		other:		
Carport		1	1	attached not attached	che	d			
Garage		1	V	attached not attached					
Garage Door Openers		1	1/	number of units:			number of remotes:		
Satellite Dish & Controls		1	1	owned lease from	n:				
Security System				owned lease from					
Water Heater		1			her:		number of units:		
Water Softener		Ť	1./	owned lease from		- International Contract			
Underground Lawn Sprink	der	+	J			eas c	overed:		
Septic / On-Site Sewer Fa		1	1				On-Site Sewer Facility (TAR-1407	<u>')</u>	
(TAR-1406) 01-01-16 J. A. Loredo, Properties, 101 East 4th St. Ha	Initia		by: Bu	uyer:,and	Sell	er:	B, C3 Pa	age 1 of 5 Brown- CR 132	

Produced with zipForm® by zipLogix 18070 Fifteen Mile Road, Fraser, Michigan 48026 www.zipLogix.com

J. A. Loredo, Properties, 101 East 4th St. Hallettsville, TX 77964

Jorge Loredo

Concerning the Property a	at					Hallettsvi	lle .		964		
		1	all Mub			The second second					
Water supply provided by: Was the Property built bef	: CII	[y <u>√</u> W	ell MUD	C	o-op _	_ unknown	0	other: _			
(If yes, complete, sign	and	attach		u	nknow	/N lood bood	nain	+ h = = =			
Roof Type:	i, and	attacri	1AIX-1900 (JOHICE	Ago:	leau-baseu	pair	naza	iras).		
Is there an overlay roof	COVE	ring or	the Prone	arty (_Aye.	os or roof	2011	oring d	placed over existing shingle	oxim	ate)
covering)? yes no _	unkı	nown	i ilie i Tope	erty (Silling	es or 1001	COV	ering	placed over existing shingle	s or	root
			omo listadi	41.:	. 0 1					81 00	
are need of renair?	ally 0	o If yee	doscribo (ottool	o oddi	ion 1 that a	re n	ot in w	orking condition, that have	lefect	s, or
was been deed to	0	on yes	, describe (allaci	i addi	tional sneet	s ii n	ecess	ary). Pool of Hot tub	rot	
In Champing	0 1	·V		A		The la	ne	m	y leak - Drick	do	nec
The Control of the Co			in pipe	- 0	raul	iting pro	01	-	0		
Section 2 Avenue (Sell								1020100			
aware and No (N) if you a	er) aw	are of	any defect	ts or	malfu	inctions in	any	of the	following?: (Mark Yes (Y)	f you	are
	are no	t awar	e.)	III.							
Item	Y	N	Item	10			Y	N	Item	Y	N
Basement		V	Floors				1	1	Sidewalks		1
Ceilings		1	Foundat	ion /	Slab(s)		1	Walls / Fences	1/	1
Doors		V	Interior \	Nalls				1	Windows		1
Driveways		V	Lighting					V	Other Structural Component	5	V
Electrical Systems	,	1	Plumbing	g Sys	tems			1			
Exterior Walls	V		Roof						1		
If the answer to any of the	items	in Sec	tion 2 is yes	ovn	Join /	ttoob odditi	اممما	abaat	P . 0	0	-
Cracks - need	lons.	1000	don'z is yes	, exp	iaiii (c	illacii addili	onai	sneets	s if necessary): Brick	ne	w
		van	gens	-							
The second secon			//								
Section 2 Are you (Sall											
Section 3. Are you (Sello	er) aw	are of	any of the	folic			: (M	ark Ye	es (Y) if you are aware and	No (I	N) if
you are not aware.)	er) aw	are of	any of the			conditions		ark Ye	es (Y) if you are aware and	No (I	N) if
you are not aware.) Condition	er) aw	are of	any of the	folio		conditions	n			No (I	N) if
Condition Aluminum Wiring	er) aw	are of	any of the		owing	Conditions Condition	n Fou	ndatio	n Repairs		
Condition Aluminum Wiring Asbestos Components	7114	are of	any of the		owing	Conditions Condition Previous Previous	n Fou Roc	ndatio	n Repairs airs		
Condition Aluminum Wiring Asbestos Components Diseased Trees:oak wi	ilt				owing	Conditions Condition Previous Previous Other Str	n Fou Roc	ndatio	n Repairs airs		
Condition Aluminum Wiring Asbestos Components Diseased Trees:oak wi Endangered Species/Habit	ilt				owing	Conditions Condition Previous Previous Other Str Radon G	n Fou Roc	ndatio	n Repairs airs		
Condition Aluminum Wiring Asbestos Components Diseased Trees:oak wi Endangered Species/Habit Fault Lines	ilttat on				owing	Conditions Condition Previous Previous Other Str Radon G Settling	n Fou Roc uctu as	ndatio of Repa ral Re	n Repairs airs		
Condition Aluminum Wiring Asbestos Components Diseased Trees: oak wi Endangered Species/Habit Fault Lines Hazardous or Toxic Waste	ilttat on				owing	Conditions Condition Previous Previous Other Str Radon G Settling Soil Move	n Fou Roc uctu as	ndatio of Repa ral Re	n Repairs airs pairs		
Condition Aluminum Wiring Asbestos Components Diseased Trees: oak wi Endangered Species/Habit Fault Lines Hazardous or Toxic Waste Improper Drainage	ilt_ tat on				owing	Conditions Previous Previous Other Str Radon G Settling Soil Move	Fou Roc uctu as emer	ndation of Reparal Reparal Reparal Reparate	n Repairs airs pairs		
Condition Aluminum Wiring Asbestos Components Diseased Trees:oak wi Endangered Species/Habit Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Spi	ilt_ tat on				owing	Conditions Previous Previous Other Str Radon G Settling Soil Move Subsurfa Undergro	Fou Roc ructu as emer	ndation of Repairal Repaira Repaira Repaira Repairal Repa	n Repairs pairs pairs re or Pits ge Tanks		
Condition Aluminum Wiring Asbestos Components Diseased Trees: oak wi Endangered Species/Habit Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Spi Landfill	ilttat on	Proper	ty		owing	Conditions Previous Previous Other Str Radon G Settling Soil Move Subsurfa Undergro Unplatted	Fou Roc uctu as emei ce S	ndatio of Repa ral Re nt tructur Storaç semen	n Repairs airs pairs re or Pits ge Tanks		
Condition Aluminum Wiring Asbestos Components Diseased Trees: oak wi Endangered Species/Habit Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Spi Landfill Lead-Based Paint or Lead-	ilt tat on rings	Proper	ty		owing	Conditions Previous Previous Other Str Radon G Settling Soil Move Subsurfa Undergro Unplatted Unrecord	Fou Roc ructuras emer ce S rund I Eas	ndation of Repairal R	n Repairs airs pairs re or Pits ge Tanks ts ents		
Condition Aluminum Wiring Asbestos Components Diseased Trees: oak wi Endangered Species/Habit Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Spi Landfill Lead-Based Paint or Lead- Encroachments onto the Pri	rings -Based	Proper	ty azards		owing	Conditions Previous Previous Other Str Radon G Settling Soil Move Subsurfa Undergro Unplatted Unrecord	Fou Roc ructuras emer ce S rund I Eas	ndation of Repairal R	n Repairs airs pairs re or Pits ge Tanks		
Condition Aluminum Wiring Asbestos Components Diseased Trees: oak wi Endangered Species/Habit Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Spi Landfill Lead-Based Paint or Lead- Encroachments onto the Pi Improvements encroaching	rings -Based roperty on ot	Proper	ty azards		owing N	Conditions Previous Previous Other Str Radon G Settling Soil Move Subsurfa Undergro Unplatted Unrecord	Foundas Fou	ndation of Reparal Reparal Reparal Reparator of Reparator	n Repairs airs pairs re or Pits ge Tanks ts ents		
Condition Aluminum Wiring Asbestos Components Diseased Trees: oak wi Endangered Species/Habit Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Spi Landfill Lead-Based Paint or Lead- Encroachments onto the Pr Improvements encroaching Located in 100-year Floodp	rings -Based roperty on ot	Proper	ty azards		owing N	Conditions Condition Previous Previous Other Str Radon G Settling Soil Move Subsurfa Undergro Unplatted Unrecord Urea-forn	n Fou Rocucturas emence Suund I Easted Enalden	ndation frage Repairs	n Repairs airs pairs re or Pits ge Tanks ts ents Insulation		
Condition Aluminum Wiring Asbestos Components Diseased Trees: oak wi Endangered Species/Habit Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Spi Landfill Lead-Based Paint or Lead- Encroachments onto the Pi Improvements encroaching Located in 100-year Floodp	rings -Based roperty on ot olain	Proper	ty azards		N V V V V V V V V V V V V V V V V V V V	Conditions Previous Previous Other Str Radon G Settling Soil Move Subsurfa Undergro Unplatted Urrecord Urea-forn Water Pe	n Foundas Seed Emaldonetra	ndation frage Repairs	n Repairs airs pairs re or Pits ge Tanks ts ents Insulation		
Condition Aluminum Wiring Asbestos Components Diseased Trees: oak wi Endangered Species/Habit Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Spi Landfill Lead-Based Paint or Lead- Encroachments onto the Pr Improvements encroaching Located in 100-year Floodp Located in Floodway Present Flood Ins. Coverage	rings -Based roperty on ot olain	Proper	ty azards		N V V V V V V V V V V V V V V V V V V V	Conditions Condition Previous Previous Other Str Radon G Settling Soil Move Subsurfa Undergro Unplatted Urrecord Urea-forn Water Pe Wetlands Wood Ro Active info	n Founcturas Emerican I East ed Emaldinetrican I testar	ndation of Repartment Storagement assement enhyde ation Proper tion of	n Repairs airs pairs re or Pits ge Tanks ts ents Insulation ty termites or other wood		
Condition Aluminum Wiring Asbestos Components Diseased Trees: oak wi Endangered Species/Habit Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Spi Landfill Lead-Based Paint or Lead- Encroachments onto the Pi Improvements encroaching Located in 100-year Floodp Located in Floodway Present Flood Ins. Coverage (If yes, attach TAR-1414)	rings -Based roperty on ot olain	Proper d Pt. Ha y hers' p	ty azards		N V V V V V V V V V V V V V V V V V V V	Conditions Previous Previous Other Str Radon G Settling Soil Move Subsurfa Undergro Unplatted Unrecord Urea-forn Water Pe Wetlands Wood Ro	n Founcturas Emerican I East ed Emaldinetrican I testar	ndation of Repartment Storagement assement enhyde ation Proper tion of	n Repairs airs pairs re or Pits ge Tanks ts ents Insulation ty termites or other wood		
Condition Aluminum Wiring Asbestos Components Diseased Trees: oak wi Endangered Species/Habit Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Spi Landfill Lead-Based Paint or Lead- Encroachments onto the Pi Improvements encroaching Located in 100-year Floodp Located in Floodway Present Flood Ins. Coverage (If yes, attach TAR-1414) Previous Flooding into the St	rings -Based roperty on otolain ge	Proper d Pt. Ha y hers' p	ty azards		N V V V V V V V V V V V V V V V V V V V	Conditions Condition Previous Previous Other Str Radon G Settling Soil Move Subsurfa Undergro Unplatted Unrecord Urea-forn Water Pe Wetlands Wood Ro Active info	n Foundas Roce Sementer Sement	ndation of Reparation nt tructure Storagement Easemeehyde ation Proper tion of sects (Utment f	n Repairs airs pairs re or Pits ge Tanks ts ents Insulation ty termites or other wood (VDI) for termites or WDI		
Condition Aluminum Wiring Asbestos Components Diseased Trees: oak wi Endangered Species/Habit Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Spi Landfill Lead-Based Paint or Lead- Encroachments onto the Pi Improvements encroaching Located in 100-year Flooding Located in Floodway Present Flood Ins. Coverage (If yes, attach TAR-1414) Previous Flooding into the Spi	rings -Based roperty on otolain ge	Proper d Pt. Ha y hers' p	ty azards		N V V V V V V V V V V V V V V V V V V V	Conditions Previous Previous Other Str Radon G Settling Soil Move Subsurfa Undergro Unplatted Unrecord Urea-forn Water Pe Wetlands Wood Ro Active infidestroying Previous Previous	n Foundary Rocal R	ndation of Reparation of Reparation of Reparation of Rects (Nament faite or Nament faite or Na	n Repairs airs pairs re or Pits ge Tanks ts ents Insulation ty termites or other wood VDI)		
Condition Aluminum Wiring Asbestos Components Diseased Trees: oak wi Endangered Species/Habit Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Spi Landfill Lead-Based Paint or Lead- Encroachments onto the Pi Improvements encroaching Located in 100-year Floody Located in Floodway Present Flood Ins. Coverage (If yes, attach TAR-1414) Previous Flooding into the Spi Previous Flooding onto the	rings -Based roperty on ot olain	Proper d Pt. Ha y hers' p	ty azards		N V V V V V V V V V V V V V V V V V V V	Conditions Condition Previous Previous Other Str Radon G Settling Soil Move Subsurfa Undergro Unplatted Unrecord Urea-forn Water Pe Wetlands Wood Ro Active infedestroying Previous Previous Previous Previous	n Founcturas Rocce Sound I East Enalded International I teast and I teast are given to the state of the state	ndation of Repairal Repairal Repairal Repairal Repairal Repairant Storage Seemen Easemen Easemen Easemen Proper Storage (Nation of Seets (Nati	n Repairs airs pairs re or Pits ge Tanks ts ents Insulation ty termites or other wood (VDI) for termites or WDI (VDI) damage repaired		N V
Condition Aluminum Wiring Asbestos Components Diseased Trees: oak wi Endangered Species/Habit Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Spi Landfill Lead-Based Paint or Lead- Encroachments onto the Pi Improvements encroaching Located in 100-year Floodp Located in Floodway Present Flood Ins. Coverage (If yes, attach TAR-1414) Previous Flooding onto the Previous Flooding onto the Located in Historic District Historic Property Designation	rings -Based roperty on ot olain	Proper d Pt. Hay hers' p	azards		N V V V V V V V V V V V V V V V V V V V	Conditions Condition Previous Previous Other Str Radon G Settling Soil Move Subsurfa Undergro Unplatted Unrecord Urea-form Water Pe Wetlands Wood Ro Active infi destroying Previous Previous Termite o	n Found Room I East Standard Firest Twitter Williams For	ndation of Reparation nt Storage semen asems ehyde ation Proper tion of sects (Variety of Storage Stor	n Repairs airs pairs re or Pits ge Tanks ts ents Insulation ty termites or other wood NDI) for termites or WDI NDI damage repaired		N V
Condition Aluminum Wiring Asbestos Components Diseased Trees: oak wi Endangered Species/Habit Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Spi Landfill Lead-Based Paint or Lead- Encroachments onto the Pi Improvements encroaching Located in 100-year Floody Located in Floodway Present Flood Ins. Coverage (If yes, attach TAR-1414) Previous Flooding into the Spi Previous Flooding onto the	rings -Based roperty on ot olain	Proper d Pt. Hay hers' p	azards		N V V V V V V V V V V V V V V V V V V V	Conditions Condition Previous Previous Other Str Radon G Settling Soil Move Subsurfa Undergro Unplatted Unrecord Urea-form Water Pe Wetlands Wood Ro Active infi destroying Previous Previous Termite o	Rocucturas Rocucturas Employers Rocucturas Rocuctu	ndation of Reparation nt Storage semen asems ehyde ation Proper tion of sects (Variety of Storage Stor	n Repairs airs pairs re or Pits ge Tanks ts ents Insulation ty termites or other wood (VDI) for termites or WDI (VDI) damage repaired		N V

(TAR-1406) 01-01-16

Page 2 of 5

Brown- CR 132

5652 CR 132 Hallettsville, Tx. 77964

Concernin	g the Property at	Ha	allettsville, Tx. 779	64	
If the enough	ver to any of the items in Sec	tion 2 is yes, syntain (atta	ah additional aboata	if managemy). M	0 000
if the answ	ver to any of the items in Sec	tion 5 is yes, explain (atta	in additional sneets	ii necessary). [[en Kon appr
1 gro.	ago - floor is	a living room	has new	2245 -	Cracks WI
wich	from sugary - M	for themits	works true	Œ	
-					
* <u></u>	*A single blockable as	sia desia passi savisa a sus			1
	"A single blockable ma	ain drain may cause a suc	ion entrapment naz	ard for an individi	ual.
Section 4	Are year (Seller) every of			a Duamante that	
	Are you (Seller) aware of				
	s not been previously disc			, explain (attach	additional sneets if
necessary)				
-					
S					
15 - 12- 11- 11- 11- 11- 11- 11- 11- 11- 11					
-					
Section 5	. Are you (Seller) aware o	f any of the following (lark Yes (Y) if you	are aware Mar	k No (N) if you are
not aware		any or the following (in	iaik 165 (1) ii you	are aware. mar	k ito (it) ii you aic
V N	•,				
TN	Deam additions atmost ral	madifications or other alt			
	Room additions, structural in compliance with building			lade without nece	essary permits or not
,	in compliance with building	codes in effect at the time	7.		
./	Homeowners' associations	or maintenance fees or a	ssessments If ves	complete the follo	owina.
		or maintenance rece or a		complete the folic	wing.
	Manager's name:			Phone:	
	Fees or assessments	are: \$	per	and are: ma	ndatory voluntary
	Any unpaid fees or ass	sessment for the Property	ves (\$) no	
	If the Property is in mo	ore than one association,	provide information a	about the other a	
	attach information to th				
1					
	Any common area (facilitie		ourts, walkways, or	other) co-owned	in undivided interest
	with others. If yes, complet				
	Any optional user fees	for common facilities char	ged? yes no I	f yes, describe: _	
1	Any notices of violations or	f deed restrictions or gove	rnmental ordinance	s affecting the co	andition or use of the
	Property.	deed restrictions of gove	minerital ordinarice	a allecting the co	indition of use of the
,	r roporty.				
	Any lawsuits or other legal	proceedings directly or in	directly affecting the	Property, (Include	les, but is not limited
A CONTRACTOR OF THE PARTY OF TH	to: divorce, foreclosure, he				411
1			,		
	Any death on the Property		caused by: natural o	auses, suicide, c	r accident unrelated
	to the condition of the Prop	erty.			
/	Anu condition on the Drope		- 41 1 141		
	Any condition on the Prope	rty which materially affect	s the nealth or safet	y of an individual.	•
	Any repairs or treatments,	other than routine mainte	nance made to the	Property to remo	diate environmental
	hazards such as asbestos,				diate environmental
		icates or other documenta			diation (for example
		ediation or other remediati		Albrit of the forme	diddor (for example,
1			· · · / ·		
	Any rainwater harvesting s	ystem located on the Prop	erty that is larger th	an 500 gallons ar	nd that uses a public
	water supply as an auxiliar	y water source.		-	•
1					
_ 4	The Property is located in a	propane gas system servi	ce area owned by a	propane distributi	on system retailer.
	Amu norti	that is leasted !			tarana ar exte
	Any portion of the Property	inal is located in a ground	iwater conservation	district or a subs	idence district.
(TAR-1406)	01-01-16 Initialed	d by: Buyer: ,	and Seller: 43	, ch	Page 3 of 5
		by zipLogix 18070 Fifteen Mile Road, Fra-		gix.com	Brown- CR 132

5652 CR 132

Concerning the Pro	perty at	Hallettsvi	ille, Tx. 77964	
If the answer to any	of the items in S	Section 5 is yes, explain (attach addit	tional sheets if necessary):	
	,			
Section 6. Seller	_ has _/has no	ot attached a survey of the Proper	rty.	
regularly provide i	inspections and	s, have you (Seller) received any who are either licensed as inspectach copies and complete the follow	ctors or otherwise permit	ts from persons who ted by law to perform
Inspection Date	Туре	Name of Inspector		No. of Pages
	71			710, 011 agoc
4				-
Section 8. Check Homestead Wildlife Man Other: Section 9. Have provider? yes Section 10. Have y insurance claim or which the claim was Section 11. Does to	any tax exempti agement you (Seller) ever no rou (Seller) ever a settlement or as made?yes	rely on the above-cited reports as a rer should obtain inspections from in	claim for the Property: Disabled Disabled Veter Unknown ge to the Property v for damage to the Proper not used the proceeds to	er. with any insurance erty (for example, an make the repairs for the smoke detector
requirements of C (Attach additional sh	hapter 766 of th	e Health and Safety Code?* ur y):	nknown ∡noyes. If no	or unknown, explain.
smoke detect which the dw know the buil local building A buyer may of the buyer's evidence of the specifies the	tors installed in a selling is located, lding code require official for more in require a seller to sellent the hearing impairakes a written relocations for installing in the locations i	and Safety Code requires one-family accordance with the requirements of including performance, location, and the ements in effect in your area, you not information. To install smoke detectors for the heat reside in the dwelling is hearing-import from a licensed physician; and equest for the seller to install smoke dallation. The parties may agree who smoke detectors to install.	of the building code in effect d power source requirement may check unknown above aring impaired if: (1) the buy paired; (2) the buyer gives to d (3) within 10 days after the ke detectors for the hearing	ct in the area in ts. If you do not or contact your ver or a member the seller written the effective date, ang-impaired and

(TAR-1406) 01-01-16

Page 4 of 5

Initialed by: Buyer: ____, ___ and Seller: _____, ____ Produced with zipForm® by zipLogix 18070 Fifteen Mile Road, Fraser, Michigan 48026 _______ www.zipLogix.com ______ Brown- CR 132

5652 CR 132

Concerning the Property at	Hallettsville, Tx. 77964			
the broker(s), has instructed or influenced Seller to provide i				
Signature of Seller Date	Caroline Brown 5/30/17			
Signature of Seller Date	Signature of Seller Date			
Signature of Seller Printed Name: ALTON E. Brown Sr.	Printed Name: Caroline Brown			
ADDITIONAL NOTICES TO BUYER:				
registered sex offenders are located in certain zip code	tabase that the public may search, at no cost, to determine if areas. To search the database, visit www.txdps.state.tx.us . certain areas or neighborhoods, contact the local police			
mean high tide bordering the Gulf of Mexico, the prop Protection Act (Chapter 61 or 63, Natural Resources C	rd of the Gulf Intracoastal Waterway or within 1,000 feet of the perty may be subject to the Open Beaches Act or the Dune ode, respectively) and a beachfront construction certificate or improvements. Contact the local government with ordinance or more information.			
(3) If you are basing your offers on square footage, me independently measured to verify any reported information	easurements, or boundaries, you should have those items on.			
(4) The following providers currently provide service to the p	property:			
Electric:	phone #:			
Sewer:	phone #:			
vvater:	priorie #.			
Cable:	priorie #.			
Trash:	priorie #.			
Natural Gas:	priorie #.			
Phone Company:	pnone #.			
Propane:	phone #:			
	as of the date signed. The brokers have relied on this notice be false or inaccurate. YOU ARE ENCOURAGED TO HAVE ROPERTY.			
The undersigned Buyer acknowledges receipt of the foregoing	ng notice.			
Signature of Buyer Date	Signature of Buyer Date			
Printed Name:	Printed Name:			

(TAR-1406) 01-01-16



TEXAS ASSOCIATION OF REALTORS®

INFORMATION ABOUT ON-SITE SEWER FACILITY

USE OF THIS FORM BY PERSONS WHO ARE NOT MEMBERS OF THE TEXAS ASSOCIATION OF REALTORS® IS NOT AUTHORIZED.

©Texas Association of REALTORS®, Inc., 2004

CON	5652 CR 132 CERNING THE PROPERTY AT Hallettsville, Tx. 77964	
	ESCRIPTION OF ON-SITE SEWER FACILITY ON PROPERTY:	
(1) Type of Treatment System: Septic Tank Aerobic Treatment	Unknown
(2	7) Type of Distribution System: Single pipe on both	Unknown
(3	Approximate Location of Drain Field or Distribution System: (1) Worth side a bathroom (2) But autside yard fence part drivera	Unknown
		, -
(4) Installer:	Unknown
(5) Approximate Age: 1965 (2) 1971 or 72	Unknown
B. M	AINTENANCE INFORMATION:	
(1) Is Seller aware of any maintenance contract in effect for the on-site sewer facility? If yes, name of maintenance contractor:	Yes No
	Phone: contract expiration date: Maintenance contracts must be in effect to operate aerobic treatment and certain non- sewer facilities.)	-standard" on-site
(2) Approximate date any tanks were last pumped? Never	
(3) Is Seller aware of any defect or malfunction in the on-site sewer facility? If yes, explain:	Yes No
(4) Does Seller have manufacturer or warranty information available for review?	Yes No
C. PL	ANNING MATERIALS, PERMITS, AND CONTRACTS:	
(1)	The following items concerning the on-site sewer facility are attached: planning materials permit for original installation final inspection when OS maintenance contract manufacturer information warranty information	SF was installed
(2)) "Planning materials" are the supporting materials that describe the on-site sewe submitted to the permitting authority in order to obtain a permit to install the on-site seven	
(3)) It may be necessary for a buyer to have the permit to operate an on-sit transferred to the buyer.	te sewer facility
(TAR-1	407) 1-7-04 Initialed for Identification by Buyer,and Seller,	Page 1 of 2
J. A. Lored	o, Properties, 101 East 4th St. Hallettsville, TX 77964 do Produced with zipForm® by zipLogix 18070 Fifteen Mile Road, Fraser, Michigan 48026 www.zipLogix.com Fax: 361-798-9488 Fax: 361-798-9488	9489 Brown- CR 132

D. INFORMATION FROM GOVERNMENTAL AGENCIES: Pamphlets describing on-site sewer facilities are available from the Texas Agricultural Extension Service. Information in the following table was obtained from Texas Commission on Environmental Quality (TCEQ) on 10/24/2002. The table estimates daily wastewater usage rates. Actual water usage data or other methods for calculating may be used if accurate and acceptable to TCEQ.

Facility	Usage (gal/day) without water- saving devices	Usage (gal/day) with water- saving devices
Single family dwelling (1-2 bedrooms; less than 1,500 sf) Single family dwelling (3 bedrooms; less than 2,500 sf) Single family dwelling (4 bedrooms; less than 3,500 sf) Single family dwelling (5 bedrooms; less than 4,500 sf) Single family dwelling (6 bedrooms; less than 5,500 sf) Mobile home, condo, or townhouse (1-2 bedroom)	225 300 375 450 525 225	180 240 300 360 420 180
Mobile home, condo, or townhouse (each add'l bedroom)	75	60

This document is not a substitute for any inspections or warranties. This document was completed to the best of Seller's knowledge and belief on the date signed. Seller and real estate agents are not experts about on-site sewer facilities. Buyer is encouraged to have the on-site sewer facility inspected by an inspector of Buyer's choice.

alter & Brown &	917	Carolini Brown	5/30/17
	ate	Signature of Seller Caroline Brown	Date
Receipt acknowledged by:			
Signature of Buyer Da	ate	Signature of Buyer	Date