

SELLER'S DISCLOSURE NOTICE

©Texas Association of REALTORS®, Inc. 2018

Section 5.008, Property Code requires a seller of residential property of not more than one dwelling unit to deliver a Seller's Disclosure Notice to a buyer on or before the effective date of a contract. This form complies with and contains additional disclosures which exceed the minimum disclosures required by the Code.

CONCERNING THE PROPERTY AT

746 S. FM 908 Rockdale, TX 76567

THIS NOTICE IS A DISCLOSURE OF SELLER'S KNOWLEDGE OF THE CONDITION OF THE PROPERTY AS OF THE DATE SIGNED BY SELLER AND IS NOT A SUBSTITUTE FOR ANY INSPECTIONS OR WARRANTIES THE BUYER MAY WISH TO OBTAIN. IT IS NOT A WARRANTY OF ANY KIND BY SELLER, SELLER'S AGENTS, OR ANY OTHER AGENT.

Seller Vis is not occupying the Property. If unoccupied (by Seller), how long since Seller has occupied the Property? (approximate date) or never occupied the Property

Section 1. The Property has the items marked below: (Mark Yes (Y), No (N), or Unknown (U).)

This notice does not establish the items to be conveyed. The contract will determine which items will & will not convey.

Item	Y	N	U	Item	Y	N,	U	Item	Y	N	U
Cable TV Wiring	V			Liquid Propane Gas:		V		Pump: sump grinder	T	V	
Carbon Monoxide Det.		V		-LP Community (Captive)		1		Rain Gutters		V	1
Ceiling Fans	V			-LP on Property		V		Range/Stove	V		
Cooktop	,			Hot Tub	8	V		Roof/Attic Vents	V		
Dishwasher	V	ł		Intercom System		V		Sauna		V	1
Disposal	V	5 42 164		Microwave	V			Smoke Detector	1	-	\square
Emergency Escape Ladder(s)		\checkmark		Outdoor Grill				Smoke Detector - Hearing Impaired		V	
Exhaust Fans	V			Patio/Decking	V	F		Spa		V	
Fences	V	1	si G	Plumbing System	V			Trash Compactor			
Fire Detection Equip.	V			Pool		V		TV Antenna		\checkmark	
French Drain		V		Pool Equipment		V		Washer/Dryer Hookup	1	-	<u>+</u>
Gas Fixtures		V		Pool Maint. Accessories	1	V		Window Screens	V		
Natural Gas Lines		V		Pool Heater		1		Public Sewer System		V	f

ltem	Y/N	1 U	Additional Information
Central A/C	V	1	
Evaporative Coolers		1	number of units:
Wall/Window AC Units	1 4	7	number of units: 1 GARAGE
Attic Fan(s)	11		if yes, describe:
Central Heat	V		electric gas number of units:
Other Heat	V		if yes, describe: WINDOW UNIT GARAGE
Oven	V		number of ovens: / velectric gas other:
Fireplace & Chimney	, V		wood gas logs mock other:
Carport	V		vattached not attached
Garage	V.		Vattached not attached
Garage Door Openers	V		number of units: / number of remotes: /
Satellite Dish & Controls	V	1	owned Vleased from: DISH
Security System	Ŷ		owned leased from:
Solar Panels	14		owned leased from:
Water Heater	V	1	velectric gas other: number of units:
Water Softener	V	1	owned leased from:
Other Leased Items(s)	V		if yes, describe:

Initialed by: Buyer: (TXR-1406) 02-01-18 and Seller: Page 1 of 5 Carol Matous-Jim Currey Realty, 221 Ackerman Rockdale TX 76567 Photo 5127605497 Eax: 5174463268 Carol Worley

Produced with zipForm® by zipLogix 18070 Fifteen Mile Road, Fraser, Michigan 48026 www.zipLogix.com

Magee

Concerning the Property at	746 S. FM 908 Rockdale. TX 76567
Underground Lawn Sprinkler	automatic manual areas covered:
Septic / On-Site Sewer Facility	if yes, attach Information About On-Site Sewer Facility (TXR-1407)
Was the Property built before 1978?yes (If yes, complete, sign, and attach TXR-1 Roof Type: <i>からて行と</i>	MUD co-op unknown other Sparthurst have an
Are you (Seller) aware of any of the items lis are need of repair? yes no If yes, descr AC FOL GARAGE DO	ted in this Section 1 that are not in working condition, that have defects, or ibe (attach additional sheets if necessary): A window UNIT

Section 2. Are you (Seller) aware of any defects or malfunctions in any of the following?: (Mark Yes (Y) if you are aware and No (N) if you are not aware.)

ltem	Y	N	Item	Y	N	Item	V	N/
Basement		V	Floors			Sidewalks	+-'	17
Ceilings		V,	Foundation / Slab(s)			Walls / Fences	1	
Doors		V	Interior Walls		V	Windows	1	a
Driveways		V	Lighting Fixtures			Other Structural Components	<u>v</u>	17
Electrical Systems		V	Plumbing Systems				+-	<u>۲</u>
Exterior Walls		V	Roof					

If the answer to any of the items in Section 2 is yes, explain (attach additional sheets if necessary): CRACK KITCHEW

Section 3. Are you (Seller) aware of any of the following conditions: (Mark Yes (Y) if you are aware and No (N) if you are not aware.)

Condition	Y	Ν,	Condition	Y	N
Aluminum Wiring			Previous Foundation Repairs		$\frac{1}{1}$
Asbestos Components		V	Previous Roof Repairs		1
Diseased Trees:oak wilt		\mathbf{V}	Previous Other Structural Repairs	1. 1	1
Endangered Species/Habitat on Property		V	Radon Gas	<u> </u>	1
Fault Lines		V.	Settling		1
Hazardous or Toxic Waste		V	Soil Movement		12
Improper Drainage		V.	Subsurface Structure or Pits		1
Intermittent or Weather Springs		V	Underground Storage Tanks		V
Landfill	2 3 332	V	Unplatted Easements		V
Lead-Based Paint or Lead-Based Pt. Hazards		V.	Unrecorded Easements		1v
Encroachments onto the Property		V	Urea-formaldehyde Insulation		1
Improvements encroaching on others' property		V	Water Penetration		
Located in 100-year Floodplain (If yes, attach TXR-1414)		1	Wetlands on Property		2
Located in Floodway (If yes, attach TXR-1414)		\checkmark	Wood Rot		V
Present Flood Ins. Coverage (If yes, attach TXR-1414)			Active infestation of termites or other wood destroying insects (WDI)		V
Previous Flooding into the Structures	1	V	Previous treatment for termites or WDI		11
Previous Flooding onto the Property		VY	Previous termite or WDI damage repaired		1
Located in Historic District	1	V	Previous Fires		1

Produced with zipForm® by zipLogix 18070 Fifteen Mic Road, Fraser, Michigan 48026

Concerninç	g the Property at		746 S. FM 908 Rockdale, TX 76567		10 - 10 <u>00</u> -0-0-
Historic Pro	operty Designation		Termite or WDI damage nee	eding renair	
Previous U	Jse of Premises for Manufacture phetamine		Single Blockable Main Drair Tub/Spa*		$\overline{\mathbf{V}}$
STAN	rer to any of the items in Section 3 is yes FOUNDATION FS N DAP P. WILL RECOUL COANS, SEEATTI *A single blockable main drain ma	ACT ACT	$\frac{H}{V} \frac{H}{A} \frac{Com VEh}{FOK}$ $\frac{V}{Q} \frac{G}{A} \frac{FE}{FOK}$ Introduction entrapment hazard for a	THESE	AP TYPE
necessary)	Are you (Seller) aware of any item, or s not been previously disclosed in t):	······································			······································
Section 5. not aware. <u>/ N</u>	Are you (Seller) aware of any of th .) Room additions, structural modificatio unresolved permits, or not in complian	ns, or other a	Ilterations or repairs made wi	thout necessary perm	
	Homeowners' associations or mainten Name of association: Manager's name: Fees or assessments are: \$ Any unpaid fees or assessment fo If the Property is in more than one attach information to this notice.	r the Property	Phorand ar /? yes (\$	ne:v re: mandatory v) no	
<u>/</u>	Any common area (facilities such as p with others. If yes, complete the follow Any optional user fees for common	ing:			
	Any notices of violations of deed restr Property.	ictions or gov	ernmental ordinances affecti	ng the condition or us	e of the
	Any lawsuits or other legal proceeding to: divorce, foreclosure, heirship, bank	s directly or i ruptcy, and ta	ndirectly affecting the Propert axes.)	y. (Includes, but is no	t limited
	Any death on the Property except for to the condition of the Property.	those deaths	caused by: natural causes, s	suicide, or accident u	nrelated
//////	Any condition on the Property which m	aterially affeo	ts the health or safety of an i	ndividual.	
	Any repairs or treatments, other than hazards such as asbestos, radon, lead If yes, attach any certificates or oth certificate of mold remediation or o	l-based paint ter document	, urea-formaldehyde, or mold. ation identifying the extent of		
	Any rainwater harvesting system locate water supply as an auxiliary water source	ed on the Pro	perty that is larger than 500 g	allons and that uses	a public
-	The Property is located in a propane ga	s system ser	vice area owned by a propane	distribution system re	tailer.
$_{-} \checkmark$	Any portion of the Property that is local				
TXR-1406) (11	and Seller: J.M.,	Pag	ge 3 of 5

Concerning the Property at

If the answer to any of the items in Section 5 is yes, explain (attach additional sheets if necessary):

	 	i i i				<u>a.</u>			10000-00 S	
	 				<u></u>	10150 10150	G Bayeron	0.000.000.00		1 -
	 xx									
1	 			<u></u>						
		1000-1120-110	· · · · · · · · · · · · · · · · · · ·		~~~	n			- 1	-)

Section 6. Seller has V has not attached a survey of the Property.

Section 7. Within the last 4 years, have you (Seller) received any written inspection reports from persons who regularly provide inspections and who are either licensed as inspectors or otherwise permitted by law to perform inspections? __yes v no If yes, attach copies and complete the following:

Inspection Date	Туре	Name of Inspector	No. of Pages
			······································
4 10 10 10 10 10 10 10 10 10 10 10 10 10			
			Los allos a constante a constante a

Note: A buyer should not rely on the above-cited reports as a reflection of the current condition of the Property. A buyer should obtain inspections from inspectors chosen by the buyer.

Section 8. Check any tax exemption(s) which you (Seller) currently claim for the Property:

✓ Homestead	Senior Citizen	Disabled
Wildlife Management	Agricultural	Disabled Veteran
Other:		Unknown
otion (Cullus)	P-1	

Section 9. Have you (Seller) ever filed a claim for damage to the Property with any insurance provider? Vyes no

Section 10. Have you (Seller) ever received proceeds for a claim for damage to the Property (for example, an insurance claim or a settlement or award in a legal proceeding) and not used the proceeds to make the repairs for which the claim was made? _____yes \underline{V} no If yes, explain: ______

Section 11. Does the Property have working smoke detectors installed in accordance with the smoke detector requirements of Chapter 766 of the Health and Safety Code?* ____unknown ___ no ___ yes. If no or unknown, explain. (Attach additional sheets if necessary): ______

*Chapter 766 of the Health and Safety Code requires one-family or two-family dwellings to have working smoke detectors installed in accordance with the requirements of the building code in effect in the area in which the dwelling is located, including performance, location, and power source requirements. If you do not know the building code requirements in effect in your area, you may check unknown above or contact your local building official for more information.

A buyer may require a seller to install smoke detectors for the hearing impaired if: (1) the buyer or a member of the buyer's family who will reside in the dwelling is hearing-impaired; (2) the buyer gives the seller written evidence of the hearing impairment from a licensed physician; and (3) within 10 days after the effective date, the buyer makes a written request for the seller to install smoke detectors for the hearing-impaired and specifies the locations for installation. The parties may agree who will bear the cost of installing the smoke detectors and which brand of smoke detectors to install.

Seller acknowledges that the statements in this notice are true to the best of Seller's belief and that no person, including the broker(s), has instructed or influenced Seller to provide inaccurate information or to omit any material information.

John Mag Signature of Seller Printed Name: Jelth	a second second	Signature of Seller	Date
(TXR-1406) 02-01-18	Initialed by: Buyer:	Printed Name: 	Page 4 of 5
Proc	luced with zipForm® by zipLogix 18070 Fifteen I	Mile Road, Fraser, Michigan 48026 www.zipLogix.com	Magee

ADDITIONAL NOTICES TO BUYER:

- (1) The Texas Department of Public Safety maintains a database that the public may search, at no cost, to determine if registered sex offenders are located in certain zip code areas. To search the database, visit <u>www.txdos.state.tx.us</u>. For information concerning past criminal activity in certain areas or neighborhoods, contact the local police department.
- (2) If the Property is located in a coastal area that is seaward of the Gulf Intracoastal Waterway or within 1,000 feet of the mean high tide bordering the Gulf of Mexico, the Property may be subject to the Open Beaches Act or the Dune Protection Act (Chapter 61 or 63, Natural Resources Code, respectively) and a beachfront construction certificate or dune protection permit may be required for repairs or improvements. Contact the local government with ordinance authority over construction adjacent to public beaches for more information.
- (3) If the Property is located in a seacoast territory of this state designated as a catastrophe area by the Commissioner of the Texas Department of Insurance, the Property may be subject to additional requirements to obtain or continue windstorm and hail insurance. A certificate of compliance may be required for repairs or improvements to the Property. For more information, please review *Information Regarding Windstorm and Hail Insurance for Certain Properties* (TXR 2518) and contact the Texas Department of Insurance or the Texas Windstorm Insurance Association.
- (4) This Property may be located near a military installation and may be affected by high noise or air installation compatible use zones or other operations. Information relating to high noise and compatible use zones is available in the most recent Air Installation Compatible Use Zone Study or Joint Land Use Study prepared for a military installation and may be accessed on the Internet website of the military installation and of the county and any municipality in which the military installation is located.
- (5) If you are basing your offers on square footage, measurements, or boundaries, you should have those items independently measured to verify any reported information.
- (6) The following providers currently provide service to the Property:

Electric: BARTLETT ELECTRIC COOP	phone #: 254-527-3551
Sewer: SEPTIC	phone #:
Water: SOUTHWEST MILAM WATER	phone #: 512-446-2404
Cable: DISH	phone #: 800-333-3474
Trash:	phone #:
Natural Gas:	phone #:
Phone Company:	phone #:
Propane:	phone #:
Internet:	phone #:

(7) This Seller's Disclosure Notice was completed by Seller as of the date signed. The brokers have relied on this notice as true and correct and have no reason to believe it to be false or inaccurate. YOU ARE ENCOURAGED TO HAVE AN INSPECTOR OF YOUR CHOICE INSPECT THE PROPERTY.

The undersigned Buyer acknowledges receipt of the foregoing notice.

Signature of Buyer	Date	Signature of Buyer	Date
Printed Name:		Printed Name:	
(TXR-1406) 02-01-18			Page 5 of 5
	Produced with zipForm® by zipLogix 18070 Fifteen Mile Re	oad, Fraser, Michigan 48026 www.zipLogix.com	Magee

746 S. FM 908 Rockdale, Texas 76567 Inspection Results

From: alison.kinnee@griptx.com

- To: cmatous1@yahoo.com; papa_john14@hotmail.com
- Cc: sharon.henderson@griptx.com
- Date: Wednesday, May 15, 2019, 7:09 PM CDT

We inspected the MH property at 746 S. FM 908 Rockdale, Texas 76567 on May 15, 2019 and it does need a retrofit in order to meet either the 1996 HUD Guidelines for FHA and VA loans or Texas Department of Housing and Community Affairs ("TDHCA") guidelines for conventional loans.

- 1. The transverse anchors are not corrosion resistant as required by FHA/IIUD and TDHCA.
- 2. There are no longitudinal anchors at all ... longitudinal anchors are required by FHA/HUD and TDHCA guidelines.
- 3. The cinderblock piers are mounted directly on the soil... this is allowed on existing homes.
- 4. The axles have been removed as required by FHA/HUD and TDHCA.
- 5. The tongues have been removed as required by FHA/HUD and TDHCA.
- 6. The drainage is adequate as required by FHA/HUD and TDHCA.
- 7. The skirting needs the following in order to meet current FHA/HUD and TDHCA guidelines:
 - a. Skirting manway hinges and latch

b. Seller may do this... If the above skirting work is done before the retrofit, the seller will avoid a \$ 175.00 reinspection fee.

- 8. The modifications to the home do not meet current FIIA/HUD guidelines... they do affect the structural integrity of the home
 - a. The front porch roof needs one () 4 X 4 support posts to remove porch roof load away from the MH.
 - b. The seller may do this prior to closing.

Our bid of \$2,777.09 for the scope of work below can, if or when you are ready, be sent by eparate email in Bid Con, tract Form, with a place for signature by the responsible party(ies).

1	Foundation Retrofit with Engineer Certification Report	\$2,395.65
2	Skirting Manway Hinges and Latch	\$175.21
3	Porch Roof Support Posts (1)	1
		\$206.23
	TOTAL	\$2,777.09

SHALES INTO THE TOP

Payment for the retrofit work is due at closing or 30 days after completion, whichever is soonest.

NOTE: A retrofit has no bearing on the level of a home nor does it impair the integrity of the home in any way. Its purpose is solely to prevent wind forces from moving the home horizontally. A retrofit installed arm-tight is to secure the home from horizontal movement but to allow for normal, seasonal vertical ground movement. Such seasonal vertical ground movement may require relevelling every 3 to 5 years.

While we allow and encourage the seller to complete most secondary items on their own prior to retrofit in order to save money, please note that our installers must install the retrofit if the client wishes for our engineer to issue the report. If the client wishes to have another company complete the retrofit, we highly recommend the client confirm that the installing company has an engineer that will sign off on their work. We can only issue engineer reports on retrofits installed by Gulftex Retrofit.

PROJECT INFORMATION

Re: 746 S. FM 908 Rockdale, Texas 76567

16' X 76' Manufactured House

HUD Label Numbers PFS0520308

SCOPE OF WORK: Foundation Retrofit, Skirting Manway Hinges and Latch, and Engineers Report

Did you have a great experience with us? Please leave us a review by clicking HERE. Thank you!

Alison Kinnee Administrative Assistant GulfTex Retrofit Installation Professionals, LLC 485 Becky Lane Waxahachie, TX 75165 Installer License MHDINS 00004551 <u>alison.kinnee@griptx.com</u> Cell 817-659-5979 (call or text) Fax 866-863-5069