

Other Options

[Return to menu](#)
[Plot this site in State Library Digital Atlas](#)
[Plot this site in Google Maps](#)
[View scanned well log \(6/19/2006 9:48:59 AM\)](#)

30 gpm with drill stem set at feet for 1 hours.
Time of recovery 1 hours.
Recovery water level 70 feet.
Pumping water level 177 feet.

Section 2: Location

Township 07S	Range 08W	Section 13	Quarter Sections NE¼ NW¼	
County		Geocode		
BEAVERHEAD				
Latitude 45.230945	Longitude -112.531085	Geomethod TRS-SEC	Datum NAD83	
Ground Surface Altitude		Ground Surface Method	Datum	Date

** During the well test the discharge rate shall be as uniform as possible. This rate may or may not be the sustainable yield of the well. Sustainable yield does not include the reservoir of the well casing.*

Addition
VALLEY VIEW FARM LOTS

Block	Lot
	28

Section 8: Remarks

Section 3: Proposed Use of Water

DOMESTIC (1)

Section 4: Type of Work

Drilling Method: ROTARY
Status: NEW WELL

Section 5: Well Completion Date

Date well completed: Tuesday, September 26, 2000

Section 6: Well Construction Details

Borehole dimensions

From	To	Diameter
0	181	6

Casing

From	To	Diameter	Wall Thickness	Pressure Rating	Joint	Type
-2	181	6				#17 STEEL

Completion (Perf/Screen)

From	To	Diameter	# of Openings	Size of Openings	Description
115	120	6			PERFORATED CASING
135	140	6			PERFORATED CASING

Annular Space (Seal/Grout/Packer)

From	To	Description	Cont. Fed?
0	20	BENTONITE	

Section 9: Well Log

Geologic Source

Unassigned

[illegible]

Driller Certification

All work performed and reported in this well log is in compliance with the Montana well construction standards. This report is true to the best of my knowledge.

Name: _____

Company: LINDSAY DRILLING CO INC

License No: WWC-253

Date _____

Completed: 9/26/2000