



STRONG HOLD INSPECTIONS & SEPTIC PUMPING

417-818-9524

inspectbystronghold@gmail.com

<https://inspectbystronghold.com/>



HOME REPORT

14725 Violet Dr.
Lynchburg, MO 65543

Rob Weaver

07/15/2025



Inspector

Brett Thompson

InterNACHI Certified Home Inspector
State-Certified Septic Inspector 51221
State-Certified Termite Inspector N8982

417-818-9524

inspectbystronghold@gmail.com



Agent

Grant Cordell

Trophy Properties and Auction

TABLE OF CONTENTS

1: Inspection Details	4
2: Exterior	5
3: Roof	15
4: Attic	22
5: HVAC	23
6: Electrical	28
7: Plumbing	29
8: Gas/Oil Fuel System	31
9: Interiors	32
10: Kitchen	38
11: Bathrooms	41
12: Laundry Room	46
13: Foundation	47
14: Misc.	49

NOTICE TO 3RD PARTY: This report is the property of Strong Hold Inspections & Septic Pumping and the Client named herein and is non-transferable to any third parties or subsequent buyers. THE INFORMATION IN THIS REPORT SHALL NOT BE RELIED UPON BY ANY ONE OTHER THAN THE CLIENT NAMED HEREIN. This report is governed by an Inspection Agreement that contained the scope of the inspection, including limitations and exclusions. Unauthorized recipients are advised to contact a qualified Home Inspector of their choosing to provide them with their own Inspection Report.

SCOPE OF INSPECTION: The purpose of the inspection is to identify and disclose to the client major deficiencies and defects of the systems and components of the subject premises, which are visually observable at the time of the inspection. The inspection report shall provide the Client with a better understanding of the property conditions as observed at the time of the inspection. Although minor problems may be mentioned, the report will not attempt to list them all. The inspection will consist of only a visual analysis of major systems and components of the property and comment on those that are in need of immediate repair, replacement, or further evaluation by a specialist. The inspection is not technically exhaustive. The inspection report contains information that may or may not be mentioned or discussed during any verbal discussion of the findings of the Inspector. It is agreed that no claim shall be made against Inspector for any verbal representations that are inconsistent with or not contained in the inspection report. PLEASE READ THE ENTIRE REPORT CAREFULLY! Standards of Practice (SOP): SOP used will be either InterNACHI or ASHI, depending on the inspector's certification. Click here for the NACHI SOP and here for the ASHI SOP.

LIMITATIONS OF THE INSPECTION: The inspection is limited to readily accessible and visible major systems, components, and equipment located in and attached to the premises. Any area that is not exposed to view, is concealed, or is inaccessible because of soil, wall coverings, floor coverings, ceiling coverings, rugs, carpets, furnishings, or other materials is not to be considered part of this inspection. Weather limitations may affect the extent to which the Inspector may inspect the property, especially in connection with the heating and air conditioning systems. This inspection is not considered to be an expressed or implied guarantee or warranty of any kind regarding the condition of the property, its systems or components. Further limitations described in the report also apply.

INSPECTION EXCLUSIONS: The following items are excluded from any inspection performed by Inspector on the subject property: Unless alternative arrangements have been made. 1. Hidden or latent defects. 2. The presence of pests, termites, wood-damaging insects, rodents, or organisms. These are considered auxiliary inspections and will be provided on a separate report if ordered. 3. Outbuildings or any other detached structures, fences and gates, pools and spas, underground plumbing or sprinklers, and other components or structures not attached to the premises, unless specifically agreed upon in writing by both parties. 4. The inspection does not include any potential environmental hazards; Building Code or Zoning Ordinance compliance or violation unless specifically agreed upon in writing by both parties. 5. The adequacy of any design or installation process of any system, component, or other feature of the subject property. 6. Structural stability from an engineering standpoint, engineering analysis, geological stability, or soil conditions. 7. A prediction of future conditions or life expectancy of systems or components. 8. The causes of the need for a repair, or the methods, materials, and costs of a repair. 9. The marketability or market value of the property, or the advisability or inadvisability of the purchase of the property. 10. Any item excluded or not inspected or reported upon in the report. 11. The internal conditions of air conditioning and heating systems that are not accessible via an easily removable access door/panel, the adequacy of air flow, duct work materials or design, and insulation of the system. 12. The furnace heat exchangers, fireplaces, chimneys, or flues will be observed for easily visible external signs of damage only! Chimneys and/or flues that are dirty or coated with creosol are also exempt. 13. Radio or remote-controlled devices, alarms, garage door openers, automatic gates, elevators, thermostatic timer controls, or dumbwaiters. 14. The insurability of the property. 15. Inspection of refrigeration systems and appliance connections.

ITEMS NOT INSPECTED: Unless alternative arrangements have been made, there are items that are not inspected in this inspection, such as, but not limited to; refrigerators, washers/dryers, water softeners/purifiers, storm doors and storm windows, screens, window AC units, central vacuum systems, alarm and intercom systems, and any item that is not a permanent attached component of the building. Drop ceiling tiles are not removed, as they are easily damaged, and this is a non-invasive inspection. Subterranean systems are also excluded, such as but not limited to: sewer lines, septic tanks, water delivery systems, and underground fuel storage tanks. Water and gas shut-off valves are not operated under any circumstances as well; any component or appliance that is unplugged or "shut-off" is not turned on or connected for the sake of evaluation. Any component or system that was not observed. Inspector will not calculate the strength, adequacy, design or efficiency of any system or component; Enter any area or perform any procedure that may damage the property or its components or be dangerous to the Inspector or other persons; Operate any system or component that is shut down or otherwise inoperable; Operate any system or component that does not respond to normal operating controls; Disturb insulation; Move personal items, furniture, equipment, plant life, soil, snow, ice, or debris that obstructs access or visibility. Lastly, the inspection does not address environmental concerns such as, but not limited to: asbestos, lead, lead-based paint, radon, mold, pesticides, treated lumber, Chinese drywall, mercury, or carbon monoxide.

1: INSPECTION DETAILS

Information

In Attendance Homeowner	Occupancy Occupied	Temperature (approximate) 87 Fahrenheit (F)
Utility - Gas Propane	Utility - Sewer Unknown	Utility - Water Private Well
Weather Conditions Dry		

2: EXTERIOR

		IN	PI	NI	NP
2.1	Grading, Drainage, & Retaining Walls	X			
2.2	Walkways & Driveways	X			
2.3	Entrances	X			
2.4	Siding, Flashing, Trim, Eaves, Soffit, & Fascia	X			
2.5	Exterior Doors & Windows	X			
2.6	Exterior Electrical	X			
2.7	Spigots	X			

IN = Inspected PI = Partially Inspected NI = Not Inspected NP = Not Present

Information

Grading, Drainage, & Retaining Walls: Grading Slope Flat, Minor	Grading, Drainage, & Retaining Walls: Retaining Wall None	Walkways & Driveways: Driveway Material Gravel
Walkways & Driveways: Walkway Material Concrete	Entrances: Front Entrance Type Covered Patio	Entrances: Secondary or Back Entrance Type(s) Covered Deck
Siding, Flashing, Trim, Eaves, Soffit, & Fascia: Siding Material Vinyl		

Observations

2.1.1 Grading, Drainage, & Retaining Walls

GRADING - INADEQUATE SLOPE

The grading does not slope away from the building sufficiently in one or more areas. This could lead to water intrusion and foundation issues. A 1/2" fall every foot for the first 10 feet away from the home is recommended.

 Repair Recommended




2.2.1 Walkways & Driveways

WALKWAY - CRACKING MINOR

Maintenance Item or Note

Minor cracks were observed. Sealing to help prevent further water penetration and movement in the future is recommended.



2.3.1 Entrances

STEPS

Maintenance Item or Note

The rise and tread on the steps are not correct.



2.3.2 Entrances

TRIP HAZARD

Repair Recommended

Settlement cracks have occurred, causing a trip hazard.



2.3.3 Entrances

MOISTURE DAMAGE

Moisture damage was observed see Roof section.



Repair Recommended



2.4.1 Siding, Flashing, Trim, Eaves, Soffit, & Fascia

FASCIA/SOFFIT - DAMAGED

One or more sections of the fascia/soffit are damaged or have moisture damage.

Sample pictures taken may not be all areas that need correction.



Repair Recommended



2.4.2 Siding, Flashing, Trim, Eaves, Soffit, & Fascia



Repair Recommended

FLASHING/TRIM - IMPROPERLY INSTALLED OR SHORT

Flashing and trim pieces are improperly installed, loose, missing, or cut short, which could result in moisture intrusion and damaging leaks.



2.4.3 Siding, Flashing, Trim, Eaves, Soffit, & Fascia




Repair Recommended

GENERAL - EXPOSED WOOD - PEELING PAINT

Paint is peeling, leaving exposed wood. Repainting to prevent further water penetration and damage to the wood is recommended.

Sample pictures taken may not be all areas that need correction.



2.4.4 Siding, Flashing, Trim, Eaves, Soffit, & Fascia

GENERAL - SEAL

Sealing all areas where siding meets brick or stone, trim, windows, doors, soffits, and all penetration points to reduce the possibility of water damage and insect entry is recommended.

Sample pictures taken may not be all areas that need sealed.



Repair Recommended



2.4.5 Siding, Flashing, Trim, Eaves, Soffit, & Fascia


SIDING - DAMAGED

Multiple holes or damaged spots in the siding and/or trim were observed.

Sample pictures taken may not be all areas that are damaged.



Repair Recommended



2.4.6 Siding, Flashing, Trim, Eaves, Soffit, & Fascia

SIDING - LOOSE, MISSING, NOT OVERLAPPED, SHORT

The siding is loose, cut short, missing, or not correctly overlapped in one or more locations.

Sample pictures taken may not be all areas that need correction.





2.4.7 Siding, Flashing, Trim, Eaves, Soffit, & Fascia

SIDING/TRIM- WARPING/BUCKLING

The siding/trim is warping or buckling in one or more areas.





2.5.1 Exterior Doors & Windows

DAYLIGHT

Daylight can be seen around all the back deck doors.



2.5.2 Exterior Doors & Windows

GLASS BOWED

Section(s) of glass are missing or broken.



Maintenance Item or Note



2.5.3 Exterior Doors & Windows

HARDWARE

Hardware is damaged, loose, or missing.



Maintenance Item or Note




2.6.1 Exterior Electrical

ELECTRICAL COVERS MISSING

Exterior covers are missing on outlets, switches, or junction boxes and should be installed.



Maintenance Item or Note



2.7.1 Spigots

LEAK

Spigot(s) have an active leak or drip.



Repair Recommended



3: ROOF

		IN	PI	NI	NP
3.1	Coverings	X			
3.2	Roof Drainage Systems	X			

IN = Inspected PI = Partially Inspected NI = Not Inspected NP = Not Present

Information


Coverings: Inspection Method Walked Safe & Accessible Areas	Coverings: Layers 2	Coverings: Material Metal
Coverings: Roof Type/Style Combination	Roof Drainage Systems: Gutter Guards No	

Observations

3.1.1 Coverings

FLASHING - LOOSE/MISSING/SEPARATED

Flashing(s) are loose, missing, not properly installed, or separated, which can lead to water intrusion or mold.

 Repair Recommended





No rake trim

3.1.2 Coverings

GENERAL - VENT BOOT

No vent boot(s) observed.



Maintenance Item or Note



3.1.3 Coverings

METAL - FOAM CLOSURES LOOSE

Foam closures are out of position or coming loose.



Repair Recommended



3.1.4 Coverings

METAL - IMPROPER OVERLAP

One or more roof sheets were incorrectly overlapped at installation.

Recommendation

Contact a qualified roofing professional

Repair Recommended



3.1.5 Coverings

METAL - NO FOAM

There are no foam closures at the eave.

Maintenance Item or Note



3.1.6 Coverings

METAL - NO TAPE

No tape mastic was used on the laps of the sheets or trim.



Maintenance Item or Note



3.1.7 Coverings

METAL - RUSTED FASTENERS

Fastener(s) are rusted, which could lead to water leaks.

Sample pictures taken may not be all areas that need correction.



Repair Recommended



3.1.8 Coverings

METAL - SCREWS INCORRECT

Screws are missing, backing out, improperly installed, or not secured well.

Sample pictures taken may not be all areas that need correction.



Repair Recommended





Loose

3.2.1 Roof Drainage Systems

DEBRIS

**Repair Recommended**

The gutters were filled with leaves and debris at the time of the inspection. Cleaning and removal of debris on a regular basis is recommended. This condition can cause water penetration at the eave.

[Here is a DIY resource](#) for cleaning your gutters.



3.2.2 Roof Drainage Systems

LEAK

**Repair Recommended**

Gutters have stains in one or more areas that could indicate leak(s). Leak(s) can result in excessive moisture in the soil at the foundation. Water seepage into crawlspaces, basements, and under foundations can be caused by inadequate removal of rainwater from the perimeter of the house, which can lead to foundation/structural movement.

[Here is a helpful DIY link](#) and video on draining water flow away from your house.



4: ATTIC

		IN	PI	NI	NP
4.1	Attic & Roofing Structure			X	
4.2	Insulation			X	
4.3	Ventilation			X	

IN = Inspected PI = Partially Inspected NI = Not Inspected NP = Not Present

Information

Attic & Roofing Structure: Access Location No Access Found	Attic & Roofing Structure: Method of Inspection Not Inspected	Attic & Roofing Structure: Roof Frame Type N/A
Insulation: Insulation Info No Access	Ventilation: Ventilation Type No Access	

5: HVAC

		IN	PI	NI	NP
5.1	Thermostat	X			
5.2	Heating Equipment		X		
5.3	Distribution System	X			
5.4	Cooling Equipment	X			

IN = InspectedPI = Partially InspectedNI = Not InspectedNP = Not Present

Information

Heating Equipment: Brand
N/A



Heating Equipment: Year of
Manufacture
N/A

Heating Equipment: Energy
Source
Electric

Heating Equipment: Heat Type
Forced Air

Heating Equipment: Location(s)
Laundry Area

Distribution System: Distribution
Type
Ducts

Cooling Equipment: Year of
Manufacture
Unk.

Cooling Equipment: Type
Forced Air

Cooling Equipment: Brand Goodman



Cooling Equipment: Label worn/missing


The date of manufacture couldn't be found because the label was worn or missing.

Limitations

Heating Equipment

INACCESSIBLE

The heating system is obstructed and inaccessible. Not Inspected.



Heating Equipment

PARTIALLY TESTED SEASONAL

The heating system was run but not fully tested at the time of inspection due to outside temperatures.

Heating Equipment

REGULAR MAINTENANCE

Maintaining a regular inspection and routine maintenance schedule in the future with a qualified HVAC company is recommended.

Cooling Equipment

REGULAR MAINTENANCE

Maintaining a regular inspection and routine maintenance schedule in the future with a qualified HVAC company is recommended.

Observations

5.3.1 Distribution System

DUCTS - CLEAN

Cleaning the ducts is recommended.



5.4.1 Cooling Equipment

ELECTRIC - DAMAGE

The electrical conduit and/or thermostat wiring have minor damage or exposed wiring.



5.4.2 Cooling Equipment

LEAKING

The unit is leaking.





5.4.3 Cooling Equipment

LINE - INSULATION MISSING OR DAMAGED



Repair Recommended

The insulation on the refrigerant line is missing or damaged, which can cause energy loss and condensation.



5.4.4 Cooling Equipment

TEMP - INCORRECT COOLING



Repair Recommended

The temperature difference between the return air and air output of the cooling system should be 15-20 degrees. At the time of inspection, the difference was more or less than that.



6: ELECTRICAL

		IN	PI	NI	NP
6.1	Service Connection	X			
6.2	Main Panel(s)	X			

IN = Inspected PI = Partially Inspected NI = Not Inspected NP = Not Present

Information

Service Connection: Electrical Service Type
Overhead, Below Ground


Main Panel(s): Panel Capacity
200 AMP

Service Connection: Main Disconnect Location(s)
At Main Panel

Main Panel(s): Panel Location
Laundry Room

Main Panel(s): Circuit Protection Type
Breakers

Main Panel(s): Wiring Method(s)
Romex



7: PLUMBING

		IN	PI	NI	NP
7.1	Main, Supply, & Drain Lines	X			
7.2	Hot Water System(s)			X	

IN = Inspected PI = Partially Inspected NI = Not Inspected NP = Not Present

Information

Main, Supply, & Drain Lines: Main Water Shut-off Location	Main, Supply, & Drain Lines: Main Water Supply Line Material	Main, Supply, & Drain Lines: Supply Lines Material
Laundry room	PEX	PEX



Main, Supply, & Drain Lines: Waste/Drain Lines Material	Hot Water System(s): Capacity	Hot Water System(s): Year of Manufacture
PVC	Unk. N/A	Unk.
	N/A	
Hot Water System(s): Location	Hot Water System(s): Power Source/Type	
Laundry room	Electric	
Hot Water System(s): Manufacturer		
N/A		

Flushing & servicing your water heater tank annually for optimal performance is recommended. The water temperature should be set to at least 120 degrees F to kill microbes and no higher than 130 degrees F to prevent scalding.

[Here is a nice maintenance guide from Lowe's to help.](#)

Limitations

Hot Water System(s)

ACCESS BLOCKED

Access to water heater was blocked.



Observations

7.1.1 Main, Supply, & Drain Lines

LOW PRESSURE

Water pressure appears to be low when using multiple plumbing fixtures at one time.



Maintenance Item or Note

8: GAS/OIL FUEL SYSTEM

		IN	PI	NI	NP
8.1	Fuel Storage & Distribution Systems	X			

IN = InspectedPI = Partially InspectedNI = Not InspectedNP = Not Present

Information

Fuel Storage & Distribution Systems: Main Fuel Shut-off
Location
At Tank

Fuel Storage & Distribution Systems: Type
Propane



9: INTERIORS

		IN	PI	NI	NP
9.1	Walls	X			
9.2	Floors	X			
9.3	Ceilings	X			
9.4	Windows	X			
9.5	Doors	X			
9.6	Electrical	X			
9.7	Smoke/Carbon Monoxide Detectors	X			

IN = Inspected PI = Partially Inspected NI = Not Inspected NP = Not Present

Limitations


Windows

STORED ITEMS

Window(s) could not be opened due to stored items.

Observations


9.1.1 Walls

 Maintenance Item or Note

COMMON


Common/cosmetic issues were observed such as normal wear, minor damage, settlement or tape joint cracks, and nail pops.

9.1.2 Walls

 Maintenance Item or Note

DAMAGE

There is damage to the wall(s).



9.1.3 Walls

MOISTURE DAMAGE WET

Moisture stains or damage is visible on the wall(s). At the time of inspection, they're wet.



46%



Master on both sides

9.2.1 Floors


COMMON

Common/cosmetic issues were observed such as worn flooring in high traffic areas, minor damage, poor workmanship, and missing/loose trim.

9.2.2 Floors

TRANSITION STRIPS

Transition strips are recommended between different flooring types to prevent wear/damage to the edges.



9.3.1 Ceilings

COMMON

Maintenance Item or Note

Common/cosmetic issues were observed such as repair areas, settlement or tape joint cracks, and nail pops.

9.3.2 Ceilings

MOISTURE DAMAGE/STAINS DRY

Maintenance Item or Note

Moisture stain(s) are visible on the ceiling. At the time of inspection, they are dry.



Living Room



Living Room



Master



Spare Bedroom



Spare Bedroom



Kitchen

9.4.1 Windows

MOISTURE STAINING

Maintenance Item or Note

Window(s) have moisture stains. At the time of inspection, they were dry.



Master Bedroom

9.5.1 Doors

ADJUST

Door(s) need minor adjustments to close properly.



Maintenance Item or Note


9.5.2 Doors

HARDWARE - LOOSE/ MISSING

Hardware is loose or missing.



Maintenance Item or Note



Master Closet

9.6.1 Electrical

COVER PLATE - DAMAGED/MISSING/LOOSE

Cover plate(s) are missing, loose, or broken on outlets, switches, or junction boxes and should be secured or replaced.



Repair Recommended



9.6.2 Electrical

EXHAUST FAN -

The exhaust fan is working but is extremely noisy.

Repair Recommended



Hall

9.6.3 Electrical

GLOBE(S) MISSING

Globe(s) are missing from fixtures.

Recommendation

Contact a qualified professional

Maintenance Item or Note



Hall

9.6.4 Electrical

SWITCH/LIGHT - INOPERABLE

Maintenance Item or Note

Switch(es) do not appear to operate anything. There may be burnt or missing bulbs, or the switches run outlets or are ran by a remote.

9.7.1 Smoke/Carbon Monoxide Detectors

SMOKE DETECTORS RECOMMENDED

Safety Concern

A working smoke detector in each applicable area is recommended. This includes every bedroom, hallway, each level of a home (including a basement), and any room with a fireplace.



Missing from hallway

10: KITCHEN

		IN	PI	NI	NP
10.1	Counters/Cabinets	X			
10.2	Sink	X			
10.3	Garbage Disposal				X
10.4	Range/Oven/Cooktop	X			
10.5	Hood Fan			X	
10.6	Dishwasher	X			
10.7	Refrigerator	X			

IN = Inspected PI = Partially Inspected NI = Not Inspected NP = Not Present

Information

Range/Oven/Cooktop:
Range/Oven Brand
GE



Range/Oven/Cooktop:
Range/Oven Energy Source
Electric

Hood Fan: Exhaust Hood Type
Re-circulate



Dishwasher: Dishwasher Brand
Whirlpool



Refrigerator: Refrigerator Brand
Frigidaire



Limitations

Sink
PERSONAL ITEMS

The view below the sink is restricted due to personal item storage.

Observations

10.1.1 Counters/Cabinets

LAMINATE LOOSE

The laminate on the countertop or cabinet is loose or missing.

 Maintenance Item or Note




10.1.2 Counters/Cabinets

SEALING BEHIND SINK

Maintenance Item or Note

Sealing or resealing behind the sink is recommended.



10.4.1 Range/Oven/Cooktop

ANTI-TIP

Maintenance Item or Note

The anti-tip is not installed on the stove which can be a safety concern, installation is recommended.

[Here's a link for more information.](#)

11: BATHROOMS

		IN	PI	NI	NP
11.1	Counters/Cabinets	X			
11.2	Sink	X			
11.3	Shower/Tub	X			
11.4	Toilet	X			

IN = Inspected PI = Partially Inspected NI = Not Inspected NP = Not Present

Limitations

Sink

PERSONAL ITEMS

The view below the sink is restricted due to personal item storage.

Observations

11.1.1 Counters/Cabinets

COUNTER/BACKSPLASH LOOSE

Maintenance Item or Note

The countertop/ backsplash isn't secured well.



11.2.1 Sink

DRAIN - STOPPER
BROKEN/MISSING

Maintenance Item or Note

Sink drain stopper(s) do not work correctly or are missing.



11.3.1 Shower/Tub

DRAIN - STOPPER

Drain stopper(s) don't function properly or are missing.



Maintenance Item or Note



11.3.2 Shower/Tub

FAUCET/SHOWER - DIVERTER VALVE

When the water is diverted from the tub to the shower head, some water is still running from the faucet or vice versa.



Repair Recommended



11.3.3 Shower/Tub

FAUCET/SHOWER - HARDWARE MISSING/LOOSE

Hardware is missing, loose, or broken.

 Maintenance Item or Note



Master

11.3.4 Shower/Tub

SHOWER HEAD - CONNECTION LEAKING

The shower head is leaking at the connection to the water line.

 Maintenance Item or Note




11.3.5 Shower/Tub

SURROUND - SEAL

Sealing the top of shower enclosures, where enclosures meet the wall, and where the tub meets the floor is recommended.



Maintenance Item or Note



11.3.6 Shower/Tub

COLD WATER - LOW PRESSURE

The tub/shower has low cold water pressure.



Maintenance Item or Note



11.4.1 Toilet

BASE - CAULKING

Caulking where the toilet meets the floor is recommended.



Maintenance Item or Note



12: LAUNDRY ROOM

		IN	PI	NI	NP
12.1	Washer/Dryer Area		X		

IN = InspectedPI = Partially InspectedNI = Not InspectedNP = Not Present

Information

Washer/Dryer Area: Dryer Power
Source
220 Electric

13: FOUNDATION

		IN	PI	NI	NP
13.1	Foundation	X			
13.2	Floor Support	X			
13.3	Crawlspace	X			
13.4	Water Prevention/Removal (Crawlspace or Basement)	X			

IN = InspectedPI = Partially InspectedNI = Not InspectedNP = Not Present

Information

Foundation: Foundation Type Crawlspace	Foundation: Inspection Method Entered Crawlspace	Foundation: Material Masonry Block
Floor Support: Floor Support Type Mobile Home	Water Prevention/Removal (Crawlspace or Basement): Does the crawlspace have a sump pump? No	

Observations

13.1.1 Foundation

CRACKS

Settlement cracks were observed. Properly sealing them, monitoring for further movement, and contacting a qualified contractor if the cracks enlarge is recommended.

Sample pictures taken may not be all areas that need correction.

 Maintenance Item or Note



13.3.1 Crawlspace

DAMP

The crawlspace is damp at the time of inspection. Proper grading, ventilation, and redirecting the downspouts may help with the moisture.

 Maintenance Item or Note



13.3.2 Crawlspace

VENTS - BELOW GRADE

Crawl space vents are at or below grade which can allow water to penetrate.



Maintenance Item or Note



13.4.1 Water Prevention/Removal (Crawlspace or Basement)

DEHUMIDIFIER - RECOMMENDED

A dehumidifier may help with moisture. The EPA recommends maintaining humidity between 30 and 50% to help prevent mold growth.



Maintenance Item or Note

13.4.2 Water Prevention/Removal (Crawlspace or Basement)

VAPOR BARRIER - NONE

There is no vapor barrier which can result in unwanted moisture.



Maintenance Item or Note

14: MISC.

		IN	PI	NI	NP
14.1	Misc.			X	

IN = Inspected PI = Partially Inspected NI = Not Inspected NP = Not Present

Limitations

Misc.
NOT INSPECTED

