

possible

4. This plat is based on a current field survey.

Mag. North
2006

TM80-4
Robert S. Maxey, Jr.
D.B. 266 p. 418
D.B. 238 p. 855
P.C. A Slide 108B

0.74mi. ± To
Rte. 659

0.52 Acres (overlap)
with plat D.B. 130 p. 577

branch

TM80-3
The Glatfelter
Pulp Wood
Company
D.B. 138 p. 474
Plat D.B. 133 p. 532

branch
86' 169'

Found Pipe
by white post

43.49 Acres

Includes 0.52 Acres overlap

Drainfield
Site

Fd Iron
@739.8'

Fd Iron
@427.9'

Fd Iron
@251.0'

Fd Iron
@108.7'

45in. Red Oak
w/chops

TM80-8 & 9
Donald Mack Barnes
Tony E. Hawley
David R. Godwin
D.B. 272 p. 866

N64°34'43"W 651.65'

Fd Iron on
line @16.3'

Set Iron (Flush)
in center old
road bed

Set Iron on line
@1563.3'

Set Iron (Flush)
in center old
road bed

S27°29'40"W
304.35'

Set Iron

S21°26'17"W
345.72'

S15°32'52"W
147.39'

Set Iron

S22°50'11"W
135.40'

Property line along center of old road bed

S17°28'37"W
185.79'

Set Iron

S12°15'04"W
259.15'

Set Iron


S12°09'50"W
278.35'

Set Iron

S17°48'35"W
224.98'

TM80-2
Thomas E. Patterson, III et als.
D.B. 178 p. 519

Boundary Survey
for
Son Nouven



Resurvey of Existing
D. A. L. 3-30-06