ACCOUNT NO.

010500266-8

TERMINIX INTERNATIONAL 1707 E. 29TH ST BRYAN TX 77802

Total Due Amount Paid Check Cash

DR. PHIL DAVIS 15918 HUY 21 U MAKE CHECK PAYABLE TO: TERMINIK INTERNATIONAL

	Service/Inspec	tion	Report In	itial Serv	ice	☐ Regula	ar Service			
Branch Account Rt. Telephone				Gric		Production	Time Scheduled	In/Out		
2405	010500266-8	.06	979/846- 89 39	13930		60	1/27/03	8:30	8:00	
Service Property At					Service Center					
1581 NORT Operator MICH	AEL DUBCAK_	mber	about De to	0	- Jane	1707 E. 2 BRYAN TX Supervisor Name & RON KIRBY	77802 Certification Number 26701 PTL:	er BCW	ation(s)	
Today Terminix inspected "in ground" Sentricon stations located at the above address and either found or performed the following as indicated:						Today Terminix inspected "above ground" Recruit AG station(s) located at the above address either found or performed the following as indicated:				
Initial installation of stations					Initial installation of Recruit AG station(s) Location(s):					
No Termite activity found in stations Termite activity found in station(s) Station #(s): Recruit* Il Baitube* placed in station(s) Station #(s):					Cocation(s): Added supplemental Recruit AG to station(s) Station #(s): Total Recruit AG Stations placed or added: EPA Reg. #62719-270 (0.5% Hexaflumuron) Bait - 70 grams each					
Replaced consumed Recruit II Baitube in station(s) Station #(s): Total Recruit II Baitubes placed EPA Reg. #62719-272 (0.5% Hexaflumuron) Bait - 35 grams each					Target Pest = Subterranean Termites Reticulitermes spp. Heterotermes spp. Coptotermes formosanus No Termite activity found in Recruit AG station(s) Termite activity found in Recruit AG station(s)					
Target Pest = Subterranean Termites Reticulitermes spp. Heterotermes spp. Coptotermes formosanus Installed auxiliary station(s) Station #(s): Removed Recruit II Baitube and reinstalled monitoring devices in station(s) Station #(s):					Termite activity found in Recruit AG station(s) Station #(s): additional (new) Recruit AG station(s) Station #(s): Recruit AG station(s) Station #(s): Recruit AG station(s) Station #(s): Recruit AG station(s)					
Static	damaged st on #(s): oved and/or relocated on #(s):	ation(s)								
Comments Found no terrete activity.					Licensed and Regulated under the Structural Pest Control Act Texas Structural Pest Control Board 1106 Clayton Lane, Suite 100 LW • Austin, TX 78723 Phone: (512) 451-7200					
*Trademark o	DowElanco			Set	vice	Sechaician's Signature		Date		

Customer's Signature

estession in terminal

Special Service Instructions:

Treat for infestation/Prevention or Inspect areas indicated. Customer not home.

Service Technician's Signature

UPON REQUEST TERMINIX WILL PROVIDE THE PURCHASER WITH A COPY OF THE MANUFACTURER'S SPECIMEN LABEL OF THE PESTICIDE(S) WHICH

Amount Paid