

LINE TABLE		
LINE	LENGTH	BEARING
L1	60.46	S24°30'37\"W
L2	70.01	S16°42'21\"W
L3	53.56	S10°09'22\"W
L4	147.23	S01°14'05\"W
L5	199.53	S00°55'40\"E
L6	364.86	S01°00'26\"E
L7	333.34	S00°25'54\"E
L8	232.16	S01°13'32\"W
L9	121.65	S02°42'52\"W
L10	125.04	S04°25'28\"W
L11	75.71	S09°02'15\"W
L12	86.67	S13°19'13\"W
L13	261.69	S13°21'37\"W
L14	232.71	S13°44'59\"W

POB - POINT OF BEGINNING
THE IRON PIN FOUND (CONDUIT) AT THE
COMMON LAND LOT CORNER OF LAND LOTS
165, 166, 193, & 194.


FIELD DATA:
CLOSURE: 1\" per 27,000'
ANGULAR ERROR: 1\" per ANGLE POINT
ADJUSTED BY: COMPASS RULE

PLAT CLOSURE:
1\" per 400,000'

EQUIPMENT USED:
TOPCON GTS 313



- MONUMENT FOUND (1/2\" REBAR UNLESS NOTED)
- BREAK IN COURSE
- UTILITY POLE



SURVEY FOR:

RON PELFREY & LUANNE PELFREY

LAND LOT 142 & 143 19th LAND DISTRICT
G.M.D. 396 MORGAN COUNTY, GEORGIA

LAND LOT 192 & 193 19th LAND DISTRICT
G.M.D. 290 JASPER COUNTY, GEORGIA

SCALE: 1\" = 400'

DATE: APRIL 11, 2005

BALDWIN ENGINEERING
& SURVEYING, LLC
150 WEST WASHINGTON STREET
MADISON, GA 30650 PH: (706) 342-0191