




1155 Sours

1155 Township Chickasaw County Chickasaw

Date Installed Sept 1990

Installed: 3" 4" 5"

6" 8" Larger

Regular inspection of the tile system is essential. Prompt repair of any failure will keep the system in working order and maintenance costs low.

PAT FINNEGAN CONSTRUCTION CO., IONIA, IOWA 50645