VALLEY VISTA RANCH

12098 Vista Oaks Lane Hearne, TX 77859

Secluded, Rolling acreage with a Custom Home, Barns and Distant Views



Conveniently located between Hearne and Bryan/College Station in Robertson County. Enjoy peaceful country living, distant views, amazing sunsets and all the privacy this property has to offer. This custom, rock home was built with efficiency and comfort in mind.









Built in 2002 the home features a stone veneer, standing seam metal roof with energy saving reflective decking. A cozy 1,800sf heated (2,630 sf total under roof) three bedroom, two bath with a large, well designed utility/mudroom area and an office with lots of built-ins for storage and organization.

Inside the home features stained and etched concrete floors, with carpet in the bedrooms, Custom Kent Moore cabinets, wood blinds and ceiling fans throughout, there is a ceiling high rock fireplace and vaulted ceilings with beautifully stained accent beams. The living area is bright and open with lots of windows to enjoy the outdoor beauty. A covered patio out back offers a place for relaxation and outdoor entertaining, while viewing the Deer that frequently make backyard visits.













It has 2 AC units zoned, insulated garage door with electric opener, home alarm system, fluorescent lighting, lawn sprinkler system, aerobic septic system and high speed wireless internet. The home is situated on a hilltop overlooking the Brazos River Valley, Mumford and Valley Junction. The ranch is partially open with improved Coastal Bermuda pastures and partially wooded with lots of wildlife activity. The ranch features many other improvements in addition to the home.





Three spacious bedrooms and 2 comfortable baths feature solid surface countertops and enclosures. The master suite features a tiled walk-in shower and a large walk-in closet. With a split floor-plan the guest rooms share a hall bath and each have their own closets.







The insulated and sheet rocked garage enters through the mud/utility room. Great for cleaning up after a hard days work. This room features built-in cabinets and a freezer space for additional storage; plus the office at one end is quiet and private for getting your paperwork work done.











There is a large 60×50 workshop, with concrete flooring, 3 overhead doors, one pass through door and a dropped level, concreted RV garage, and a side equipment/livestock apron.











Another garage with overhead door is used for additional storage or parking next to the large barn.







Additionally, there is a hay/feed/tack storage room with pass through doors on each side for feeding convenience.











Several smaller livestock barns and shelters, pens and cross-fencing are located throughout the property for you livestock maintaining convenience. All of which have water in place. The improved pasture areas are well maintained and there is a pond for your fishing pleasure. There are also two water wells, a separate sprinkler system for the pecan grove, water lines running to the pond, three electric meters in place and water and electricity to the front gate.







There is a paved driveway from the commercial gated entry and a small helipad near the front of the large workshop. There is an additional pad site set up with water, power and septic, previously for a mobile home, that could now be used as an RV site or to build a guest cabin.
















Shown By Advance Appointment Only

Purchase Options Available

- ** 1) Home & Improvements on Tract 1- 13.6 Acres \$ 349,000.00
- ** 2) Home & Improvements on Tracts-1 & 2- 29.5 Acres \$ 430,000.00
 - ** 3) Home, Improvements and all 48.9 Acres \$ 495,000.00

For More Information:

info@cunninghamrealestate.com

www.CunninghamRealEstate.com

(979) 279-2757 or (800) 345-2757

Recap of Improvements


LAND

3 Barns

- 1 steel metal building 60x50 with concrete floor with livestock/eqt apron, Plus a concreted, dropped level RV garage on the opposite side
 - 1 Wood framed, metal sided garage with overhead and a side pass through door
 - 1 livestock shelter, plus numerous smaller individual livestock shelters
 - Paved drive
 - 2 cattle guards
 - Pipe, metal entrance
- Commercial gate opener at entry with free exit, remotes and keypad
 - Appx 80% is new fencing with cross-fencing
 - Appx 70% of the fences are in metal posts
 - Irrigated Pecan Orchard with paper shell pecans
 - 2 water wells 1 @ 250'(Barn) and 1 @ 800'(House)
 - 3 electric meters
 - RV or Mobile Home site with water, power & septic
 - Pond with water lines running to it
 - Water and Electricity run to the front gate

Home

- Built in 2002
- Standing seem metal roof w/ reflective decking
 - Stone veneer
 - 2 AC units Zoned
- 100% fluorescent lighting throughout the home
- Custom Kent Moore cabinets, wood blinds and ceiling fans
 - Wireless HS internet
 - Tiled message shower in master suite
- Home alarm system with fire alarm on water heater, plus CO alarm
 - Low utility bills
 - Insulated garage door with electric opener
 - Aerobic Septic system
 - Fenced yard with sprinkler system
 - Covered back patio with great views !!





TEXAS ASSOCIATION OF REALTORS® SELLER'S DISCLOSURE NOTICE

©Texas Association of REALTORS®, Inc. 2007

Section 5.008, Property Code requires a seller of residential property of not more than one dwelling unit to deliver a Seller's Disclosure Notice to a buyer on or before the effective date of a contract. This form complies with and contains additional disclosures which exceed the minimum disclosures required by the Code.

CONCERNING THE PRO	OPE	RT	YA	r_L	20	9	8 Vista 0	AK	ſ	1	ane	Heorne, 7x 77850	7		
THIS NOTICE IS A DISC DATE SIGNED BY SEL	LER	SUI AI	RE (OF SE	ELI	ER'	S KNOWLEDGE O	FTH	HE	CO	NDI	TION OF THE PROPERTY AS IONS OR WARRANTIES TH SELLER'S AGENTS, OR AN	SO	11 11	CD
Seller ★is □ is not or	ccup	yin	g th	e Pro	per	ty. I	f unoccupied (by Sever occupied the Pr	ller)	, h	now	long	since Seller has occupied the	Pro	per	rty?
Section 1. The Proper	ty ha	as t	the i	items	m	arke	d below: (Mark Ye	s (Y).	No ((N), c	or Unknown (U).) e which items will & will not conve	V		
Item	Y		U		ter			_	_	V U	-	Item	Y	N	U
Cable TV Wiring	X			(Ga	s Lir	es (Nat/LP)	X	Ť	-		Pump: ☐ sump ☐ grinder	•	V	-
Carbon Monoxide Det.	X				_	Tub			7			Rain Gutters		\wedge	
Ceiling Fans	X			1	nte	ercor	n System		5			Range/Stove	V		
Cooktop	X					rowa		X	1			Roof/Attic Vents	Ŷ		
Dishwasher	X			(Du	tdoo	r Grill	1	1	1		Sauna	/\	X	
Disposal	X			F	at	io/Đ	ecking concrete	X	-			Smoke Detector	X	/\	-
Emergency Escape		V				-	ng System	V	t			Smoke Detector - Hearing	/\	,	V
Ladder(s)		\wedge						X				Impaired			X
Exhaust Fans	X			F	000	ol		3)	/		Spa		Y	_
Fences	X			F	000	ol Ec	uipment		1	Ž		Trash Compactor		$\overrightarrow{\checkmark}$	
Fire Detection Equip.	X						aint. Accessories		15	7		TV Antenna	X	$^{\wedge}$	
French Drain		X			-		ater		5		1	Washer/Dryer Hookup	\Diamond		
Gas Fixtures	X			F	Pul	olic S	Sewer SystemPrivot	4	5	2		Window Screens	X		
Item		_		V	- A	1 11			_						
Central A/C				Y	- 1	1 U	A clastic P					al Information			
Evaporative Coolers		_			1	/	number of units:	s n	ur	nber	ot u	nits: 2			
Wall/Window AC Units					1			-	_						
Attic Fan(s)					1		number of units:	K	<i>></i>		_				
Central Heat					/	\	if yes, describe:	- 7	_	_					
Other Heat				^	1	/	delectric Aga	s n	ur	nber	of u	nits: 2			
100000000000000000000000000000000000000		_			1	1	if yes, describe: _	-			<i>y</i> .				
Oven		_			+	+	number of ovens:	=	_			tric gas other:			_
Fireplace & Chimney Carport				-	1		wood gas lo		_			other:	_		
					1	-				che	-				
Garage Door Openers					+	+			_	che	d				
Satellite Dish & Controls			Not		1	+	number of units:		3		2	number of remotes:3			
Security System	5 5	tal	1	V	-	+	☑ owned ☐ leas		_	_		YR Contract			
Water Heater		_			-	+	owned leas		_	-		ADT	-		
Water Softener		_		-	-		electric gas		_	other	:	number of units:	1		
	mida			X	+	1	owned leas			-					
Underground Lawn Spri		_			-	+		man	_			covered: House Fenced	_	arc	1
Septic / On-Site Sewer	raci	III	· Farm		1_	_		mat	10	n Ab	out (On-Site Sewer Facility (TAR-1	407)	
(TAR-1406) 7-2-07 Cunningham Real Estate 1205 5 Market, Heal Cunningham Real Estate	ne TX	7859		aled I			er: by RE-Porms Net, LLC 18025 Fit	teen M		Diam.	uyer		age		of 5

Concerning the Property at _		120	98 015	1 4	U	AKS	Lane	- TRar	me /x	77869		
Water supply provided by: [] ci	ty 🔼	well MUD) [100-0	on \square ur	known	other:		7 0 % (
Was the Property built befor	e 1	9/8/	∐ yes ⊅ho	[] unk	known						
(If yes, complete, sign,	and	attach	1 I AR-1906 co	once	erning	lead-ba	sed pain	t hazards).				
Roof Type: metal		tani	ding SEA	MA	ge:_	5	YRS			(appro	xim	ate
Is there an overlay roof cove	ering	g on th	e Property (sh	ning	les or	r roof cov	ering pla	aced over e	xisting shingle	s or roof co	veri	ng)
Are you (Seller) aware of an	v of	f the ite	ame listed in the	nic (Contin	s = 1 4h = 4						
Are you (Seller) aware of an	lno	If you	describe (et	IIS C	Section	on I that	are not i	n working o	ondition, that h	have defects	s, or	ar
need of repair? yes	N IO	ii yes	s, describe (at	lacr	addi	tional she	eets if ne	ecessary): _				
Section 2. Are you (Seller	r) av	ware o	of any defects	or	malf	innetiene		- 5 11 - 5 11		2000 to 000 to 000		
Section 2. Are you (Seller aware and No (N) if you are	no	t awar	re.)	. 01	man	unctions	s in any	of the folio	owing?: (Mark	Yes (Y) if	you	ar
Item	Y	N	Item				YN	Item			V	- NI
Basement NA			Floors				X		alks at Ft	D. F. d	X	N
Ceilings		X	Foundatio	n/5	Slab(s	3)	X		Fences	cont arial	1	
Doors		X	Interior Wa			/	X	Window			+	X
Driveways		X	Lighting Fi		es		X			2020210	+	4
Electrical Systems		X	Plumbing				X	Others	Structural Com	ponents	+	X
Exterior Walls		X	Roof	-,-			×					-
If the answer to any of the ite												
	Bro	ken	Corner	,	I	drove	Moto	1- Home	0027.		0 (1	l) i
Sidewalk has A	Bro	ken	Corner	follo	I c	g conditi	ons: (M	- Home	0027.			
Sidewalk has A Section 3. Are you (Seller you are not aware.) Condition	Bro	ken	Corner	follo	I	g conditi	ions: (M	ark Yes (Y	0027.			N
Section 3. Are you (Seller you are not aware.) Condition Aluminum Wiring	Bro	ken	Corner	follo	I c	g conditi	ions: (M	ark Yes (Y	0027.			N
Section 3. Are you (Seller you are not aware.) Condition Aluminum Wiring Asbestos Components	g, o	ken	Corner	follo	I c	g condition Previous Other	ions: (M	ark Yes (Y	0027.			N
Section 3. Are you (Seller you are not aware.) Condition Aluminum Wiring Asbestos Components Diseased Trees:	r) av	ware o	of any of the	follo	I c	Condition Other Rado	ions: (M lition ous Root Structur n Gas	ark Yes (Y	0027.			N
Section 3. Are you (Seller you are not aware.) Condition Aluminum Wiring Asbestos Components	r) av	ware o	of any of the	follo	I c	Condition Other Rado Settling	ions: (M lition ous Root Structur n Gas	ark Yes (Y	0027.			N X X X
Section 3. Are you (Seller you are not aware.) Condition Aluminum Wiring Asbestos Components Diseased Trees: ak wi Endangered Species/Habita	r) av	ware o	of any of the	follo	I c	Condition Previous Other Rado Settlin Soil N	ions: (M lition ous Room Structur n Gas ng	ark Yes (Y) f Repairs ral Repairs) if you are av			N
Section 3. Are you (Seller you are not aware.) Condition Aluminum Wiring Asbestos Components Diseased Trees: ak wi Endangered Species/Habita Fault Lines Hazardous or Toxic Waste	r) av	ware o	of any of the	follo	I c	Condition of the condit	ions: (M lition ous Room Structum n Gas ng Movement	ark Yes (Y) f Repairs ral Repairs nt tructure or F) if you are av			N X X X
Section 3. Are you (Seller you are not aware.) Condition Aluminum Wiring Asbestos Components Diseased Trees: ak wi Endangered Species/Habita Fault Lines Hazardous or Toxic Waste Improper Drainage	r) av	ware o	of any of the	follo	I c	Condition Previous Other Rado Settlin Soil M. Substituted Under	ions: (M lition ous Room Structure n Gas ng Movemer urface Si	ark Yes (Y) f Repairs ral Repairs nt tructure or F) if you are av			N X X X
Section 3. Are you (Seller you are not aware.) Condition Aluminum Wiring Asbestos Components Diseased Trees: ak wi Endangered Species/Habita Fault Lines Hazardous or Toxic Waste	r) av	ware o	of any of the	follo	I c	Condition Previous Other Rado Settlin Soil N Subsitunde Unpla	ions: (M lition ous Room Structur n Gas ng Movement urface Si rground atted Eas	ark Yes (Y) f Repairs ral Repairs nt tructure or F Storage Ta sements) if you are av			N X X X
Section 3. Are you (Seller you are not aware.) Condition Aluminum Wiring Asbestos Components Diseased Trees: oak wi Endangered Species/Habita Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Spri	Rry) av	ware o	of any of the	follo	I c	Condition of the condit	ions: (Mailition ous Room Structum n Gas and Movemer ourface Signature of the Corded East	f Repairs ral Repairs nt tructure or F Storage Ta sements asements) if you are av			N X X X
Section 3. Are you (Seller you are not aware.) Condition Aluminum Wiring Asbestos Components Diseased Trees: oak wi Endangered Species/Habita Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Spri Landfill Lead-Based Paint or Lead-F	r) av	ware o	of any of the	follo	I c	Condition Previous Other Rado Settlin Soil M Substitute Unpla Unreception Urea-	ions: (M lition ous Room Structure n Gas ng Movement urface Si rground atted East corded E	f Repairs ral Repairs nt tructure or F Storage Ta sements asements asements	Pits	ware and N	Y	N X X X
Section 3. Are you (Seller you are not aware.) Condition Aluminum Wiring Asbestos Components Diseased Trees: aoak wi Endangered Species/Habita Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Spri Landfill Lead-Based Paint or Lead-Reservant of the Pri	r) av	ware o	erty	follo	I c	Condition of the condit	ions: (M lition ous Room Structur n Gas ng Movemer urface Si rground atted East corded E formalder	f Repairs ral Repairs rat tructure or F Storage Tal sements asements asements) if you are av	ware and N	Y	N X X X
Section 3. Are you (Seller you are not aware.) Condition Aluminum Wiring Asbestos Components Diseased Trees: oak wi Endangered Species/Habita Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Spri Landfill Lead-Based Paint or Lead-F	r) av	ware o	erty	follo	I c	Condition of the condit	ions: (Mailition ous Room Structum n Gas and Movemer arted East corded East co	f Repairs ral Repairs rat tructure or F Storage Tal sements asements asements	Pits	ware and N	Y	N X X X
Section 3. Are you (Seller you are not aware.) Condition Aluminum Wiring Asbestos Components Diseased Trees: aoak wi Endangered Species/Habita Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Spri Landfill Lead-Based Paint or Lead-E Encroachments onto the Pri Improvements encroaching Located in 100-year Floodp Present Flood Insurance Co	ings Baseope	ware o	erty	follo	I c	Condition of the condit	ions: (Mailition ous Room Structum n Gas ang Movemer urface Signaturface Signaturface East corded East corded East corded East formalded and son Fill Rot	ark Yes (Y) f Repairs ral Repairs rat tructure or F Storage Ta sements asements ehyde Insula ation Property	Pits nks ation Barn - Motor	ware and No	Y	N X X X
Section 3. Are you (Seller you are not aware.) Condition Aluminum Wiring Asbestos Components Diseased Trees: oak wi Endangered Species/Habita Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Spri Landfill Lead-Based Paint or Lead-I Encroachments onto the Pri Improvements encroaching Located in 100-year Floodp	ings Baseope	ware o	erty	follo	I c	Condition Previous Other Rado Settlin Soil M Subsi Unde Unpla Unrec Urea- Wate Wetla Wood Active	ions: (M lition ous Room Structur n Gas ng Movemer urface Si rground atted East corded E formalder r Penetra ands on F	ark Yes (Y) f Repairs ral Repairs rat tructure or F Storage Ta sements asements ehyde Insula ation Property	Pits	ware and No	Y	N X X X
Section 3. Are you (Seller you are not aware.) Condition Aluminum Wiring Asbestos Components Diseased Trees: oak wi Endangered Species/Habita Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Spri Landfill Lead-Based Paint or Lead-I Encroachments onto the Pri Improvements encroaching Located in 100-year Floodp Present Flood Insurance Co (If yes, attach TAR-1414) Previous Flooding into the S	Basiope on lain	ware o	erty	follo	I c	Condition of the condit	ions: (Mailition ous Room Structum n Gas and Movemer urface Signaturface Signaturface East corded East corded East formalded and son Fill Rot exinfestate bying ins	f Repairs	Pits nks ation Barn - Motor	ware and No	Y	N X X X
Section 3. Are you (Seller you are not aware.) Condition Aluminum Wiring Asbestos Components Diseased Trees: oak wi Endangered Species/Habita Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Spri Landfill Lead-Based Paint or Lead-Encroachments onto the Pri Improvements encroaching Located in 100-year Floodp Present Flood Insurance Co (If yes, attach TAR-1414) Previous Flooding into the Servious Flooding onto the	Basiope on lain	ware o	erty	follo	I c	Condition of the condit	ions: (Mailition ous Roof Structurent Gas and Movement our face Signaturent Gas and Garded East our face our fa	f Repairs ral Repairs ral Repairs rat ructure or F Storage Ta sements casements caseme	Pits nks ation Barn - Motor	Ware and No	Y	N X X X
Section 3. Are you (Seller you are not aware.) Condition Aluminum Wiring Asbestos Components Diseased Trees: oak wi Endangered Species/Habita Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Spri Landfill Lead-Based Paint or Lead-I Encroachments onto the Pri Improvements encroaching Located in 100-year Floodp Present Flood Insurance Co (If yes, attach TAR-1414) Previous Flooding into the Selevious Flooding onto the Previous Flooding onto the Previous Fires	ings Basiope on lain over	ware o	erty	follo	I c	Condition Previous Condition Pre	ions: (Mailition ous Room Structum n Gas ng Movemer urface Structude East corded East cord	ark Yes (Y) f Repairs ral Repairs rat tructure or F Storage Tal sements easements easements casements c	Pits nks ation Barn - Motor ites or other wo	ware and No	Y	N X X X
Section 3. Are you (Seller you are not aware.) Condition Aluminum Wiring Asbestos Components Diseased Trees: oak wi Endangered Species/Habita Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Spri Landfill Lead-Based Paint or Lead-Encroachments onto the Pri Improvements encroaching Located in 100-year Floodp Present Flood Insurance Co (If yes, attach TAR-1414) Previous Flooding into the Servious Flooding onto the	ings Basiope on lain over	ware o	erty	follo	I c	Condition of the condit	ions: (Maintenance of the infestate of t	f Repairs ral Repairs ral Repairs rat tructure or F Storage Ta sements easements easements casements casem	Pits nks ation Barn - Motor	ware and No	Y	N X X X

Produced with ZipForm™ by RE FormsNet, LLC 18025 Fifteen Mile Road, Clinton Township, Michigan 48035 www.zipform.com

Se	The ction	Born has a motor Home Strage and water will seep after heavy Pains. 4. Are you (Seller) aware of any item, equipment, or system in or on the Property that is in need of repair, as not been previously disclosed in this notice? The Theory of the Property that is in need of repair,
		as not been previously disclosed in this notice? yes no If yes, explain (attach additional sheets if
Se	ction 5	5. Are you (Seller) aware of any of the following (Mark Yes (Y) if you are aware. Mark No (N) if you are
<u>Y</u>	N	Room additions, structural modifications, or other alterations or repairs made without necessary permits or not in compliance with building codes in effect at the time.
	X	Homeowners' associations or maintenance fees or assessments. If yes, complete the following: Name of association: Manager's name: Fees or assessments are: \$ per and are: \ mandatory \ voluntary Any unpaid fees or assessment for the Property? \ yes (\$) \ no If the Property is in more than one association, provide information about the other associations below or attach information to this notice.
	×	Any common area (facilities such as pools, tennis courts, walkways, or other) co-owned in undivided interest with others. If yes, complete the following: Any optional user fees for common facilities charged? yes no If yes, describe:
	Ø	Any notices of violations of deed restrictions or governmental ordinances affecting the condition or use of the Property.
	Ø	Any lawsuits or other legal proceedings directly or indirectly affecting the Property.
	×	Any death on the Property except for those deaths caused by: natural causes, suicide, or accident unrelated to the condition of the Property.
	M	Any condition on the Property which materially affects the health or safety of an individual.
	P(Any repairs or treatments, other than routine maintenance, made to the Property to remediate environmental hazards such as asbestos, radon, lead-based paint, urea-formaldehyde, or mold. If yes, attach any certificates or other documentation identifying the extent of the remediation (for example, certificate of mold remediation or other remediation).
		ver to any of the items in Section 5 is yes, explain (attach additional sheets if necessary):
		6) 7-2-07 Initialed by: Seller:, and Buyer:, Page 3 of 5

Concerning the Pro	perty at12098	Vista OAKs Lone	, Heorne, TX 77859	
Section 6. Seller	has has n	ot attached a survey o	of the Property.	
Section 7. Withir regularly provide	the last 4 years	, have you (Seller) re	ceived any written inspection	n reports from persons who permitted by law to perform
Inspection Date	Туре	Name of Inspector		
11/1/10/07	Sewer		ld systems	No. of Pages
		C Douge	14 14 1 km)	
Pr	operty. A buyer s	snould obtain inspecti	eports as a reflection of the co	by the buyer.
Section 8. Check Homestead	any tax exemption	on(s) which you (Selle Senior Citizen	r) currently claim for the Prop	erty:
Wildlife Mana	gement	Agricultural	☐ Disabled Veteral	n
Other:	wes:		Unknown	
Section 10. Does requirements of C (Attach additional si	the property hav hapter 766 of the neets if necessary)	re working smoke de Health and Safety Cod	tectors installed in accordante?* unknown no	ce with the smoke detector yes. If no or unknown, explain.
smoke detec which the dv know the bu	ctors installed in a velling is located, i	occordance with the req including performance, ements in effect in your	nuirements of the building code location, and power source requ area, you may check unknown	in effect in the area in uirements. If you do not
Seller acknowledge broker(s), has instru	s that the statement acted or influenced	nts in this notice are true Seller to provide inacci	e to the best of Seller's belief an urate information or to omit any	d that no person, including the material information.
Signature of Seller	Damil	11/19/07 Date	Signature of Seller Printed Name:	Date
Printed Name: 114	ICK C, MARI	no sa	Printed Name:	Date
(TAR-1406) 7-2-07	الماما	led by: Seller:	and Buyer:	
(1/11-1400) /-2-0/	initia	led by, Seller:	, and Buyer:	_, Page 4 of 5

ADDITIONAL NOTICES TO BUYER:

The following providers surrently and it

- (1) The Texas Department of Public Safety maintains a database that the public may search, at no cost, to determine if registered sex offenders are located in certain zip code areas. To search the database, visit www.txdps.state.tx.us. For information concerning past criminal activity in certain areas or neighborhoods, contact the local police department.
- (2) If the property is located in a coastal area that seaward of the Gulf Intracoastal Waterway or within 1,000 feet of the mean high tide bordering the Gulf of Mexico, the property may be subject to the Open Beaches Act or the Dune Protection Act (Chapter 61 or 63, Natural Resources Code, respectively) and a beachfront construction certificate or dune protection permit may be required for repairs or improvements. Contact the local government with ordinance authority over construction adjacent to public beaches for more information.
- (3) If you are basing your offers on square footage, measurements, or boundaries, you should have those items independently measured to verify any reported information.

(4)	The following providers currently provide service to the p	property:	
	Electric: Navosota Velley Electric	_ Sewer: Private	Scwer Plant
	Water: Private water wells (2)	_ Cable: _ Direct	TV
	Trash:	Natural Gas:	
	Local Phone: AT+T (SWB)	Propane: Shor	p Propone
(5)	This Seller's Disclosure Notice was completed by Seller as true and correct and have no reason to believe it to AN INSPECTOR OF YOUR CHOICE INSPECT THE PROPERTY OF THE PROPER	be false or inaccurate. Y	ne brokers have relied on this notice OU ARE ENCOURAGED TO HAVE
dete	undersigned Buyer acknowledges receipt of the foregoike detector requirements of Chapter 766, Health and Safetor requirements of Chapter 766, the buyer waives the background Chapter 766.	ety Code, or, if the prope	erty does not comply with the smale
	ature of Buyer Date ted Name:	Signature of Buyer Printed Name:	Date



INFORMATION ABOUT ON-SITE SEWER FACILITY

USE OF THIS FORM BY PERSONS WHO ARE NOT MEMBERS OF THE TEXAS ASSOCIATION OF REALTORS® IS NOT AUTHORIZED. ©Texas Association of REALTORS®, Inc., 2004

CO	NCERNING THE	PROPERTY AT	12098 Vista	OAKS LN	Hearne, Tx	77859
A.	DESCRIPTION (OF ON-SITE SEWE	ER FACILITY ON	PROPERTY:		
	(1) Type of Treat		Septic Tank	second .	c Treatment	Unknown
	(2) Type of Distri	bution System:	sprinkler L	reads		Unknown
	(3) Approximate Two particles	Location of Drain F ture near	Field or Distribution	on System:	morked wi	Unknown
	(4) Installer:	c Dougeld	Systems, I.	nc dba To	exas Jet Sucte	ms Inc Unknown
	(5) Approximate	Age: 8/19	96 11	YRS	7,7.	Unknown
B.	MAINTENANCE					Officiown
	Phone: 936	contracts must be	tractor: (e K = 1	iration date:	Var 1 2000	Yes No
	(2) Approximate	date any tanks wer	e last pumped?	Never	e	
		e of any defect or i				☐ Yes ☒ No
	-					
0		ave manufacturer			le for review?	Yes 🔲 No
C.		ERIALS, PERMITS				
	blanning r	items concerning t materials	t for original inst	allation / Nin	ached: al inspection wher ranty information〔	OSSF was installed
	(2) "Planning ma submitted to t	terials" are the su	upporting materi	als that desc	ribe the on-site so to install the on-site	ewer facility that are e sewer facility.
	(3) It may be n transferred to	ecessary for a	buyer to have	the permit t	to operate an or	n-site sewer facility
					0 -	1
	2-1407) 1-7-04	Initialed for Identif	ication by Buyer		and Seller	Page 1 of 2
hone	ngham Real Estate 1205 S M : (979) 279-2757 F	farket, Hearne TX 77859 fax: (979) 279-5338	Cunningham Real Est		U	V-1

Marino.zfx

D. INFORMATION FROM GOVERNMENTAL AGENCIES: Pamphlets describing on-site sewer facilities are available from the Texas Agricultural Extension Service. Information in the following table was obtained from Texas Commission on Environmental Quality (TCEQ) on 10/24/2002. The table estimates daily wastewater usage rates. Actual water usage data or other methods for calculating may be used if accurate and acceptable to TCEQ.

<u>Facility</u>	Usage (gal/day) without water- saving devices	Usage (gal/day) with water- saving devices
Single family dwelling (1-2 bedrooms; less than 1,500 sf) Single family dwelling (3 bedrooms; less than 2,500 sf) Single family dwelling (4 bedrooms; less than 3,500 sf) Single family dwelling (5 bedrooms; less than 4,500 sf) Single family dwelling (6 bedrooms; less than 5,500 sf) Mobile home, condo, or townhouse (1-2 bedroom) Mobile home, condo, or townhouse (each add'l bedroom)	225 300 375 450 525 225 75	180 240 300 360 420 180 60

This document is not a substitute for any inspections or warranties. This document was completed to the best of Seller's knowledge and belief on the date signed. Seller and real estate agents are not experts about on-site sewer facilities. Buyer is encouraged to have the on-site sewer facility inspected by an inspector of Buyer's choice.

Signature of Seller	g (o 7 Date	Signature of Seller	Date
Receipt acknowledged by:			
Signature of Buyer	Date	Signature of Buyer	Date

McDougald System

71860 FM 244 Iola, Tx 77861 936-394-2507

SAMPLE TESTING AND REPORTING RECORD

receive one copy of this record as well as an invoice for work performed during inspection. A copy of this record will also be sent to the local permitting authority and the maintenance company will retain a copy.

li	System Owner Mani- roperty Address 1209 Heam Permit Number 1981 County Robe ispectors Initials Record Desimation Robe	8 Vista Odk Lane ie, TX - 77959 07 vtson
Inspected Item	Operational	Non-Operational
Aerators	V	
Filters		
Imigation Pumps		
Recirculation Pumps		
Disinfecting Device	4	
Chlorine Supply		
Electrical Circuits		
Distribution System		
Spraufield Vegetation/Seeding		[]

4 Repairs to System (List components replaced).

Other as Noted

5 Test required and results

Annual Visits - 3

Date of Visit

Test	Requ	tred	Results	Test Method	
	Yes	No	mg/1, mpn/100ml, or Trace		
BOD (Grab)		4			
TSS (Grab)		4			
Cl ₂ (Grab)	-		6		
Fecal Coliforn			*		

6 General Comments or Recommendations:

