

### TEXAS ASSOCIATION OF REALTORS®

#### SELLER'S DISCLOSURE NOTICE

©Texas Association of REALTORS®, Inc. 2016

Section 5.008, Property Code requires a seller of residential property of not more than one dwelling unit to deliver a Seller's Disclosure Notice to a buyer on or before the effective date of a contract. This form complies with and contains additional disclosures which exceed the minimum disclosures required by the Code.

CONCERNING THE PROPERTY AT						2732 Goehmann Lane Fredericksburg, TX 78624									
DATE SIGNED BY SELLER AND IS NOT A					A	ER'S KNOWLEDGE OF THE CONDITION OF THE PROPERTY AS OF THE A SUBSTITUTE FOR ANY INSPECTIONS OR WARRANTIES THE BUYER RANTY OF ANY KIND BY SELLER, SELLER'S AGENTS, OR ANY OTHER									
Seller is is not occupying the Property.							f unoccupied (by Seller), lever occupied the Proper		v Ic	ng s	since Seller has o	cupied the P	'rop	ert	y?
Section 1. The Property ha	as stat	<b>the</b>	ite	ems e ite	ms	ark to	ted below: (Mark Yes (Y) be conveyed. The contract w	), N	lo ( dete	(N), e	or Unknown (U).) e which items will &	will not convey	<b>/</b> .		
Item	Y	N	U		It	em		Υ	N	U	Item		Y	N	U
Cable TV Wiring			X	1	Li	qui	d Propane Gas:		X	Ħ	Pump: sum	p grinder	H	-	V
Carbon Monoxide Det.			X	1			Community (Captive)		X	Н	Rain Gutters	grinder	Н	X	$\overline{}$
Ceiling Fans	X		,	1	$\overline{}$		on Property		^	X	Range/Stove		1	^	
Cooktop	_		V			ot 7		$\vdash$	1	1	Roof/Attic Ven	9	X		X
Dishwasher		V	_	1	_	-	com System		2	$\overline{}$	Sauna	3	Н	7	^
Disposal		V			_		owave		2	Н	Smoke Detector	nr .	Н	7	Х
Emergency Escape		^					oor Grill		,	Н	Smoke Detecto		Н		$\overline{}$
Ladder(s)		X	_						X		Impaired				X
Exhaust Fans			×		Patio/Decking				X		Spa			×	
Fences	X				Plumbing System			Х			Trash Compac	tor		×	
Fire Detection Equip.			X		Pool				X		TV Antenna				X
French Drain			X		Pool Equipment				3		Washer/Dryer		X		
Gas Fixtures		Ĺ.,	X		Pool Maint. Accessories				X		Window Scree	าร			X
Natural Gas Lines		X			Р	ool	Heater		X		Public Sewer S	ystem		X	
Item				Y	N	U		Λ	44	ition	al Information				
Central A/C				i	-	Ü	electric gas numl	_							$\dashv$
Evaporative Coolers				^			number of units:	Dei	UI	uriita	o				_
Wall/Window AC Units				V		number of units:		_						$\dashv$	
Attic Fan(s)			-	Α		if yes, describe:	-					_		$\dashv$	
Central Heat			_	V		^	electric gas numl	hor	of	unite	s·			_	$\dashv$
Other Heat			-	0	-		if yes, describe: Woor						_		$\neg$
Oven				Ç			number of ovens:	١.		elect		-	_	_	-
Fireplace & Chimney			_	0	×	•		mo	_		other:	•		-	_
Carport				-	×		attached not attac	_	_		outer.			-	-
Garage				$\frac{4}{\sqrt{2}}$		attached not attac	_							$\dashv$	
Garage Door Openers			7		number of units:	1100		-	number of remotes				_		
Satellite Dish & Controls			Ŷ		owned lease from:				idinber of remotes	·		_	$\dashv$		
Security System				owned lease from:											
Water Heater				✓ electricgasother: number of units:											
Water Softener			~	owned lease from:											
Underground Lawn Sprinkler			_	Н	V		automatic manual		ear	s cov	vered:		11 12-11		
Septic / On-Site Sewer Facili				V	_		if yes, attach Information	_				v (TAR-1407	)	_	_
(TAR-1406) 01-01-16 Nixon Real Estate, 1325 E. Main Fredericksburg,			tial	ed t	y:	Buy	er:,and 9	Sell	er:	JX	997-2187 Fax:	Pa	ge 732 Ge		

Produced with zipForm® by zipLogix 18070 Fifteen Mile Road, Fraser, Michigan 48026 www.zipLogix.com

Scott Frantzen

## 2732 Goehmann Lane

Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property Located in 100-year Floodplain Located in Floodway Present Flood Ins. Coverage (If yes, attach TAR-1414) Previous Flooding into the Structures Previous Flooding onto the Property Located in Historic District  Soil Movement Subsurface Structure or Pits Underground Storage Tanks Unplatted Easements Unrecorded Easements Water Penetration Wetlands on Property Wood Rot Active infestation of termites or other wood destroying insects (WDI) Previous treatment for termites or WDI Previous termite or WDI damage repaired Previous Fires	Concerning the Property at						Fredericksb	ourg	, TX 7	78624		
Was the Property built before 1978? Yes_no_unknown (If yes, complete, sign, and attach TAR-1906 concerning lead-based paint hazards).  Roof Type:	Water supply provided by: city X well MUD					o-op	unknown	o	ther:			
(If yes, complete, sign, and attach TAR-1906 concerning lead-based paint hazards).  Roof Type:	Was the Property built before	re 19	78?	yes no	u	nknow	'n					
Roof Type:	(If yes, complete, sign, a	and a	attach	TAR-1906 co	nce	rning	lead-based	pain	t haza	rds).		
Is there an overlay roof covering on the Property (shingles or roof covering placed over existing shingles or roof covering)? _yes _ no _ unknown   Are you (Seller) aware of any of the items listed in this Section 1 that are not in working condition, that have defects, or are need of repair? _yes _x no If yes, describe (attach additional sheets if necessary):						Age:	1) dk	20	06/	(appro	xima	te)
Are you (Seller) aware of any of the items listed in this Section 1 that are not in working condition, that have defects, or are need of repair?yes _X no if yes, describe (attach additional sheets if necessary):	Is there an overlay roof covering on the Property (shingles						es or roof	cov	ering	placed over existing shingles	or r	roof
Section 2. Are you (Seller) aware of any defects or malfunctions in any of the following?: (Mark Yes (Y) if you are aware and No (N) if you are not aware.)    tem	covering)? yes no	unkr	nown									
Section 2. Are you (Seller) aware of any defects or malfunctions in any of the following?: (Mark Yes (Y) if you are aware and No (N) if you are not aware.)    tem	Are you (Seller) aware of a	nv o	f the it	tems listed in	this	Sect	ion 1 that a	re n	ot in w	orking condition, that have de	fects	or
Section 2. Are you (Seller) aware of any defects or malfunctions in any of the following?: (Mark Yes (Y) if you are aware and No (N) if you are not aware.)    Item	are need of repair? yes	/ no	o If yes	, describe (at	tach	addi	tional sheets	s if n	ecess	arv):	1000	, 01
Item												
Item							-					
Item												
Item	Section 2 Are you (Seller	r) au	vare o	f any defects	or	malfi	netions in	anı,	of the	following 2: /Mark Van (V) is		
Item   Y   N   Basement   X   Ceilings   X   Driveways   X   Driveways   X   Electrical Systems   X   Electrical System	aware and No (N) if you ar	e no	t awa	re.)	U	mant	inctions in	arry	or the	following?. (Mark Yes (Y) If	you	are
Basement  Ceilings  X Ceilings  X Driveways  Driveways  Electrical Systems  Exterior Walls  If the answer to any of the items in Section 2 is yes, explain (attach additional sheets if necessary):  Section 3. Are you (Seller) aware of any of the following conditions: (Mark Yes (Y) if you are aware and No (N) if you are not aware.)  Condition  Section 3. Are you (Seller) aware of any of the following conditions: (Mark Yes (Y) if you are aware and No (N) if you are not aware.)  Condition  Y N Aluminum Wiring  Asbestos Components  Diseased Trees: oak wilt  Endangered Species/Habitat on Property  Fault Lines  Hazardous or Toxic Waste  Improper Drainage  Intermittent or Weather Springs  Landfill  Lead-Based Paint or Lead-Based Pt. Hazards  Lead-Based Pint or Lead-Based Pt. Hazards  Lead-Based Pt. Haza		_						_				
Ceilings		Y	N					Υ	N		Y	N
Dorie Driveways   X   Lighting Fixtures   X   Lighting Fixtures   X   Exterior Walls   X   Roof   X			X						X	STATE OF THE PROPERTY OF THE P		X
Driveways Electrical Systems Exterior Walls  If the answer to any of the items in Section 2 is yes, explain (attach additional sheets if necessary):  Section 3. Are you (Seller) aware of any of the following conditions: (Mark Yes (Y) if you are aware and No (N) if you are not aware.)  Condition  Y N Aluminum Wiring Asbestos Components Diseased Trees: oak wilt Endangered Species/Habitat on Property Enzymous or Toxic Waste Improper Drainage Intermittent or Weather Springs Landfill Landfill Landfill Landfill Landfill Landfill Landfill Located in 100-year Floodplain Located in 100-year Floodplain Located in Floodway Previous Flooding onto the Property Previous Flooding into the Structures Previous Flooding onto the Property Previous Flooding into the Structures Previous Flooding onto the Property Previous Flooding						Slab(s	5)		X			
Electrical Systems   X   Roof    If the answer to any of the items in Section 2 is yes, explain (attach additional sheets if necessary):			X						V	Windows		X
Exterior Walls  If the answer to any of the items in Section 2 is yes, explain (attach additional sheets if necessary):  Section 3. Are you (Seller) aware of any of the following conditions: (Mark Yes (Y) if you are aware and No (N) if you are not aware.)  Condition  Y N  Aluminum Wiring  Asbestos Components  Diseased Trees: oak wilt  Endangered Species/Habitat on Property  Fault Lines  Hazardous or Toxic Waste  Intermittent or Weather Springs  Lendfill  Lead-Based Paint or Lead-Based Pt. Hazards  Encroachments onto the Property  Located in 100-year Floodplain  Located in 100-year Floodplain  Vervious Flooding onto the Property  Well And School Components  Well And School Components  V N  Previous Foundation Repairs  Y N  Previous Endoling Repairs  Y N  N Intermited Previous Foundation Repairs  Y N  N Intermited P			×						X	Other Structural Components		1×
If the answer to any of the items in Section 2 is yes, explain (attach additional sheets if necessary):    Section 3. Are you (Seller) aware of any of the following conditions: (Mark Yes (Y) if you are aware and No (N) if you are not aware.)    Condition			X	Plumbing	Sys	tems			X			
Section 3. Are you (Seller) aware of any of the following conditions: (Mark Yes (Y) if you are aware and No (N) if you are not aware.)  Condition Y N Aluminum Wiring	Exterior Walls		X	Roof					X			
Aluminum Wiring Asbestos Components Diseased Trees: oak wilt Endangered Species/Habitat on Property Hazardous or Toxic Waste Improper Drainage Improper Drainage Intermittent or Weather Springs Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property Located in 100-year Flooding into the Structures Previous Flooding into the Structures Previous Flooding into the Property Located in Historic District Previous Use of Premises for Manufacture  Previous Roof Repairs Other Structural Repairs Radon Gas Settling Soil Movement Subsurface Structure or Pits Underground Storage Tanks Underground Storage Tanks Unrecorded Easements Urrea-formaldehyde Insulation Water Penetration Wetlands on Property Wood Rot Active infestation of termites or other wood destroying insects (WDI) Previous treatment for termites or WDI Previous Flooding onto the Property Single Blockable Main Drain in Pool/Hot	Section 3. Are you (Seller you are not aware.)	r) aw	vare o	f any of the f	ollo	owing	conditions	: (N	lark Y	es (Y) if you are aware and I	lo (N	l) if
Aluminum Wiring Asbestos Components Diseased Trees: oak wilt Endangered Species/Habitat on Property Hazardous or Toxic Waste Improper Drainage Improper Drainage Intermittent or Weather Springs Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property Located in 100-year Flooding into the Structures Previous Flooding into the Structures Previous Flooding into the Property Located in Historic District Previous Use of Premises for Manufacture  Previous Roof Repairs Other Structural Repairs Radon Gas Settling Soil Movement Subsurface Structure or Pits Underground Storage Tanks Underground Storage Tanks Unrecorded Easements Urrea-formaldehyde Insulation Water Penetration Wetlands on Property Wood Rot Active infestation of termites or other wood destroying insects (WDI) Previous treatment for termites or WDI Previous Flooding onto the Property Single Blockable Main Drain in Pool/Hot					Y	N	Conditio	n			TV	N
Asbestos Components Diseased Trees: oak wilt Endangered Species/Habitat on Property Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property Located in 100-year Floodplain Located in Floodway Present Flood Ins. Coverage (If yes, attach TAR-1414) Previous Flooding into the Structures Previous Flooding onto the Property Located in Historic District Historic Property Designation Previous Use of Premises for Manufacture  Previous Glockable Main Drain in Pool/Hot  Previous Flooding Into Property Frevious Use of Premises for Manufacture  Previous Use of Premises for Manufacture  Previous Flooding Into Property Frevious Use of Premises for Manufacture  Previous Glockable Main Drain in Pool/Hot						5			ındatio	n Renaire	+-	_
Diseased Trees: _oak wilt						$\bigcirc$					+	
Endangered Species/Habitat on Property Fault Lines  Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property Located in 100-year Floodplain Located in Floodway Present Flood Ins. Coverage (If yes, attach TAR-1414) Previous Flooding into the Structures Previous Flooding onto the Property Located in Historic District Historic Property Designation Previous Use of Premises for Manufacture  Radon Gas Settling Soil Movement Subsurface Structure or Pits Underground Storage Tanks Unplatted Easements Unrecorded Easements Urea-formaldehyde Insulation Wetlands on Property Wood Rot Active infestation of termites or other wood destroying insects (WDI) Previous treatment for termites or WDI Previous Elonding onto the Property Frevious Use of Premises for Manufacture  Radon Gas Settling Soil Movement Subsurface Structure or Pits Underground Storage Tanks Unplatted Easements Urea-formaldehyde Insulation Wetlands on Property Wood Rot Active infestation of termites or other wood destroying insects (WDI) Previous treatment for termites or WDI Previous termite or WDI damage repaired Previous Fires Termite or WDI damage needing repair Single Blockable Main Drain in Pool/Hot						<b>\(\frac{1}{2}\)</b>					+	
Fault Lines  Hazardous or Toxic Waste  Improper Drainage  Intermittent or Weather Springs  Landfill  Lead-Based Paint or Lead-Based Pt. Hazards  Encroachments onto the Property  Improvements encroaching on others' property  Located in 100-year Floodplain  Located in Floodway  Present Flood Ins. Coverage (If yes, attach TAR-1414)  Previous Flooding into the Structures  Previous Flooding onto the Property  Located in Historic District  Historic Property Designation  Frevious Use of Premises for Manufacture  Settling  Soil Movement  Subsurface Structure or Pits  Underground Storage Tanks  Unplatted Easements  Urea-formaldehyde Insulation  Water Penetration  Wetlands on Property  Wood Rot  Active infestation of termites or other wood destroying insects (WDI)  Previous treatment for termites or WDI  Previous Fires  Termite or WDI damage needing repair  Single Blockable Main Drain in Pool/Hot									ar ar r to	pans	+	
Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property Located in 100-year Floodplain Located in Floodway Present Flood Ins. Coverage (If yes, attach TAR-1414) Previous Flooding into the Structures Previous Flooding onto the Property Located in Historic District Historic Property Designation Previous Use of Premises for Manufacture  Soil Movement Subsurface Structure or Pits Underground Storage Tanks Unplatted Easements Unrecorded Easements Urrea-formaldehyde Insulation Water Penetration Wetlands on Property Wood Rot Active infestation of termites or other wood destroying insects (WDI) Previous treatment for termites or WDI Previous Fires Termite or WDI damage needing repair	Fault Lines					$\hat{\mathbf{v}}$					_	×
Improper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property Located in 100-year Floodplain Located in Floodway Present Flood Ins. Coverage (If yes, attach TAR-1414) Previous Flooding into the Structures Previous Flooding onto the Property Located in Historic District Historic Property Designation Previous Use of Premises for Manufacture  Subsurface Structure or Pits Underground Storage Tanks Unplatted Easements Unrecorded Easements Urrea-formaldehyde Insulation Water Penetration Water Penetration Wetlands on Property Wood Rot Active infestation of termites or other wood destroying insects (WDI) Previous treatment for termites or WDI Previous Fires Termite or WDI damage needing repair Single Blockable Main Drain in Pool/Hot								eme	ent		+	5
Intermittent or Weather Springs  Landfill  Lead-Based Paint or Lead-Based Pt. Hazards  Encroachments onto the Property  Improvements encroaching on others' property  Located in 100-year Floodplain  Located in Floodway  Present Flood Ins. Coverage (If yes, attach TAR-1414)  Previous Flooding into the Structures  Previous Flooding onto the Property  Located in Historic District  Historic Property Designation  Previous Underground Storage Tanks  Unplatted Easements  Unrecorded Easements  Unrecorded Easements  Urea-formaldehyde Insulation  Wetlands on Property  Wood Rot  Active infestation of termites or other wood destroying insects (WDI)  Previous treatment for termites or WDI  Previous termite or WDI damage repaired  Previous Fires  Termite or WDI damage needing repair  Single Blockable Main Drain in Pool/Hot	Improper Drainage					V						1
Lead-Based Paint or Lead-Based Pt. Hazards  Encroachments onto the Property Improvements encroaching on others' property Located in 100-year Floodplain Located in Floodway Present Flood Ins. Coverage (If yes, attach TAR-1414) Previous Flooding into the Structures Previous Flooding onto the Property Located in Historic District Historic Property Designation Previous Unplatted Easements Unrecorded Easements Unrecorded Easements Water Penetration Wetlands on Property Wood Rot Active infestation of termites or other wood destroying insects (WDI) Previous treatment for termites or WDI Previous termite or WDI damage repaired Previous Fires Termite or WDI damage needing repair Single Blockable Main Drain in Pool/Hot		ngs				V					+	
Lead-Based Paint or Lead-Based Pt. Hazards  Encroachments onto the Property Improvements encroaching on others' property Located in 100-year Floodplain Located in Floodway Present Flood Ins. Coverage (If yes, attach TAR-1414) Previous Flooding into the Structures Previous Flooding onto the Property Located in Historic District Historic Property Designation Previous Use of Premises for Manufacture  Unrecorded Easements Urrea-formaldehyde Insulation Water Penetration Wetlands on Property Wood Rot Active infestation of termites or other wood destroying insects (WDI) Previous treatment for termites or WDI Previous termite or WDI damage repaired Previous Fires Termite or WDI damage needing repair Single Blockable Main Drain in Pool/Hot	Landfill					X					T	V
Improvements encroaching on others' property  Located in 100-year Floodplain  Located in Floodway  Present Flood Ins. Coverage (If yes, attach TAR-1414)  Previous Flooding into the Structures  Previous Flooding onto the Property  Located in Historic District  Historic Property Designation  Water Penetration  Wetlands on Property  Wood Rot  Active infestation of termites or other wood destroying insects (WDI)  Previous treatment for termites or WDI  Previous termite or WDI damage repaired  Previous Fires  Termite or WDI damage needing repair  Single Blockable Main Drain in Pool/Hot	Lead-Based Paint or Lead-B	Base	d Pt. F	lazards		V				$\vdash$	x	
Improvements encroaching on others' property  Located in 100-year Floodplain  Located in Floodway  Present Flood Ins. Coverage (If yes, attach TAR-1414)  Previous Flooding into the Structures  Previous Flooding onto the Property  Located in Historic District  Historic Property Designation  Water Penetration  Wetlands on Property  Wood Rot  Active infestation of termites or other wood destroying insects (WDI)  Previous treatment for termites or WDI  Previous termite or WDI damage repaired  Previous Fires  Termite or WDI damage needing repair  Single Blockable Main Drain in Pool/Hot	The state of the s					X					3	
Located in Floodway  Present Flood Ins. Coverage (If yes, attach TAR-1414)  Previous Flooding into the Structures  Previous Flooding onto the Property  Located in Historic District  Historic Property Designation  Previous Use of Premises for Manufacture  Wood Rot  Active infestation of termites or other wood destroying insects (WDI)  Previous treatment for termites or WDI Previous termite or WDI damage repaired Previous Fires  Termite or WDI damage needing repair Single Blockable Main Drain in Pool/Hot						V					()	
Located in Floodway  Present Flood Ins. Coverage (If yes, attach TAR-1414)  Previous Flooding into the Structures  Previous Flooding onto the Property  Located in Historic District  Historic Property Designation  Previous Use of Premises for Manufacture  Wood Rot  Active infestation of termites or other wood destroying insects (WDI)  Previous treatment for termites or WDI  Previous termite or WDI damage repaired  Previous Fires  Termite or WDI damage needing repair  Single Blockable Main Drain in Pool/Hot	Located in 100-year Floodplain					X	A CANADA AND THE ARCHITECTURE SHOPE IN THE STATE OF THE S			T	7	
Present Flood Ins. Coverage (If yes, attach TAR-1414)  Previous Flooding into the Structures  Previous Flooding onto the Property  Located in Historic District  Historic Property Designation  Previous Use of Premises for Manufacture  Active infestation of termites or other wood destroying insects (WDI)  Previous treatment for termites or WDI  Previous termite or WDI damage repaired  Previous Fires  Termite or WDI damage needing repair  Single Blockable Main Drain in Pool/Hot	Located in Floodway											
(If yes, attach TAR-1414)        destroying insects (WDI)         Previous Flooding into the Structures        Previous treatment for termites or WDI         Previous Flooding onto the Property        Previous termite or WDI damage repaired         Located in Historic District        Previous Fires         Historic Property Designation        Termite or WDI damage needing repair         Previous Use of Premises for Manufacture        Single Blockable Main Drain in Pool/Hot	Present Flood Ins. Coverage						Active inf	festa	ation o	f termites or other wood		
Previous Flooding onto the Property  Located in Historic District  Historic Property Designation  Previous Use of Premises for Manufacture  Previous termite or WDI damage repaired  Previous Fires  Termite or WDI damage needing repair  Single Blockable Main Drain in Pool/Hot	(If yes, attach TAR-1414)					X						X
Located in Historic District  Historic Property Designation  Previous Use of Premises for Manufacture  Previous Use of Premises for Manufacture  Previous Fires  Termite or WDI damage needing repair  Single Blockable Main Drain in Pool/Hot	Previous Flooding into the Structures					X					V	
Historic Property Designation  Termite or WDI damage needing repair  Single Blockable Main Drain in Pool/Hot	Previous Flooding onto the Property					X	Previous					X
Previous Use of Premises for Manufacture  Single Blockable Main Drain in Pool/Hot	Located in Historic District					X						X
V   English En	Historic Property Designation					X					X	
						X			able M	ain Drain in Pool/Hot		X

(TAR-1406) 01-01-16

Page 2 of 5

Initialed by: Buyer: \_\_\_\_\_, \_\_\_\_ and Seller: \_\_\_\_, \_\_\_\_\_, \_\_\_\_\_\_\_\_, Produced with zipForm® by zipLogix 18070 Fifteen Mile Road, Fraser, Michigan 48026 www.zipLogix.com

2732 Goehmann

# 2732 Goehmann Lane Fredericksburg, TX 78624

Concerning	the Property	at		Fredericksburg,	TX 78624	
If the answ	er to any of th	e items in Section 3	is yes, explain	(attach additional s	heets if necessa	ry):
which has	Are you (Se not been pr	eviously disclose	item, equipmen d in this notice	nt, or system in or e?yes <u>X</u> no	on the Property If yes, explain (	that is in need of repair, attach additional sheets if
Section 5.				2000		e. Mark No (N) if you are
not aware.  Y N  X	) Room addition		fications, or othe	er alterations or rep		ut necessary permits or not
_ 🗡	Name of Manager Fees or Any unpoint If the Pro	s' associations or ma association: 's name: assessments are: \$ aid fees or assessment operty is in more that formation to this not	ent for the Prop	per perty? yes (\$	Phone:	me following: mandatory voluntary no ther associations below or
_ X	with others.	f yes, complete the	following:			wned in undivided interest
_ 🗶	Any notices Property.	of violations of deed	d restrictions or	governmental ordin	nances affecting	the condition or use of the
_ X	Any lawsuits to: divorce, for	or other legal proce preclosure, heirship	eedings directly , bankruptcy, an	or indirectly affectind taxes.)	ng the Property.	(Includes, but is not limited
_*	Any death or to the conditi	n the Property exce on of the Property.	pt for those dea	aths caused by: na	tural causes, sui	cide, or accident unrelated
_ *	Any condition	on the Property wi	hich materially a	affects the health or	safety of an indi	vidual.
_ <b>Y</b>	hazards such If yes, at	n as asbestos, rador	n, lead-based pa or other docum	aint, urea-formaldel nentation identifying	hyde, or mold.	o remediate environmental e remediation (for example,
_ 🛪	Any rainwate water supply	r harvesting system as an auxiliary wate	n located on the er source.	Property that is lar	ger than 500 gall	ons and that uses a public
_×	The Property	is located in a propa	ane gas system	service area owned	by a propane di	stribution system retailer.
_ 🗴	Any portion of	of the Property that i	s located in a g	roundwater conser	vation district or a	a subsidence district.
(TAR-1406)	01-01-16 F	Initialed by: B roduced with zipForm® by zipLo	Suyer:, _ gix 18070 Fifteen Mile Ro	and Seller:	Mw.zipLogix.com	Page 3 of 5

Concerning the Prope	erty at	Fredericksburg, TX 78624							
f the answer to any of the items in Section 5 is yes, explain (attach additional sheets if necessary):									
Section 7. Within the regularly provide in:	ne last 4 years, I spections and w	no are either license	ceived any writt	en inspection reports or otherwise permitte	s from persons who ed by law to perform				
	<u></u>	ch copies and complet							
Inspection Date	Туре	Name of Inspec			No. of Pages				
Feb 4, 2017	HomL	DEBIN	SPECTION	5	160				
		,							
Section 8. Check an  Homestead Wildlife Manag Other: Section 9. Have yo provider? yes X  Section 10. Have yo insurance claim or a	gement  ou (Seller) even  ou (Seller) even  ou (Seller) ever re	(s) which you (Seller Senior Citizen Agricultural er filed a claim	for damage to a claim for deding) and not u	n for the Property:  Disabled Disabled Vetera Unknown  to the Property will  amage to the Property  used the proceeds to	n ith any insurance ty (for example, an				
Section 11.Does the requirements of Cha (Attach additional she	apter 766 of the I	Health and Safety Co	ode?* 🗶 unknov	in accordance with wn no yes. If no	the smoke detector or unknown, explain.				
smoke detecto which the dwel know the build	rs installed in acc lling is located, inc	cordance with the requirely cluding performance, linents in effect in your	uirements of the ocation, and pow	two-family dwellings to building code in effect ver source requirement check unknown above t	t in the area in s. If you do not				
of the buyer's in evidence of the the buyer mak specifies the lo	family who will res thearing impairm tes a written requ ocations for install	ide in the dwelling is a ent from a licensed ph uest for the seller to	hearing-impaired lysician; and (3) v install smoke de y agree who will	impaired if: (1) the buye ; (2) the buyer gives th within 10 days after the tectors for the hearing bear the cost of instal	ne seller written neffective date, g-impaired and				

(TAR-1406) 01-01-16

	2732 Goehmann Lane
Concerning the Property at	Fredericksburg, TX 78624
the broker(s), has instructed or influenced Seller to provide i	strue to the best of Seller's belief and that no person, including naccurate information or to omit any material information.  Signature of Seller  Printed Name:
ADDITIONAL NOTICES TO BUYER:	
registered sex offenders are located in certain zip code	tabase that the public may search, at no cost, to determine if areas. To search the database, visit <a href="www.txdps.state.tx.us">www.txdps.state.tx.us</a> . certain areas or neighborhoods, contact the local police
mean high tide bordering the Gulf of Mexico, the prop Protection Act (Chapter 61 or 63, Natural Resources C	ord of the Gulf Intracoastal Waterway or within 1,000 feet of the perty may be subject to the Open Beaches Act or the Dune ode, respectively) and a beachfront construction certificate or improvements. Contact the local government with ordinance or more information.
(3) If you are basing your offers on square footage, moindependently measured to verify any reported information	easurements, or boundaries, you should have those items on.
(4) The following providers currently provide service to the p	property:
Electric: Sewer: Water: Cable: Trash: Natural Gas: Phone Company: Propane:	phone #:
(5) This Seller's Disclosure Notice was completed by Seller as true and correct and have no reason to believe it to AN INSPECTOR OF YOUR CHOICE INSPECT THE PR	as of the date signed. The brokers have relied on this notice be false or inaccurate. YOU ARE ENCOURAGED TO HAVE ROPERTY.
The undersigned Buyer acknowledges receipt of the foregoing	ng notice.
Signature of Buyer Date	Signature of Buyer Date
Printed Name:	Printed Name:

(TAR-1406) 01-01-16