

REPORT SHEET FOR PERCOLATION AND SIX FOOT HOLE TESTING

Subdivision Name Bluffs on the Potomac County Hampshire

Total Number of Lots _____ Name of Applicant WV Hunter, LLC

Name of Certified Installer Responsible for Testing Justin Tame, Exc.

Installer Certification No. 54-00-A-0207 Installer Signature Jay Mullins

Address HC 64 Box 1034 Romney, W.V. 26757

Type System	Lot Number	Percolation Test Results (Minutes per Inch of Fall)					Six Foot Hole Results		Date Conducted
							Depth to Water	Depth to Rock	
II	85	63	72	68	55	10.7	N/A	N/A	
II	86	98	90	100	85	15.5	N/A	N/A	
II	87	65	78	68	54	11.0	N/A	N/A	
II	88	118	100	105	95	17.4	N/A	N/A	
II	89	100	80	95	90	15.2	N/A	N/A	
I	90	120	110	112	130	19.6	N/A	N/A	
II	91	80	100	45	60	11.8	N/A	N/A	
II	92	15	100	85	45	12.1	N/A	N/A	
I	93	90	90	45	100	13.5	N/A	N/A	
I	94	40	85	80	90	12.2	N/A	N/A	
I	95	95	80	85	90	14.5	N/A	N/A	
I	96	80	80	90	70	13.3	N/A	N/A	
II	97	95	70	100	85	19.5	N/A	N/A	
I	98	120	90	118	100	17.8	N/A	N/A	
II	60	98	90	70	68	13.5	N/A	N/A	
II	61	85	65	90	72	13	N/A	N/A	
II	62	70	70	75	70	11.8	N/A	N/A	
I	63	120	112	90	95	17.3	N/A	N/A	
II	64	55	50	100	85	12.0	N/A	N/A	
I	65	140	135	145	120	22.5	N/A	N/A	

(Attach additional pages if needed)