



NORTH

455.92'

213.70'


Good





Concrete Drive

166.45'

Pump & Filter System



2.0' Planters



0.8' Brick Wall 4' High

Survey

Survey

IMPROVEMENTS

3.1495

AC.