

Kathy Beckham

From: "Virdell Drilling" <virdelldrilling@verizon.net>
To: "Kathy Beckham" <kbeckham@remax-llano-tx.com>
Sent: Friday, June 21, 2013 3:05 PM
Subject: Emailing: Well Report Tracking #107194.htm

Tract F (85ac)

When we drilled we actually had as Lot L and then was changed to M and now maybe F? But it is 18 GPM. Have a great weekend.

STATE OF TEXAS WELL REPORT for Tracking #107194

Owner:	Vista Encantata	Owner Well #:	No Data
Address:	5925 Forest Lane, Ste. 505 Dallas , TX 75230	Grid #:	57-27-1
Well Location:	Vista Encantata, Lot #L; .6 mi. W of entrance on CR 113; 50' S on lot TX	Latitude:	30° 35' 23" N
Well County:	Llano	Longitude:	098° 44' 21" W
Elevation:	No Data	GPS Brand Used:	Garmin III
Type of Work:	New Well	Proposed Use:	Domestic

Drilling Date: Started: **3/21/2007**
 Completed: **3/21/2007**

Diameter of Hole: Diameter: **9 in From Surface To 21 ft**
 Diameter: **6.75 in From 21 ft To 22 ft**
 Diameter: **6 in From 22 ft To 120 ft**

Drilling Method: **Air Hammer**

Borehole Completion: **Straight Wall**

Annular Seal Data: 1st Interval: **From 0 ft to 3 ft with 1 Cement (#sacks and material)**
 2nd Interval: **From 3 ft to 17 ft with 4 Bentonite (#sacks and material)**
 3rd Interval: **No Data**
 Method Used: **Grout**
 Cemented By: **Taylor Virdell Jr.**

6/21/2013

Distance to Septic Field or other Concentrated Contamination: **No Data**
Distance to Property Line: **No Data**
Method of Verification: **No Data**
Approved by Variance: **No Data**

Surface
Completion: **Surface Sleeve Installed**

Water Level: Static level: **19 ft. below land surface on 3/21/2007**
Artesian flow: **No Data**

Packers: **Rubber 17'**

Plugging Info: Casing or Cement/Bentonite left in well: **No Data**

Type Of Pump: **Submersible**
Depth to pump bowl: **100 ft**

Well Tests: **Jetted**
Yield: **18 GPM with (No Data) ft drawdown after (No Data) hours**

Water Quality: Type of Water: **good (320 ppmTDS)**
Depth of Strata: **17-21, 76 ft.**
Chemical Analysis Made: **No**
Did the driller knowingly penetrate any strata which contained undesirable constituents: **No**

Certification Data: The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the log(s) being returned for completion and resubmittal.

Company Information: **Virdell Drilling Inc.**
111 E. Grayson St.
Llano , TX 78643

Driller License Number: **1900**

Licensed Well Driller Signature: **Taylor Virdell Jr.**

Registered Driller Apprentice: **James Caleb Virdell**

Signature:

Apprentice 3254

Registration

Number:

Comments: No Data

IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED

CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking number (Tracking #107194) on your written request.

Texas Department of Licensing & Regulation

P.O. Box 12157

Austin, TX 78711

(512) 463-7880

DESC. & COLOR OF FORMATION MATERIAL		CASING, BLANK PIPE & WELL SCREEN DATA		
From (ft)	To (ft) Description	Dia.	New/Used	Type Setting
0 - 2	Topsoil			
2 - 10	Brown Clay & Gravel	6"	N PVC	+5 - 17 sch 40
10 - 21	Broken Metamorphic	6"	N PVC,	Custom Slott 17 - 22 sch 40
21 - 120	Black & White Metamorphic w/Red Streaks			