Tom Shaw

From:

"Virdell Drilling Inc." <virdelldrilling@verizon.net>

Date:

Wednesday, April 27, 2011 1:33 PM <tshaw@virdellrealestate.com>

To: Subject:

Tract #T

STATE OF TEXAS WELL REPORT for Tracking #190448

Owner:

Oxford Ranch

Owner Well #:

No Data

Address:

5925 Forest Ln., Ste. 505

Grid #:

57-27-4

Dallas, TX 75230

Well

Far Southwest end of Sub.

Latitude:

30° 34' 27" N

Location: TX

Well Llano Longitude:

098° 43' 23" W

County:

Elevation: No Data

GPS Brand

Garmin III

Used:

Type of Work:

New Well

Proposed Use:

Domestic

Drilling Date:

Started: 8/19/2009

Completed: 8/19/2009

Diameter of

Diameter: 9 in From Surface To 31 ft

Hole:

Diameter: 6.75 in From 31 ft To 32 ft

Diameter: 6 in From 32 ft To 200 ft

Drilling Method: Air Hammer

Borehole

Open Hole

Completion:

Annular Seal

Data:

1st Interval: From 0 ft to 3 ft with 1 Cement (#sacks and material)

2nd Interval: From 3 ft to 31 ft with 5 Bentonite (#sacks and

material)

3rd Interval: No Data Method Used: Grout Cemented By: Lynn Hoy

Distance to Septic Field or other Concentrated Contamination: No D

Distance to Property Line: No Data Method of Verification: No Data

Approved by Variance: No Data

Surface

Surface Sleeve Installed

Completion:

Water Level: Static level: 55 ft. below land surface on 8/19/2009

Artesian flow: No Data

Packers:

No Data

Plugging Info:

Casing or Cement/Bentonite left in well: No Data

Type Of Pump:

Submersible

Depth to pump bowl: 180 ft

Well Tests:

Jetted

Yield: 25 GPM with (No Data) ft drawdown after (No Data) hours

Water Quality:

Type of Water: good (370 ppmTDS)

Depth of Strata: 191 ft. Chemical Analysis Made: No

Did the driller knowingly penetrate any strata which contained

undesirable constituents: No

Certification

Data:

The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that

failure to complete the required items will result in the log(s) being

returned for completion and resubmittal.

Company

Information:

Virdell Drilling Inc.

111 E. Grayson St.

Llano, TX 78643

Driller License

Number:

1900

Licensed Well

Taylor Virdell Jr.

Driller Signature:

Registered

James Caleb Virdell

Driller

Apprentice Signature:

57668

Apprentice Registration

Number:

Comments:

No Data

IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking number (Tracking #190448) on your written request.

Texas Department of Licensing & Regulation P.O. Box 12157
Austin, TX 78711
(512) 463-7880

DESC. & COLOR OF FORMATION MATERIAL	CASING, BLANK PIPE & WELL SCREEN DATA

From (ft) To (ft) Description

0 - 2 Topsoil

2 - 10 Metamorphic Gravel & Clay

10 - 18 Weathered Metamorphic

18 - 35 Red & Black Metamorphic

35 - 80 Gray & Black Metamorphic

80 - 180 White & Black Metamorphic

180 - 200 Red Metamorphic

From/To

Dia. New/Used

6" N PVC +3 - 32 sch 40

Type

Setting