

Tom Shaw

VE LOT S

From: "Virdell Drilling Inc." <virdelldrilling@verizon.net>
Date: Wednesday, April 27, 2011 1:31 PM
To: <tshaw@virdellrealestate.com>
Subject: Tract #S

STATE OF TEXAS WELL REPORT for Tracking #178653

Owner:	Vista Encantata	Owner Well #:	No Data
Address:	5925 Forest Lane, Ste. 505 Dallas , TX 75230	Grid #:	57-27-4
Well Location:	Vista Encantata, Lot #E-2 TX	Latitude:	30° 34' 28" N
Well County:	Llano	Longitude:	098° 43' 41" W
Elevation:	No Data	GPS Brand Used:	Garmin III
Type of Work:	New Well	Proposed Use:	Domestic

Drilling Date: Started: **5/14/2009**
 Completed: **5/14/2009**

Diameter of Hole: Diameter: **9 in From Surface To 22 ft**
 Diameter: **6.75 in From 22 ft To 23 ft**
 Diameter: **6 in From 23 ft To 220 ft**

Drilling Method: **Air Hammer**

Borehole Completion: **Open Hole**

Annular Seal Data: 1st Interval: **From 0 ft to 4 ft with 1 Cement (#sacks and material)**
 2nd Interval: **From 4 ft to 22 ft with 4 Bentonite (#sacks and material)**
 3rd Interval: **No Data**
 Method Used: **Grout**
 Cemented By: **Lynn Hoy**
 Distance to Septic Field or other Concentrated Contamination: **No D**

Distance to Property Line: **No Data**
 Method of Verification: **No Data**

Approved by Variance: **No Data**Surface
Completion: **Surface Sleeve Installed**

Water Level: Static level: **30 ft. below land surface on 5/14/2009**
Artesian flow: **No Data**Packers: **No Data**Plugging Info: Casing or Cement/Bentonite left in well: **No Data**Type Of Pump: **Submersible**
Depth to pump bowl: **200 ft**Well Tests: **Jetted**
Yield: **7 GPM with (No Data) ft drawdown after (No Data) hours**

Water Quality: Type of Water: **good (270 ppmTDS)**
Depth of Strata: **30-35, 55 ft.**
Chemical Analysis Made: **No**
Did the driller knowingly penetrate any strata which contained
undesirable constituents: **No**Certification
Data: The driller certified that the driller drilled this well (or the well was
drilled under the driller's direct supervision) and that each and all of the
statements herein are true and correct. The driller understood that
failure to complete the required items will result in the log(s) being
returned for completion and resubmittal.Company
Information: **Virdell Drilling Inc.**
111 E. Grayson St.
Llano , TX 78643Driller License
Number: **1900**Licensed Well
Driller Signature: **Taylor Virdell Jr.**Registered
Driller
Apprentice
Signature: **James Caleb Virdell**Apprentice
Registration
Number: **57668**

Comments: No Data

IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking number (Tracking #178653) on your written request.

Texas Department of Licensing & Regulation
P.O. Box 12157
Austin, TX 78711
(512) 463-7880

DESC. & COLOR OF FORMATION MATERIAL			CASING, BLANK PIPE & WELL SCREEN DATA			
From (ft)	To (ft)	Description	Dia.	New/Used	Type	Setting
0	2	Topsoil				
2	4	Boulder				
4	21	Metamorphic Gravel & Clay				
21	50	Red Metamorphic				
50	220	Red & Black Metamorphic				