

STATE OF TEXAS WELL REPORT for Tracking #74198

Owner:	Peter Malin Six Peaks LLC	Owner Well #:	No Data
Address:	5925 Forest Lane, Ste. 505 Dallas , TX 75230	Grid #:	57-26-2
Well Location:	.9 mi. W from CR 113 on CR 112; .2 mi. N on tract; (East Tract Well) TX	Latitude:	30° 36' 30" N
Well County:	Llano	Longitude:	098° 48' 31" W
Elevation:	No Data	GPS Brand Used:	Garmin III
Type of Work:	New Well	Proposed Use:	Domestic

Drilling Date: Started: **1/13/2006**
Completed: **1/13/2006**

Diameter of Hole: Diameter: **9 in From Surface To 26 ft**
Diameter: **6.75 in From 26 ft To 27 ft**
Diameter: **6 in From 27 ft To 120 ft**

Drilling Method: **Air Hammer**

Borehole Completion: Gravel Packed From: **15 ft to 27 ft**
Gravel Pack Size: **4A**

Annular Seal Data: 1st Interval: **From 0 ft to 8 ft with 1 Cement (#sacks and material)**
2nd Interval: **From 8 ft to 15 ft with 3 Bentonite (#sacks and material)**
3rd Interval: **No Data**
Method Used: **Grout**
Cemented By: **Lynn Hoy**
Distance to Septic Field or other Concentrated Contamination: **No Data**
Distance to Property Line: **100+ ft**
Method of Verification: **estimated**
Approved by Variance: **No Data**

Surface Completion: **Surface Sleeve Installed**

Water Level: Static level: **20 ft. below land surface on 1/13/2006**
Artesian flow: **No Data**

Packers: **No Data**

Plugging Info: Casing or Cement/Bentonite left in well: **No Data**

Type Of Pump: **Submersible**
Depth to pump bowl: **110 ft**

Well Tests: **Jetted**
Yield: **2 GPM with (No Data) ft drawdown after (No Data) hours**

Water Quality: Type of Water: **good (360 ppmTDS)**
Depth of Strata: **25 - 26 ft.**
Chemical Analysis Made: **No**
Did the driller knowingly penetrate any strata which contained undesirable constituents: **No**

Certification Data: The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete

the required items will result in the log(s) being returned for completion and resubmittal.

Company Information: **Virdell Drilling Inc.**
111 E. Grayson St.
Llano, TX 78643

Driller License Number: **4071**

Licensed Well Driller Signature: **Lynn Hoy**

Registered Driller Apprentice Signature: **No Data**

Apprentice Registration Number: **No Data**

Comments: **No Data**

IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking number (Tracking #74198) on your written request.

Texas Department of Licensing & Regulation
P.O. Box 12157
Austin, TX 78711
(512) 463-7880

DESC. & COLOR OF FORMATION MATERIAL

From (ft) To (ft) Description
0 - 1 Topsoil
1 - 20 Granite Gravel & Clay
20 - 120 Red Granite

CASING, BLANK PIPE & WELL SCREEN DATA

Dia.	New/Used	Type	Setting From/To
6"	N	PVC	+2 - 22 sch 40
6"	N	PVC, Custom Slott	22 - 27 sch 40