FIELD INSPECTION
REPORT FOR
ON-SITE SEWERAGE
FACILITY

PERMIT NO. [illegible]

INSPECTION:
DATE [illegible]
TIME [illegible]
BY [illegible]

Mike [illegible]

SITE ADDRESS Lot # 22 Ridgeview
PROPERTY ADDRESS
INSTALLER/NAME & NUMBER

SYSTEM CONSIST OF:
SEPTIC TANKS-

1500 GALLONS MANUFACTURER CAPACITY 1500

ABSORPTION FIELD-

BED ✓ TRENCH 750 SQUARE FEET

OTHER

DISTANCE TO: WELL 200' FT STRUCTURE 90' FT
SEPTIC TANKS 70' FT PROPERTY LINES: FRONT - REAR NA FT
SIDE FT SIDE FT TRENCH WIDTH 36 INCHES
DEPTH OF GRAVEL UNDER PIPE 8-10" INCHES
TOTAL DEPTH OF GRAVEL 14" INCHES DEPTH: TOP OF PIPE TO
FINISHED GRADE 12" INCHES CLEAN-CUTS WITHIN 3 FT OF
STRUCTURE ✓ AT 90% AT 50 FOOT INTERVALS
REMARKS:

DIAGRAM:



250 LF X 3 = 750 SF
OK