OPY

## JERRY BROWN 1503 W 13<sup>TH</sup> AVE CORSICANA TEXAS 75110 903-874-52425

Owner: Paul Williams and Becky Brown

Ref: Inspection of Onsite Sewerage Facilities

Date: July 7, 2011

Location: 9020 Blue Diamond

Type of System: Low Pressure Dosage System

Water Supply: Public Water Supply

Tank Size:

Length of Field:

I, Jerry Brown, 2477 at the time of my inspection find the system to be in working order. With proper maintenance the system should function satisfactorily and is unlikely to create an unsanitary condition. This does not assure the owner that it will continue to perform satisfactorily. The system can be expected to be adequate based on the knowledge of the present site condition.

Comments: No surface water was found at time of inspection

Jerry Brown OSSF #2477