

LINE	BEARING	DISTANCE
[illegible]	N 00° 51' 15" E	107 23
[illegible]	N 89° 18' 58" W	11 94
[illegible]	S 27° 15' 30" W	60 58
[illegible]	S 18° 52' 06" W	[illegible]
[illegible]	N 15° 37' 30" E	126 46
[illegible]	N 44° 48' 01" W	35 35
[illegible]	N 89° 49' 53" W	[illegible]
8	S 81° [illegible] 47" W	150 [illegible]
[illegible]	N 85° 39' 50" W	[illegible] 55
10	S 49° 24' 46" W	35 39
[illegible]	S 04° 28' 19" W	125 02
[illegible]	S 08° 14' 40" W	150 32
[illegible]	S 85° 38' 49" E	[illegible]
[illegible]	S 00° 21' 52" E	32 39



Location Map

CURVE	DELTA ANGLE	RADIUS	ARC	TANGENT	CHORD	CHORD BEAR
C 1	03° 38' 46"	1135 92'	72 29	36 15	72 27	N 02° 40' [illegible]
C 2	07° 41' 01"	2874 79	385 52'	193 05	385 23	N 00° 39' [illegible]
C 3	03° 34' 57"	700 00	43 77	21 89	43 76	S 01° 59' [illegible]
C 4	14° 45' 24"	674 00	173 59	87 28	173 [illegible]	S 14° 52' [illegible]
C 5	03° 23' 24"	726 00	42 96	21 48	42 95	S 20° 33' [illegible]
C 6	10° 13' 43"	742 50'	132 55	66 45	132 38	N 10° 27' [illegible]
C 7	15° 21' 21"	657 50	176 22'	88 64	175 69	N 07° 53' [illegible]
C 8	11° 35' 18"	597 50	120 85	60 63	120 64'	S 84° 23' [illegible]
C 9	12° 11' 25"	692 50	147 34	73 95	147 06	S 88° 15' [illegible]
C 10	[illegible]	527 50'	[illegible]	[illegible]	[illegible]	[illegible]
[illegible]	[illegible]	[illegible]	[illegible]	[illegible]	[illegible]	[illegible]
[illegible]	[illegible]	[illegible]	[illegible]	[illegible]	[illegible]	[illegible]
[illegible]	[illegible]	754 [illegible]	[illegible]	[illegible]	[illegible]	[illegible]

PROPERTY DESCRIPTION

[illegible]

** Basis of Bearings **

[illegible]

Brennan Land Surveying

[illegible]