ES-76
Page 2

REPORT SHEET

FOR

PERCOLATION AND SIX FOOT HOLE TESTING

Subdivision Name Crooked Creek Section 2 County Hampshire

Total Number of Lots 5 Name of Applicant Black Diamond Experience

Name of Certified Installer Responsible for Testing Davis Excavating, Ralph Davis

Installer Certification No. 54-83-123 Installer Signature Ralph Davis

	Lot No.	Percolation Test Results (Minutes Per Inch of Fall)				Average Result	Six Foot Hole Results		Date Conducted
							Depth to Water	Depth to Rock	
STD	2-A	182	189	194	199	31.8	6'	6'	
STD	2-B	235	240	243	250	40.3	6'	6'	
STD	2-C	210	213	219	222	32	6'	6'	
STD	2-D	186	192	196	200	32.2	6'	6'	
STD	2-E	166	171	174	183	28.9	6'	6'	
		ALL STANDARD Systems							

(Attach additional pages if needed)