

ES-76
Page 2

REPORT SHEET

FOR

PERCOLATION AND SIX FOOT HOLE TESTING

Subdivision Name Ranch View Estates County Hampshire
 Total Number of Lots 24 Name of Applicant M. Puno
 Name of Certified Installer Responsible for Testing Bob Lummus
 Installer Certification No. 34-00-0204 Installer Signature [Signature]

Lot No.	Percolation Test Results (Minutes Per Inch of Fall)					Average Result	Six Foot Hole Results		Date Conducted
							Depth to Water	Depth to Rock	
24"	1	80	45	59	30	53.5	6ft	6ft	10/25/0
18"	2	55	70	73	68	54			
18"	3	81	46	60	61	62			
II	4	23	30	27	32	28.5			
II	5	50	55	50	60	54			
II	6	40	35	51	43	42			
II	7	57	52	58	40	52			
24"	8	31	37	29	28	31			
24"	9	41	46	32	51	41			
24"	10	23	37	30	33	31			
18"	11	18	16	21	27	19			
24"	12	39	41	48	35	41			
24"	13	48	36	47	38	42			
18"	14	22	28	27	31	27			
II	15	70	82	81	55	72			
II	16	62	72	46	49	57			
C.D. 18"	17	40	32	27	30	32			
C.D. 48"	18	33	27	31	40	32			
C.D. II	19	17	21	21	25	21			
C.D. 18"	20	20	21	30	17	22			
24"	21	41	38	31	35	36			
24"	22	31	37	28	42	35			
24"	23	25	31	20	18	24			
24"	24	19	23	18	26	21			

(Attach additional pages if needed)

C.D. = Cutoff in Drain II is CLASS II system