STATE OF TEXAS WELL REPORT for Tracking #238007					
Owner:	David Stanley	Owner Well #:	No Data		
Address:	956 CR 286 Edna, TX 77957	Grid #:	66-50-9		
Well Location:		Latitude:	29°09'25"N		
	Edna, TX 77957	Longitude:	096° 46' 39" W		
Well County:	Jackson	Elevation:	113 ft. above sea level		
Type of Work:	New Well	Proposed Use:	Domestic		

Drilling Start Date: 3/29/2010 Drilling End

Drilling End Date: 3/29/2010

	Diameter (in.) Top D	epth (ft.)	Bottom Depth (ft.)		
Borehole:	7.875		0	255		
Drilling Method:	Mud (Hydraulic) Rotary					
Borehole Completion:	Straight Wall					
	Top Depth (ft.)	Bottom Depth (ft.)	De	scription (number of sacks & material)		
Annular Seal Data:	0	15		6 bags Cement		
Seal Method: Po	operty Line (ft.): No Data					
Sealed By: Steven Berry Distance to Septic Field or other concentrated contamination (ft.): No Data Distance to Septic Tank (ft.): No Data						
				d of Verification: No Data		
Surface Completion:	Surface Sleeve In	nstalled	Wetho			
Water Level:	68 ft. below land surface, and 75 GPM Measurement Method: Unknown artesian flow on 2010-03-29					
Packers:	1st rubber packer at 15 ft 2 nd rubber packer at 235 ft					
Type of Pump:	Jet					
Well Tests:	Jetted	Yield: 15 GPM	with 2 ft. dra	awdown after unspecified hours	S	

Water Quality:	No Data	No Data		
		No Dala		
		Chemical Analysis Made:	No	
	Did the driller kno	wingly penetrate any strata which		
		contained injurious constituents?:	No	
Certification Data:	driller's direct supervision	he driller drilled this well (or the we n) and that each and all of the state rstood that failure to complete the r	ements he	rein are true and
Certification Data:	driller's direct supervision correct. The driller under	n) and that each and all of the state	ements he required it	rein are true and
	driller's direct supervision correct. The driller unde the report(s) being return	n) and that each and all of the state rstood that failure to complete the r ned for completion and resubmittal.	ements he required it	rein are true and
	driller's direct supervision correct. The driller unde the report(s) being return	n) and that each and all of the state rstood that failure to complete the r ned for completion and resubmittal.	ements he required it	rein are true and
	driller's direct supervision correct. The driller unde the report(s) being return Berry Water Well Serv PO Box 935	n) and that each and all of the state rstood that failure to complete the r ned for completion and resubmittal.	ements he required it	rein are true and
Company Information:	driller's direct supervision correct. The driller unde the report(s) being return Berry Water Well Serv PO Box 935 Edna, TX 77957	n) and that each and all of the state rstood that failure to complete the r ned for completion and resubmittal. vice	ements he required it	rein are true and ems will result in

Lithology: DESCRIPTION & COLOR OF FORMATION MATERIAL

Top (ft.)	Bottom (ft.)	Description
0	3	surface
3	18	clay
18	25	sand
25	45	clay
45	50	sand
50	90	clay
90	95	sand
95	125	clay
125	135	sand
135	155	clay
155	170	sand
170	172	Mud
172	182	sand
182	235	clay
235	255	sand

Casing: BLANK PIPE & WELL SCREEN DATA

Dia. (in.)	New/Used	Туре	Setting From/To (ft.)			
4" new casing mfg plastic from 0-255 ft						
14 gau	ge screen	235-25	5 ft			

IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

Texas Department of Licensing and Regulation P.O. Box 12157 Austin, TX 78711 (512) 334-5540