



VIRDELL DRILLING INC.

111 E. GRAYSON ST.
LLANO, TEXAS 78643
(325) 247-4249
www.virdelldrilling.com
virdelldrilling@verizon.net

Invoice Date: Apr 27, 2016

Invoice Number: 40199

Account Number: 08250

Bill To:

GILBERT COBIAN
C/O KERR LAND CO.
P O BOX 294597
KERRVILLE, TX 78028

INVOICE

Payment Terms

Net Due Upon Receipt

Quantity	Description	Unit Price	Amount
	GILLESPIE CO.; LOT 28, LONGHORN RANCH SUBDIVISION TRACKING #421184, N301935, W991344 =====		
240	FT. DRILLING	14.00	3,360.00
20	FT. DRILLING (NO CHARGE)		
78	FT. PVC CASING 6" SCH 40	10.50	819.00
1	CEMENT & BENTONITE	100.00	100.00
1	REGISTRATION	120.00	120.00
	DATE DRILLED: 4/25/16		
THANK YOU FOR YOUR BUSINESS!		Subtotal	4,399.00
		Sales Tax	62.03
		TOTAL	4,461.03

ALL ACCOUNTS ARE CONSIDERED
PAST DUE 15 DAYS AFTER
INVOICE DATE. A FINANCE
CHARGE OF 1-1/2% PER MONTH
(18% ANNUAL) WILL BE ADDED TO
ALL PAST DUE ACCOUNTS.

STATE OF TEXAS WELL REPORT for Tracking #421184

Owner:	Gilbert Cobian	Owner Well #:	No Data
Address:	156 Old Pasture Rd Kerrville, TX 78028	Grid #:	56-47-4
Well Location:	Lot 28, Longhorn Ranch Subdivision Harper, TX	Latitude:	30° 19' 35" N
		Longitude:	099° 13' 44" W
Well County:	Gillespie	Elevation:	No Data
Type of Work:	New Well	Proposed Use:	Domestic

Drilling Start Date: 4/25/2016 Drilling End Date: 4/25/2016

Borehole:	Diameter (in.)	Top Depth (ft.)	Bottom Depth (ft.)
	9.5	0	75
	6.75	75	76
	6	76	260

Drilling Method: Air Hammer

Borehole Completion: Open Hole

Annular Seal Data:	Top Depth (ft.)	Bottom Depth (ft.)	Description (number of sacks & material)
	1	3	Cement 1 Bags/Sacks
	3	50	Bentonite 11 Bags/Sacks

Seal Method: Poured

Sealed By: Driller

Distance to Property Line (ft.): No Data

Distance to Septic Field or other
concentrated contamination (ft.): No Data

Distance to Septic Tank (ft.): No Data

Method of Verification: No Data

Surface Completion: Pitless Adapter Used

Water Level: 155 ft. below land surface on 2016-04-25

Packers: Rubber at 50 ft.

Type of Pump: Submersible

Pump Depth (ft.): 240

Well Tests: Jetted Yield: 12 GPM

Water Quality:

Strata Depth (ft.)	Water Type
155	Good (360 ppmTDS)
240	Good (360 ppmTDS)

Chemical Analysis Made: No

Did the driller knowingly penetrate any strata which
contained injurious constituents?: No

Certification Data: The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the report(s) being returned for completion and resubmittal.

Company Information: Virdell Drilling Inc.

111 E. Grayson St.
Llano, TX 78643

Driller Name: James Taylor Virdell Jr.

License Number: 1900

Comments: No Data

Lithology:
DESCRIPTION & COLOR OF FORMATION MATERIAL

Top (ft.)	Bottom (ft.)	Description
0	1	Topsoil
1	7	Caliche
7	260	White, Brown & Gray Limestone

Casing:
BLANK PIPE & WELL SCREEN DATA

Dia (in.)	Type	Material	Sch./Gage	Top (ft.)	Bottom (ft.)
6	Blank	New Plastic (PVC)	Sch40	-2	76

IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

Texas Department of Licensing and Regulation

P.O. Box 12157
Austin, TX 78711
(512) 463-7880