



MID-MICHIGAN DISTRICT HEALTH DEPARTMENT

An Accredited Local Public Health Department

www.mmdhd.org

CLINTON
Branch Office
1307 E. Townsend Rd.
St Johns MI 48879-9036
(989) 224-2195

GRATIOT
Branch Office
151 Commerce Drive
Innaca MI 48847-1621
(989) 875-3681

MONTCALM
Branch Office
615 N. State St. Ste 1
Stanton MI 48888-9702
(989) 331-5237

ADMINISTRATIVE OFFICES
615 N. State St. Ste 2
Stanton MI 48888-9702
(989) 331-5237

MARK W. (MARCUS) CHEATHAM
Health Officer

JENNIFER MORSE, MD
Medical Director

Clinton County



06/07/2018

Paul Phillips & Lisa Farley
3216 Ellen Ave
Lansing MI 48910
United States

Re: Application for 004056

Dear Paul :

Pursuant to your application for a Vacant Land Evaluation, this department conducted a routine investigation on 06/01/2018 in Victor, Section 22, Shepardsville Rd. This investigation has revealed varied suitable soils and a suitable seasonal water table (please see the attached soils worksheet for more details). An approved area has been designated for on-site sewage disposal should the applicant choose to pursue a permit for an on-site sewage disposal system (see attached worksheet). The approved area is based on current soil/site conditions and the expressed usage as a single-family residential site. This evaluation expires in two years from the date above. Any alteration (driving on or moving of soil) of the current site conditions may void the approved area. Actual sewage system design will be determined at the time of permit issuance.

Should you wish to discuss the findings of our investigation, please contact this department.

Sincerely,
Adam Byrne
Environmental Health Specialist -
abyrne@mmdhd.org
Clinton County

Soils Worksheet

Owner's Name

Paul Phillips

Date of Site Visit

2018-06-
01T00:00:00Z

Soil Texture Key

O	Organic, Muck, Peat	LS	Loamy Sand
CL	Clay Loam	TS	Topsoil
C	Clay	WT	Water (Current)
L	Loam	G	Mottling, Gleying, or Seasonal Water Table
S	Sand	B	Hand Auger Boring
Si	Silt	BH	Back Hoe Cut
SL	Sandy Loam	MC	Mechanical Cut

Soil Profile 1

Type of Boring BH
 Profile Depth in Inches 60"
 0"-11" TS LS
 Soil Profile in Inches 11"-48" LS
 48"-60" SL
 Seasonal Water Table Depth in Inches Not observed

Soil Profile 2

Type of Boring BH
 Profile Depth in Inches 60"
 0"-10" TS LS
 Soil Profile in Inches 10"-40" LS
 40"-60" SL
 Seasonal Water Table Depth in Inches 40"

Soil Profile 3

Type of Boring BH
 Profile Depth in Inches 60"
 0-12" TS LS
 Soil Profile in Inches 12"-60" LS
 Seasonal Water Table Depth in Inches Not observed



Phillips-Farley Vacant Land

140-022-300-005-02
Shepardsville Rd, Victor
Twp, Section 22, Clinton






Map Publication:
06/07/2018 3:35 PM

20m
60ft

powered by
FetchGIS

Disclaimer: This map does not represent a survey or legal document and is provided on an "as is" basis. Mid Michigan District Health Department expresses no warranty for the information displayed on this map document.





Phillips-Farley
Vacant Land
140-022-300-005-02
Shepardsville Rd, Victor
Twp, Section 22, Clinton



Map Publication:
06/07/2018 3:39 PM



powered by
FetchGIS

Disclaimer: This map does not represent a survey or legal document and is provided on an "as is" basis. Mid Michigan District Health Department expresses no warranty for the information displayed on this map document.