

REAL ESTATE CONDITION REPORT**DISCLAIMER**

THIS CONDITION REPORT CONCERNS THE REAL PROPERTY LOCATED AT N5929 Schneeberger Rd IN THE Town
 (CITY) (VILLAGE) (TOWN) OF Mount Pleasant, COUNTY OF Green
Green STATE OF WISCONSIN.

THIS REPORT IS A DISCLOSURE OF THE CONDITION OF THAT PROPERTY IN COMPLIANCE WITH SECTION 709.02 OF THE WISCONSIN STATUTES AS OF 9 (MONTH) 1 (DAY), 2019 (YEAR). IT IS NOT A WARRANTY OF ANY KIND BY THE OWNER OR ANY AGENTS REPRESENTING ANY PARTY IN THIS TRANSACTION AND IS NOT A SUBSTITUTE FOR ANY INSPECTIONS OR WARRANTIES THAT THE PARTIES MAY WISH TO OBTAIN.

A buyer who does not receive a fully completed copy of this report within 10 days after the acceptance of the contract of sale or option contract for the above-described real property has the right to rescind that contract (Wis. Stat. s. 709.02), provided the owner is required to provide this report under Wisconsin Statutes chapter 709.

NOTICE TO PARTIES REGARDING ADVICE OR INSPECTIONS

Real estate licensees may not provide advice or opinions concerning whether or not an item is a defect for the purposes of this report or concerning the legal rights or obligations of parties to a transaction. The parties may wish to obtain professional advice or inspections of the property and to include appropriate provisions in a contract between them with respect to any advice, inspections, defects, or warranties.

A. OWNER'S INFORMATION

A1. In this form, "aware" means the "owner(s)" have notice or knowledge.

A2. In this form, "defect" means a condition that would have a significant adverse effect on the value of the property; that would significantly impair the health or safety of future occupants of the property; or that if not repaired, removed, or replaced would significantly shorten or adversely affect the expected normal life of the premises.

A3. In this form, "owner" means the person or persons, entity, or organization that owns the above-described real property. An "owner" who transfers real estate containing one to four dwelling units, including a condominium unit and time-share property, by sale, exchange, or land contract is required to complete this report.

Exceptions: An "owner" who is a personal representative, trustee, conservator, or fiduciary appointed by or subject to supervision by a court, and who has never occupied the property transferred is not required to complete this report. An "owner" who transfers property that has not been inhabited or who transfers property in a manner that is exempt from the real estate transfer fee is not required to complete this report. (Wis. Stat. s. 709.01)

A4. The owner represents that to the best of the owner's knowledge, the responses to the following questions have been accurately checked as "yes," "no," or "not applicable (N/A)" to the property being sold. If the owner responds to any question with "yes," the owner shall provide, in the additional information area of this form, an explanation of the reason why the response to the question is "yes."

A5. If the transfer is of a condominium unit, the property to which this form applies is the condominium unit, the common elements of the condominium, and any limited common elements that may be used only by the owner of the condominium unit being transferred.

A6. The owner discloses the following information with the knowledge that, even though this is not a warranty, prospective buyers may rely on this information in deciding whether and on what terms to purchase the property. The owner hereby authorizes the owner's agents and the agents of any prospective buyer to provide a copy of this report, and to disclose any information in the report, to any person in connection with any actual or anticipated sale of the property.

CAUTION: The lists of defects following each question below are examples only and are not the only defects that may properly be disclosed in response to each respective question.

B. STRUCTURAL AND MECHANICAL

- | | YES | NO | N/A |
|---|-------------------------------------|-------------------------------------|--------------------------|
| B1. Are you aware of defects in the roof?
Roof defects may include items such as leakage or significant problems with gutters or eaves. | ☐ | ☒ | ☐ |
| B2. Are you aware of defects in the electrical system?
Electrical defects may include items such as electrical wiring not in compliance with applicable code, knob and tube wiring, 60 amp service, or aluminum-branch circuit wiring. | ☐ | ☒ | ☐ |
| B3. Are you aware of defects in part of the plumbing system (including the water heater, water softener, and swimming pool)?
Other plumbing system defects may include items such as leaks or defects in pipes, toilets, interior or exterior faucets, bathtubs, showers, or any sprinkler system. | ☒ | ☐ | ☐ |
| B4. Are you aware of defects in the heating and air conditioning system (including the air filters and humidifiers)?
Heating and air conditioning defects may include items such as defects in the heating ventilation and air conditioning (HVAC) equipment, supplemental heaters, ventilating fans or fixtures, or solar collectors. | ☐ | ☒ | ☐ |
| B5. Are you aware of defects in a woodburning stove or fireplace or of other defects caused by a fire in a stove or fireplace or elsewhere on the property?
Such defects may include items such as defects in the chimney, fireplace flue, inserts, or other installed fireplace equipment; or woodburning stoves not installed pursuant to applicable code. | ☐ | ☒ | ☐ |
| B6. Are you aware of defects related to smoke detectors or carbon monoxide detectors or a violation of applicable state or local smoke detector or carbon monoxide detector laws?
NOTE: State law requires operating smoke detectors on all levels of all residential properties and operating carbon monoxide detectors on all levels of most residential properties (see Wis. Stat. ch. 101). | ☒ | ☐ | ☐ |
| B7. Are you aware of defects in the basement or foundation (including cracks, seepage, and bulges)?
Other basement defects may include items such as flooding, defects in drain tiling or sump pumps, or movement, shifting, or deterioration in the foundation. | ☒ | ☐ | ☐ |
| B8. Are you aware of defects in any structure on the property?
Structural defects with respect to the residence or other improvements may include items such as movement, shifting, or deterioration in walls; major cracks or flaws in interior or exterior walls, partitions, or the foundation; wood rot; and significant problems with driveways, sidewalks, patios, decks, fences, waterfront piers or walls, windows, doors, floors, ceilings, stairways, or insulation. | ☒ | ☐ | ☐ |
| B9. Are you aware of defects in mechanical equipment included in the sale either as fixtures or personal property?
Mechanical equipment defects may include items such as defects in any appliance, central vacuum, garage door opener, in-ground sprinkler, or in-ground pet containment system that is included in the sale. | ☒ | ☐ | ☐ |
| B10. Are you aware of rented items located on the property such as a water softener or other water conditioner system or other items affixed to or closely associated with the property? | ☒ | ☐ | ☐ |
| B11. Are you aware of basement, window, or plumbing leaks, overflow from sinks, bathtubs, or sewers, or other ongoing water or moisture intrusions or conditions? | ☐ | ☒ | ☐ |

B12. Explanation of "yes" responses B1, B3, B6, B7, B8, B9, B10, B11

SEE ADDENDUM 1 TO REAL ESTATE CONDITION REPORT FOR N5929 SCHNEEBERGER RD. DATED 9/1/2019

C. ENVIRONMENTAL

- | | YES | NO | N/A |
|--|--------------------------|-------------------------------------|--------------------------|
| C1. Are you aware of the presence of unsafe levels of mold? | ☐ | ☒ | ☐ |
| C2. Are you aware of a defect caused by unsafe concentrations of, or unsafe conditions relating to, radon, radium in water supplies, high voltage electric (100 KV or greater) or steel natural gas transmission lines located on but not directly serving the property, lead in paint, lead in soil, or other potentially hazardous or toxic substances on the property?
NOTE: Specific federal lead paint disclosure requirements must be complied with in the sale of most residential properties built before 1978. | ☐ | ☒ | ☐ |

- | | YES | NO | N/A |
|--|--------------------------|-------------------------------------|--------------------------|
| C3. Are you aware of the presence of asbestos or asbestos-containing materials on the property? | ☐ | ☒ | ☐ |
| C4. Are you aware of the presence of or a defect caused by unsafe concentrations of, unsafe conditions relating to, or the storage of hazardous or toxic substances on neighboring properties? | ☐ | ☒ | ☐ |
| C5. Are you aware of current or previous termite, powder post beetle, or carpenter ant infestations or defects caused by animal, reptile, or insect infestations? | ☐ | ☒ | ☐ |
| C6. Are you aware of water quality issues caused by unsafe concentrations of or unsafe conditions relating to lead? | ☐ | ☒ | ☐ |
| C7. Are you aware of the manufacture of methamphetamine or other hazardous or toxic substances on the property? | ☐ | ☒ | ☐ |

C8. Explanation of "yes" responses

D. WELLS, SEPTIC SYSTEMS, STORAGE TANKS

- | | YES | NO | N/A |
|---|-------------------------------------|-------------------------------------|-------------------------------------|
| D1. Are you aware of defects in a well on the property or in a well that serves the property, including unsafe well water?
Well defects may include items such as an unused well not properly closed in conformance with state regulations, a well that was not constructed pursuant to state standards or local code, or a well that requires modifications to bring it into compliance with current code specifications. Well water defects might include, but are not limited to, unsafe levels of bacteria (total Coliform and E. coli), nitrate, arsenic, or other substances affecting human consumption safety. | ☐ | ☒ | ☐ |
| D2. Are you aware of a joint well serving the property? | ☒ | ☐ | ☐ |
| D3. Are you aware of a defect related to a joint well serving the property? | ☐ | ☒ | ☐ |
| D4. Are you aware that a septic system or other private sanitary disposal system serves the property? | ☒ | ☐ | ☐ |
| D5. Are you aware of defects in the septic system or other private sanitary disposal system on the property or any out-of-service septic system that serves the property and that is not closed or abandoned according to applicable regulations?
Septic system defects may include items such as backups in toilets or in the basement; exterior ponding, overflows, or backups; or defective or missing baffles. | ☐ | ☒ | ☐ |
| D6. Are you aware of underground or aboveground fuel storage tanks on or previously located on the property? (If "yes," the owner, by law, may have to register the tanks with the Wisconsin Department of Agriculture, Trade and Consumer Protection at P.O. Box 8911, Madison, Wisconsin, 53708, whether the tanks are in use or not. Regulations of the Wisconsin Department of Agriculture, Trade and Consumer Protection may require the closure or removal of unused tanks.) | ☐ | ☒ | ☐ |
| D7. Are you aware of defects in the underground or aboveground fuel storage tanks on or previously located on the property?
Defects in underground or aboveground fuel storage tanks may include items such as abandoned tanks not closed in conformance with applicable local, state, and federal law; leaking; corrosion; or failure to meet operating standards. | ☐ | ☐ | ☒ |
| D8. Are you aware of an "LP" tank on the property? (If "yes," specify in the additional information space whether the owner of the property either owns or leases the tank.) | ☒ | ☐ | ☐ |
| D9. Are you aware of defects in an "LP" tank on the property? | ☐ | ☒ | ☐ |

D10. Explanation of "yes" responses

D2, D4, D8

SEE ADDENDUM 1 TO REAL ESTATE CONDITION REPORT FOR N5929 SCHNEEBERGER RD. DATED 9/1/2019

E. TAXES, SPECIAL ASSESSMENTS, PERMITS, ETC.

- | | YES | NO | N/A |
|--|--------------------------|-------------------------------------|--------------------------|
| E1. Have you received notice of property tax increases, other than normal annual increases, or are you aware of a pending property reassessment? | ☐ | ☒ | ☐ |
| E2. Are you aware that remodeling was done that may increase the property's assessed value? | ☐ | ☒ | ☐ |

	YES	NO	N/A
E3. Are you aware of pending special assessments?	☐	☒	☐
E4. Are you aware that the property is located within a special purpose district, such as a drainage district, that has the authority to impose assessments against the real property located within the district?	☐	☒	☐
E5. Are you aware of any proposed construction of a public project that may affect the use of the property?	☐	☒	☐
E6. Are you aware of any remodeling, replacements, or repairs affecting the property's structure or mechanical systems that were done or additions to this property that were made during your period of ownership without the required permits?	☐	☒	☐
E7. Are you aware of any land division involving the property for which a required state or local permit was not obtained?	☐	☒	☐
E8. Explanation of "yes" responses <u>E2</u>			

SEE ADDENDUM 1 TO REAL ESTATE CONDITION REPORT FOR N5929 SCHNEEBERGER RD. DATED 9/1/2019

F. LAND USE

	YES	NO	N/A
F1. Are you aware of the property being part of or subject to a subdivision homeowners' association?	☐	☒	☐
F2. If the property is not a condominium unit, are you aware of common areas associated with the property that are co-owned with others?	☐	☒	☐
F3. Are you aware of any zoning code violations with respect to the property?	☐	☒	☐
F4. Are you aware of the property or any portion of the property being located in a floodplain, wetland, or shoreland zoning area?	☐	☒	☐
F5. Are you aware of nonconforming uses of the property? A nonconforming use is a use of land, a dwelling, or a building that existed lawfully before the current zoning ordinance was enacted or amended, but that does not conform to the use restrictions in the current ordinance.	☒	☐	☐
F6. Are you aware of conservation easements on the property? A conservation easement is a legal agreement in which a property owner conveys some of the rights associated with ownership of his or her property to an easement holder such as a governmental unit or a qualified nonprofit organization to protect the natural habitat of fish, wildlife, or plants or a similar ecosystem, preserve areas for outdoor recreation or education, or for similar purposes.	☐	☒	☐
F7. Are you aware of restrictive covenants or deed restrictions on the property?	☐	☒	☐
F8. Are you aware of nonowners having rights to use part of the property, including, but not limited to, rights-of-way and easements other than recorded utility easements?	☐	☒	☐
F9. Are you aware of the property being subject to a mitigation plan required under administrative rules of the Wisconsin Department of Natural Resources related to county shoreland zoning ordinances, which obligates the owner of the property to establish or maintain certain measures related to shoreland conditions and which is enforceable by the county?	☐	☒	☐
F10. The use value assessment system values agricultural land based on the income that would be generated from its rental for agricultural use rather than its fair market value. When a person converts agricultural land to a non agricultural use (e.g., residential or commercial development), that person may owe a conversion charge. For more information visit https://www.revenue.wi.gov/Pages/FAQS/slf-useassmt.aspx or (608) 266-2486.			
a. Are you aware of all or part of the property having been assessed as agricultural land under Wis. Stat. s. 70.32 (2r) (use value assessment)?	☒	☐	☐
b. Are you aware of the property having been assessed a use-value assessment conversion charge relating to this property? (Wis. Stat. s. 74.485 (2))	☐	☒	☐
c. Are you aware of the payment of a use-value assessment conversion charge having been deferred relating to this property? (Wis. Stat. s. 74.485 (4))	☐	☒	☐
F11. Is all or part of the property subject to or in violation of a farmland preservation agreement? Early termination of a farmland preservation agreement or removal of land from such an agreement can trigger payment of a conversion fee equal to 3 times the class 1 "use value" of the land.	☐	☒	☐

Visit https://datcp.wi.gov/Pages/Programs_Services/FarmlandPreservation.aspx for more information.

- | | YES | NO | N/A |
|---|--------------------------|-------------------------------------|--------------------------|
| F12. Is all or part of the property subject to, enrolled in, or in violation of the Forest Crop Law, Managed Forest Law, the Conservation Reserve Program, or a comparable program? | ☐ | ☒ | ☐ |
| F13. Are you aware of a dam that is totally or partially located on the property or that an ownership in a dam that is not located on the property will be transferred with the property because it is owned collectively by members of a homeowners' association, lake district, or similar group? (If "yes," contact the Wisconsin Department of Natural Resources to find out if dam transfer requirements or agency orders apply.) | ☐ | ☒ | ☐ |
| F14. Are you aware of boundary or lot line disputes, encroachments, or encumbrances (including a joint driveway) affecting the property?
Encroachments often involve some type of physical object belonging to one person but partially located on or overlapping on land belonging to another; such as, without limitation, fences, houses, garages, driveways, gardens, and landscaping. Encumbrances include, without limitation, a right or claim of another to a portion of the property or to the use of the property such as a joint driveway, liens, and licenses. | ☐ | ☒ | ☐ |
| F15. Are you aware there is not legal access to the property? | ☐ | ☒ | ☐ |
| F16. Are you aware of federal, state, or local regulations requiring repairs, alterations, or corrections of an existing condition? This may include items such as orders to correct building code violations. | ☐ | ☒ | ☐ |
| F17. Are you aware of a pier attached to the property that is not in compliance with state or local pier regulations? See http://dnr.wi.gov/topic/waterways for more information. | ☐ | ☒ | ☐ |
| F18. Are you aware of one or more burial sites on the property? (For information regarding the presence, preservation, and potential disturbance of burial sites, contact the Wisconsin Historical Society at 800-342-7834 or www.wihist.org/burial-information). | ☐ | ☒ | ☐ |

F19. Explanation of "yes" responses ☐ F4, ☐ F5, ☐ F10a, ☐ F18

SEE ADDENDUM 1 TO REAL ESTATE CONDITION REPORT FOR N5929 SCHNEEBERGER RD. DATED 9/1/2019

G. ADDITIONAL INFORMATION

- | | YES | NO | N/A |
|---|--------------------------|-------------------------------------|--------------------------|
| G1. Have you filed any insurance claims relating to damage to this property or premises within the last five years? | ☐ | ☒ | ☐ |
| G2. Are you aware of a structure on the property that is designated as a historic building or that all or any part of the property is in a historic district? | ☐ | ☒ | ☐ |
| G3. Are you aware of any agreements that bind subsequent owners of the property, such as a lease agreement or an extension of credit from an electric cooperative? | ☐ | ☒ | ☐ |
| G4. Are you aware of other defects affecting the property?
Other defects might include items such as drainage easement or grading problems; excessive sliding, settling, earth movements, or upheavals; or any other defect or material condition. | ☐ | ☒ | ☐ |
| G5. The owner has owned the property for <input type="text" value="23"/> years. | | | |
| G6. The owner has lived in the property for <input type="text" value="21"/> years. | | | |
| G7. Explanation of "yes" responses | | | |

Notice: You may obtain information about the sex offender registry and persons registered with the registry by contacting the Wisconsin Department of Corrections at <http://www.doc.wi.gov> or by phone at 608-240-5830.

OWNER'S CERTIFICATION

NOTE: Wisconsin Statute section 709.035 requires owners who, prior to acceptance of a purchase contract or an option to purchase, obtain information that would change a response on this report to submit a complete amended report or an amendment to the previously completed report to the prospective buyer within 10 days of acceptance.

The owner certifies that the information in this report is true and correct to the best of the owner's knowledge as of the date on which the owner signs this report.

Owner Frank Garber Goodman Date 9/1/2019
DocuSigned by: 0A53FDD17D84431
 Owner _____ Date _____
 Owner _____ Date _____
 Owner _____ Date _____
 Owner _____ Date _____

CERTIFICATION BY PERSON SUPPLYING INFORMATION

A person other than the owner certifies that the person supplied information on which the owner relied for this report and that the information is true and correct to the best of the person's knowledge as of the date on which the person signs this report.

Person _____ Items _____ Date _____
 Person _____ Items _____ Date _____
 Person _____ Items _____ Date _____

BUYER'S ACKNOWLEDGEMENT

The prospective buyer acknowledges that technical knowledge such as that acquired by professional inspectors may be required to detect certain defects such as the presence of asbestos, building code violations, and floodplain status.

I acknowledge receipt of a copy of this statement.

Prospective buyer _____ Date _____
 Prospective buyer _____ Date _____
 Prospective buyer _____ Date _____
 Prospective buyer _____ Date _____
 Prospective buyer _____ Date _____

Information appearing in italics is supplemental in nature and is not required pursuant to Section 709.03 of the Wisconsin Statutes.

ADDENDUM 1 TO REAL ESTATE CONDITION REPORT FOR N5929 SCHNEEBERGER RD. DATED 9/1/2019

B1 When there was a lift available for painting the house, the current owner did what he could to tighten the screws holding down the metal roofing panels but was not able to get to all of them. There is no observable leaking but it may be good for a new owner to make sure the screws have all been tightened. Likewise, the current owner did what he could but it may be good for a new owner to make sure the "cobra vent" at the ridge caps is intact and in place.

B3 The water heater works but needs to be replaced. The water softener leaks and needs to be replaced.

B6 The fire alarm system was installed by ADT approximately 15 years ago and hasn't been checked since. The system has needed to be checked, updated, verified etc.

There are ADT smoke detectors on all 3 floors, a carbon monoxide detector on the first floor and a freeze detector in the basement

An ADT technician visited the property on 8/30/19 to perform necessary checks. The technician checked and/or replaced all detectors in all buildings and verified that the ADT system is working properly. However, the ADT tech discovered that there were problems with the TDS land line (static and no dial tone) that was preventing the alarm system from working properly. A TDS technician will be at the property to check the phone line on 9/4/19. It is to be assumed that the TDS tech will address the land line issues and then both the TDS landline and the alarm system will be operating properly. This report will be updated as needed. Interested parties should verify with either ADT or the current owner. As per code, there are additional plug-in carbon monoxide detectors and battery powered smoke detectors in several other locations in the building.

B7 There is a crack in the foundation with a leak that will sometimes allow water to accumulate in the NW corner of the basement. This crack will be repaired by Zander Solutions of Verona, WI on 9/3/19. There are some other cracks in the foundation from the inevitable settling of the building. At the moment they are not causing leaks. This may be due in part to the installation of a "french drain" on the north side of the building.

The ejector pump in the sump that collects the water from the basement sink, toilet, washing machines etc. is in working condition but should probably be replaced.

The dehumidifier works but should be replaced.

B8 The concrete piers that support the 6x6 posts around the perimeter of the building were not poured on top of footings. Therefore, they have settled somewhat. Since the posts were attached to both the top of the piers and the beam that supports the rafters of the porch overhangs, there has been some minor distortion of the eave line. A viewer will note that it is not perfectly straight or level. To address this problem, the owner cut the bottom of the posts free from the top of the piers so that the eaves would not be affected should there be any further settling. He then inserted shims between the bottom of the posts and the top of the piers so that the posts had some direct bearing surface onto the pier.

B9 See B3 and B7. Additionally, the ceiling fan in the main living area is not currently working. The reason for this has not yet been determined. It could be the fan but it may be the switch.

B10 LP tank is owned by Badger State Propane which charges a \$10/yr rental fee.

B11 There are no on-going leaks though there have been a few incidences of people causing leaks into the basement through such carelessness as showering with the shower door not properly closed.

D2 One high capacity well (up to 70 gallons/minute) serves N5927, N5929, and N5931 Schneeberger Rd. This same well provides for outdoor uses as well including irrigation system and several external spigots.

D4 There are two septic systems on the property. One serves N5929 and N5931 and the other serves N5927.

D8 There are two LP tanks on the Little Sugar River Farm property. A 1000 gallon tank serves N5929 and N5931 and a 500 gallon tank serves N5927. Both are owned by Badger State Propane of Monroe, WI. See B10.

E2 None has been done since last assessment

F4 Owner consulted Wisconsin Dept. of Natural Resources before purchase of property in 1996 to inquire about floodplain status. Owner was told at that time that the property existed beyond the 500 year floodplain. Interested parties should verify.

F5 Current zoning regulations in Green County prohibit more than one residence per lot. The residence at N5931 Schneeberger Rd shares a lot with the residence at N5929 Schneeberger Rd. This situation existed before the implementation of the current regulations and, therefore, has been grandfathered in. This means that there is a legal non-conforming use on the lot that includes N5929 and N5931. Green County Zoning is aware of the current status and approves this current use. Interested parties should verify.

F10a The lot where N5929 and N5939 Schneeberger Rd are located has been assessed for tax purposes as part agricultural and part residential. For zoning purposes, the entire property is zoned agricultural. Interested parties should check with realtor or Green County for details.

F18 Owners buried a pet dog under a tree on the north lawn.

DocuSigned by:

Frank Garber Goodman 1/2019

6A83FDD17D84451...