

APPROVED BY THE TEXAS REAL ESTATE COMMISSION (TREC)



SELLER'S DISCLOSURE NOTICE

NCERNING THE PROPERTY A	(Street Address	Harwood
	(Offeet Address	and City)
	OR ANY INSPECTIONS OR WARRANTIES THE	F THE PROPERTY AS OF THE DATE SIGNED B PURCHASER MAY WISH TO OBTAIN. IT IS NOT
er 🔀 is 🗌 is not occupying the F	Property. If unoccupied, how long since Sel	ller has occupied the Property?
The Property has the items checke	d below [Write Yes (Y), No (N), or Unknown (U)]:
Y_Range	Y_Oven	Y_Microwave
Y_ Dishwasher	N Trash Compactor	Y Disposal
Y Washer/Dryer Hookups	Y Window Screens	Y Rain Gutters
N_ Security System	N Fire Detection Equipment	N_Intercom System
	Smoke Detector	
	N Smoke Detector-Hearing Impaired	
	Y Carbon Monoxide Alarm	
	N Emergency Escape Ladder(s)	
Y_ TV Antenna	Cable TV Wiring	Y Satellite Dish
Y Ceiling Fan(s)	Y_Attic Fan(s)	Y Exhaust Fan(s)
Y_ Central A/C	Y Central Heating	Y Wall/Window Air Conditioning (9 9 rage
Y Plumbing System	Y Septic System	N Public Sewer System
Y Patio/Decking	N Outdoor Grill	Y Fences
N Pool	N Sauna	N Spa N Hot Tub
N Pool Equipment	N Pool Heater	Y Automatic Lawn Sprinkler System
Fireplace(5) & Chimney (Wood-burning)		Y Fireplace(s) & Chimney (Mock)
N Natural Gas Lines		Y_ Gas Fixtures
Y Liquid Propane Gas	N LP Community (Captive)	Y LP on Property
Garage: Attached	Y Not Attached (small equipment)	Y Carport
Garage Door Opener(s): Y	Y Electronic	Y Control(s)
Water Heater: Y	Y Gas	Y Electric 4 For some "point of use"
Water Supply: City	N Well N MUD	N Co-op units in garage
Roof Type: Galvalume		Age:2015(approx.)
Are you (Seller) aware of any of need of repair? XYes ☐ No ☐ Unknow	n. If yes, then describe. (Attach additional sheets if no	ndition, that have known defects, or that are
Disclosure Addendum		

TREC No. OP-H

Fax:

TREC No. OP-H

property? Yes No. If yes, explain (attach additional sheets as necessary):

Have you (Seller) ever received assistance from FEMA or the U.S. Small Business Administration (SBA) for flood damage to the

property within the structure(s).



This form was prepared by the Texas Real Estate Commission in accordance with Texas Property Code § 5.008(b) and is to be used in conjunction with a contract for the sale of real property entered into on or after September 1, 2019. Texas Real Estate Commission, P.O. Box 12188, Austin, TX 78711-2188, 512-936-3000 (http://www.trec.texas.gov) TREC NO. OP-H

TREC No. OP-H

Seller's Disclosure Addendum

- 1. The house has been levelled several times over the years due to natural movements of the clay soil. However, in Oct. 2019, Eco-Soil Stabilizers was hired to inject a proprietary solution around the perimeter of the house, garage and barn to try and minimize these soil movements. While these injections (as well as the use of drip lines around the perimeters of the house, garage and barn) do appear to have reduced soil movement in the areas applied, minor shifting/settlement may still occur from time to time (which could lead to temporary door misalignments, etc.).
- 2. The roof was completely re-done in 2015.
- 3. The propane tank is buried on the east side of the house, just past the wooden fence and north of the 3 AC units.
- 4. Seller is not aware of any termite damage to the house since it was purchased in August 2008, but Annie Oakley provides yearly maintenance checkups/service to the crawl space under the house as a preventative measure.
- Between 2013 and 2017, the house was updated with two additional rooms, a new roof, and a complete interior remodel. Permits were not secured because the property did not fall within the incorporated area of any city.
- 6. The entire 373.06 Ac. property falls within the Gonzales County Underground Water Conservation District.
- 7. The water meter for the house is located approximately ¾ of a mile west of the property on CR 150. Gonzales County Water Supply Corporation does not service line breaks occurring on the property owner's (i.e., east) side of the meter, so the property owner is responsible for repairing such breaks as well as for any increased water usage that results therefrom. Breaks can occur from time to time due to cattle stepping on the water line (as the line is buried approx. a foot deep in some areas) and/or due to fast moving water in Sandy Fork Creek (where the water line is exposed however, it should be noted that where the water line crosses Sandy Fork Creek, it is encased in Schedule 80 pipe and staked down for additional protection from the elements).
- 8. The window screens for the house are stored in the attic of the garage. Some of the screens may be damaged.
- 9. The vent-free fireplace in the living room of the house works, but the unit must sometimes be reset more than once before the fireplace will stay on.
- 10. The seller was notified in or around February 18, 2020 that GVEC is in the process of deciding where to build a new 138 kV transmission line from Delhi to Bluestem. Two of the proposed route segments could potentially affect the seller's property (Route V and Route Z see "Preliminary Alternative Route Segment" map from GVEC). The final route has not been determined.

