

## **SELLER'S DISCLOSURE NOTICE**

©Texas Association of REALTORS®, Inc. 2019

Section 5.008, Property Code requires a seller of residential property of not more than one dwelling unit to deliver a Seller's Disclosure Notice to a buyer on or before the effective date of a contract. This form complies with and contains additional disclosures which exceed the minimum disclosures required by the Code.

CONCERNING THE PROPERTY AT Bedias, TX 77831										_					
THIS NOTICE IS A DISCLOSURE OF SELLER'S KNOWLEDGE OF THE CONDITION OF THE PROPERTY AS OF THE DATE SIGNED BY SELLER AND IS NOT A SUBSTITUTE FOR ANY INSPECTIONS OR WARRANTIES THE BUYER MAY WISH TO OBTAIN. IT IS NOT A WARRANTY OF ANY KIND BY SELLER, SELLER'S AGENTS, OR ANY OTHER AGENT.															
Seller is <u>√</u> is not_o 5/18/2021	ccup	ying	j the	Pro	oper (ap	ty. I prox	f unoccupied (by Sell rimate date) or ne	er), l ver d	how	long pied	; si the	nce Seller has occupied the Fe Property	, rob	erty	?
Section 1. The Proper	rty h not e	as t stabi	he i lish t	tem	s m	ark	ed below: (Mark Yes	: /Y)	Nο	/NN	^-		/.		
Item	Y	N	U	]		em	. <u> </u>	Υ	N	U	1	Item		T	·
Cable TV Wiring	1			1			Propane Gas:	+*		-		<u></u>		N	Ľ
Carbon Monoxide Det.	<del>                                     </del>	/	ļ	1			ommunity (Captive)	$\vdash$		_		Pump: sump grinder Rain Gutters	1		H
Ceiling Fans		<u> </u>	<del>                                     </del>	1			Property	<del>                                     </del>	<u> </u>				1	$\square$	<u> </u>
Cooktop	1			1	_	ot Ti	<del></del>	1	_			Range/Stove			<u>.</u>
Dishwasher	1.		ļ	1	-		om System	<del>  -</del>		-		Roof/Attic Vents	1		<b></b>
Disposal			<u> </u>	1			wave	<del>                                     </del>	~			Sauna		~	
Emergency Escape	<del>  ^</del>	<del></del> -					or Grill	1				Smoke Detector		$\sqcup \sqcup$	_
Ladder(s)	<b>/</b>				"	uluu	or Grill					Smoke Detector - Hearing			
Exhaust Fans	1				P	atio/	Decking		~			Impaired		V	
Fences		-			_		ing System					Spa	$\sqcup$	<b>V</b>	
Fire Detection Equip.	7				-	ool	ing Cystem	1	-			Trash Compactor	$\sqcup$	~	
French Drain	+				-		quipment	4	_			TV Antenna		<u>'</u>	
Gas Fixtures		7	-				faint. Accessories	1				Washer/Dryer Hookup	$   \sqrt{} $		
Natural Gas Lines		<u>`</u>			_		leater		$\leftarrow$			Window Screens	1		
Trataral Gas Ellios	<u> </u>					JUI F	leater					Public Sewer System			
Item	·· · · · · ·			Υ	N	U	T			1 014					
Central A/C					IN	<u> </u>	Cala atria					al Information			
Evaporative Coolers	<del>-</del>			V		┾	electric gas	num	iber	of u	nit	s: <u>2</u>			
Wall/Window AC Units			$\dashv$		1	-	number of units:		<del>-</del>						_
Attic Fan(s)				<del>م</del> ـــــــــــــــــــــــــــــــــ	-	┝	number of units:								
Central Heat					-	├	if yes, describe:		l.						
Other Heat					_	-	electric gas number of units: (2)								
Oven							if yes, describe:				-				
Fireplace & Chimney							number of ovens:					icgasother:			
Carport	<del></del>	-		<u>/</u>			wood gas log		mo		_01	her: Go assist			
Garage							attachednot								
Garage Door Openers			-	<u> </u>		-	attachednot	attac	hed						
Satellite Dish & Controls			-	-	<del>/</del>		number of units:					umber of remotes:			
Security System			$\dashv$				ownedleased					CC			
Solar Panels				~	_		ownedleased			AU	- 9	- U d - 5			
					_		ownedleased								
Water Heater (2) Water Softener	<del></del>			<u> </u>	_		_∕electric gas		ner:			number of units: 2			
Other Leased Items(s)			-	$\dashv$	<u> </u>		ownedleased	fror	n:	. "					
Other Leased items(s)	·· .		[		/		if yes, describe:								
(TXR-1406) 09-01-19		lı	nitial	ed b	y: B	uyer	:, ar	nd Se	ller:	<u>(</u> -v	_	, A Pag	је 1	of 6	
Brazos Land Company, 116 S Main St And Beau Skinner									Phon	e: 979:	57418	57 Fax: 9368732301 Rodriv	mes c	Gabriel	
AGU ORIBIET	Proc	luced v	vith Lo	ne Wo	lf Tran	saction	ns (zipForm Edition) 231 Shearson	Cr. Car	nbridge	e, Onta	rio, (	Canada N1T 1J5 www.lwolf.com	, were to	, and PCI	

Concerning the Property at	
----------------------------	--

16007 CR 228 Bedias, TX 77831

Septic / On-Site Sewer Facility   If yes, ettach Information About On-Site Sewer Facility (TXR-1407)   Water supply provided by: _city _weil _ MUD _ co-op _ unknown _ other: _(3)	Underground Lawn Sprink	der			au	tomati	C manual	20	225 60	vorod:		
Waler supply provided by: _city _well _ MUD _ co-op _ unknown _ other: _(3)											07\	
(#yes, complete, sign, and attach TXR-1906 concerning lead-based paint hazards).  Age:			fu /	well Mill	<u>, , , , , , , , , , , , , , , , , , , </u>	20.00		170		-Site Sewer Facility (TXR-14	07)	
(if yes, complete, sign, and attach TXR-1906 concoming lead-based paint hazards). Age:	Was the Property built bef	ore 19	978?	VES AN	<u></u> '	co-op	unknown		other: _	(3) welly un prup	17.	1
is there an overlay roof covering on the Property (shingles or roof covering)?yesYoounknown  Are you (Seller) aware of any of the items listed in this Section 1 that are not in working condition, that have defects, or are need of repair?yesYoothy own  Section 2. Are you (Seller) aware of any defects or malfunctions in any of the following? (Mark Yes (Y) if you are aware and No (N) if you are not aware.}  Section 3. Are you (Seller) aware of any defects or malfunctions in any of the following? (Mark Yes (Y) if you are aware and No (N) if you are not aware.}  Item	(If yes, complete, sign	, and	attacl	h TXR-1906	conc	erning	vii lead-based	nai	nt haza	arde)		•
Are you (Seller) aware of any of the items listed in this Section 1 that are not in working condition, that have defects, or are need of repair?yesno if yes, describe (attach additional sheets if necessary):  Section 2. Are you (Seller) aware of any defects or malfunctions in any of the following? (Mark Yes (Y) if you are aware and No (N) if you are not aware.)  Item	Roof Type: _ ~ - + - \				77	Aae		Pan	III HAZO	arus).	en vim	
Are you (Seller) aware of any of the items listed in this Section 1 that are not in working condition, that have defects, or are need of repair?yesno if yes, describe (attach additional sheets if necessary):  Section 2. Are you (Seller) aware of any defects or malfunctions in any of the following? (Mark Yes (Y) if you are aware and No (N) if you are not aware.)  Item	is there an overlay roof	cove	ring o	on the Prop	erty	shing	les or roof	COV	/erina	Diaced over existing shingle	ioxim	iate)
Section 2. Are you (Seller) aware of any defects or malfunctions in any of the following? (Mark Yes (Y) If you are aware and No (N) if you are not aware.)  Item	covering)? yes _/no _	_ unk	nown	•	•	` `			· • · · · · · · · · · · ·	placed over existing shiring	75 UI	1001
Section 2. Are you (Seller) aware of any defects or malfunctions in any of the following? (Mark Yes (Y) If you are aware and No (N) if you are not aware.)  Item	Are you (Seller) aware of	any c	of the	items listed	in th	is Sec	tion 1 that a	re r	not in w	working condition that have	٠.٠.	
Section 2. Are you (Seller) aware of any defects or malfunctions in any of the following? (Mark Yes (Y) if you are aware, and No (N) if you are not aware.)  Item Y N Basement Y N Floors Schildren Y N Sidewalks Walls / Fences Windows Windo	are need of repair? yes	√n(	o If ye	s, describe	(attac	ch add	itional sheet	e if i	necese	volking condition, that have (	jeteci	ts, or
Item			_						100000	ary).		
Item												
Item				·								
Item	Section 2. Are you (Selle	er) av	vare d	of any defe	cts o	r malf	unctions in	anı	of the	e following? (Mark Voc (V)	if was	
Basement Ceilings Doors Driveways Driveways Electrical Systems Exterior Walls If the answer to any of the items in Section 2 is yes, explain (attach additional sheets if necessary):  Section 3. Are you (Seller) aware of any of the following conditions? (Mark Yes (Y) if you are aware and No (N) if you are not aware.)  Condition Aluminum Wiring Asbestos Components Diseased Trees: oak wilt Endangered Species/Habitat on Property Fault Lines Hazardous or Toxic Waste Internitent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property Internitent or Weather Springs Landfill Lead-Based Psint or Lead-Based Pt. Hazards Encroachments onto the Property Internitent or Weather Springs Landfill Lead-Based Psint or Lead-Based Pt. Hazards Encroachments onto the Property Internitent or Weather Springs Landfill Lead-Based Psint or Lead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property Internitent or Weather Springs Landfill Lead-Based Psint or Lead-Based Pt. Hazards Encroachments onto the Property Internitent or Weather Springs Landfill Lead-Based Psint or Lead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property Internitent or Weather Springs Landfill Lead-Based Psint or Lead-Based Pt. Hazards Encroachments onto the Property Internitent or Weather Springs Landfill Lead-Based Psint or Lead-Based Pt. Hazards Encroachments onto the Property Internitent or Weather Springs Previous Foreint for termites or other wood destroying insects (WDI) Previous termite or WDI damage repaired Previous Foreint for termites or WDI Previous Foreint for termites or WDI Previous Hazards Enterior Wall damage needing repair Single Blockable Main Drain in Pool/Hot Tub/Spa*  Previous Use of Premises for Manufacture of Methamphetamine  Intilization States with additional sheets if necessary):    Condition	aware and No (N) if you a	re no	ot awa	are.)					, 0	c lonowing: (Mark res (1)	ıı yot	л аге
Basement Ceilings Doors Driveways Electrical Systems Exterior Walls If the answer to any of the items in Section 2 is yes, explain (attach additional sheets if necessary):  Section 3. Are you (Seller) aware of any of the following conditions? (Mark Yes (Y) if you are aware and No (N) if you are not aware.)  Condition Aluminum Wiring Asbestos Components Diseased Trees: oak wilt Endangered Species/Habitat on Property Fault Lines Hazardous or Toxic Waste Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property Located in Historic District Historic Property Designation Previous Foundation Repairs Previous Gornadation Repairs Previous Use of Premises for Manufacture of Methamphetamine Intermittent or Walls  Foundation / Slab(s) Walls / Fences Walls / Fences Windows Other Structural Components Uniter on Mark Yes (Y) if you are aware and No (N) if Water Andditional sheets if necessary):  Charlier Fixtures  Uniterior Walls  Condition Radon Gas Settling Soil Movement Subsurface Structure or Pits Unrecorded Easements Unrecorded Easem	Item	Y	N	Item				V	T N	léam	-	<del></del>
Foundation / Slab(s)   Walls / Fences   Windows   Wind	Basement	1		<u> </u>		<del></del>		<b>'</b>			Y	<u> </u>
Driveways Driveways Electrical Systems Exterior Walls  Frevious Roof  Interior Walls  Lighting Fixtures Plumbing Systems Roof  Interior Walls  Under Structural Components Interior Walls  Other Structural Components  Other Structu	Ceilings				tion /	Slah(s		├-	+			<u> </u>
Electrical Systems   Plumbing Systems   Roof   Cher Structural Components   Plumbing Systems   Roof   Cher Structural Components   Plumbing Systems   Cher Structural Components   Cher Structural Cher Structural Components   Cher Structural Cher Structural Components   Cher Structural Components   Cher Structural Cher St		_					?)				-	- L
Electrical Systems Exterior Walls  Flumbing Systems Roof  Plumbing Systems Roof  If the answer to any of the items in Section 2 is yes, explain (attach additional sheets if necessary):  Section 3. Are you (Seller) aware of any of the following conditions? (Mark Yes (Y) if you are aware and No (N) if you are not aware.)  Condition  Y N Aluminum Wiring Asbestos Components Diseased Trees: oak wilt Endangered Species/Habitat on Property Fault Lines Improper Drainage Intermittent or Weather Springs Intermitten	Driveways	+						<del> </del>	1			_
Exterior Walls  Roof  If the answer to any of the items in Section 2 is yes, explain (attach additional sheets if necessary):  Section 3. Are you (Seller) aware of any of the following conditions? (Mark Yes (Y) if you are aware and No (N) if you are not aware.)  Condition  Y N Aluminum Wiring  Asbestos Components  Diseased Trees: oak wilt  Endangered Species/Habitat on Property  Fault Lines  Hazardous or Toxic Waste  Improper Drainage  Intermittent or Weather Springs  Landfill  Lead-Based Paint or Lead-Based Pt. Hazards  Encroachments onto the Property  Located in Historic District  Previous Foordation Repairs  Previous Foordation Repairs  Previous Cher Structural Repairs  Previous Use of Premises for Manufacture of Methamphetamine  (TXR-1406) 09-01-19  Initialed by: Buyer:							<del>-</del>	<u> </u>		Other Structural Component	S	ساء ا
If the answer to any of the Items in Section 2 is yes, explain (attach additional sheets if necessary):  Section 3. Are you (Seller) aware of any of the following conditions? (Mark Yes (Y) if you are aware and No (N) if you are not aware.)  Condition  Y N Radon Gas Asbestos Components  Diseased Trees: oak wilt Endangered Species/Habitat on Property Fault Lines Hazardous or Toxic Waste Unplatted Easements Unplatted Easements Unrecorded Easements U		_		}	ig Oy	Joysteins						
Section 3. Are you (Seller) aware of any of the following conditions? (Mark Yes (Y) if you are aware and No (N) if you are not aware.)  Condition Y N Aluminum Wiring Asbestos Components Diseased Trees: oak wilt Soil Movement Endangered Species/Habitat on Property Fault Lines Underground Storage Tanks Unrea-formaldehyde insulation Water Damage Not Due to a Flood Event Wetlands on Property Wood Rot Active infestation of termites or other wood destroying insects (WDI) Previous Roof Repairs Previous Other Structural Repairs Previous Use of Premises for Manufacture of Methamphetamine (TXR-1406) 09-01-19  Initialed by: Buyer:	If the answer to any of the	·•	انتا اس ۵۰	<u> </u>				Щ.		<u> </u>		Щ.
Condition Aluminum Wiring Asbestos Components Diseased Trees: oak wilt Endangered Species/Habitat on Property Fault Lines Improper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Improvements encroaching on others' property Located in Historic District Historic Property Designation Previous Roof Repairs Previous Other Structural Repairs  Previous Underground Storage Tanks Underground St	in the answer to any or the	items	ın Se	ection 2 is ye	s, ex	plain (a	attach additi	onai	l sheet	s if necessary):		
Condition Aluminum Wiring Asbestos Components Diseased Trees: oak wilt Endangered Species/Habitat on Property Fault Lines Improper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Improvements encroaching on others' property Located in Historic District Historic Property Designation Previous Roof Repairs Previous Other Structural Repairs  Previous Underground Storage Tanks Underground St									·			
Condition Aluminum Wiring Asbestos Components Diseased Trees: oak wilt Endangered Species/Habitat on Property Fault Lines Improper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Improvements encroaching on others' property Located in Historic District Historic Property Designation Previous Roof Repairs Previous Other Structural Repairs  Previous Underground Storage Tanks Underground St			<del>-</del>									
Condition Aluminum Wiring Asbestos Components Diseased Trees: oak wilt Endangered Species/Habitat on Property Fault Lines Improper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Improvements encroaching on others' property Located in Historic District Historic Property Designation Previous Roof Repairs Previous Other Structural Repairs  Previous Underground Storage Tanks Underground St	Section 3 Are you (Salle	\										——
Condition  Aluminum Wiring Asbestos Components Diseased Trees: oak wilt Endangered Species/Habitat on Property Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property Located in Historic District Historic Property Designation Previous Roof Repairs Previous Other Structural Repairs Initialed by: Buyer:  Active infestation of termites or wDI damage needing repair Single Blockable Main Drain in Pool/Hot Tub/Spa*  Page 2 of 6  Condition Radon Gas Settling Soil Movement Subsurface Structure or Pits Unplated Easements Unplated Easements Unplated Easements Unproveded Easements Unrecarded Easements Unre	Voll are not aware !	er) aw	rare c	or any or the	e foll	owing	conditions	? (N	lark Y	es (Y) if you are aware and	No (	N) if
Aluminum Wiring Asbestos Components Diseased Trees: oak wilt Endangered Species/Habitat on Property Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property Located in Historic District Historic Property Designation Previous Foundation Repairs Previous Other Structural Repairs  Previous Use of Premises for Manufacture of Methamphetamine  Initialed by: Buyer:  Activiting  Soil Movement Subsurface Structure or Pits  Subsurface Structure or Pits Underground Storage Tanks Unplatted Easements Unplatted Easements Unplatted Easements Unrecorded					т							
Asbestos Components Diseased Trees: oak wilt Endangered Species/Habitat on Property Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property Located in Historic District Historic Property Designation Previous Foundation Repairs Previous Gother Structural Repairs Previous Use of Premises for Manufacture of Methamphetamine  Settling Soil Movement Subsurface Structure or Pits Underground Storage Tanks Unplatted Easements Unrecorded Easements Unreadements Unreadements Unreadements Unreadements Unreadements Unreadements Unreadements Unreademe					_ <b>Y</b>	N			·		Υ	N
Diseased Trees: oak wilt  Endangered Species/Habitat on Property Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property Located in Historic District Historic Property Designation Previous Foundation Repairs Previous Other Structural Repairs  Previous Use of Premises for Manufacture of Methamphetamine    Soil Movement   Subsurface Structure or Pits					<del>- </del>	<b> </b>						
Endangered Species/Habitat on Property Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property Located in Historic District Historic Property Designation Previous Foundation Repairs Previous Goff Repairs Previous Use of Premises for Manufacture of Methamphetamine  Endangered Species/Habitat on Property Underground Storage Tanks Underground Storage Ta		+		<del></del>		14						1
Fault Lines Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property Located in Historic District Historic Property Designation Previous Foundation Repairs Previous Other Structural Repairs Previous Use of Premises for Manufacture of Methamphetamine  Underground Storage Tanks Unplatted Easements Unrecorded Easements Unrea-formaldehyde Insulation Water Damage Not Due to a Flood Event Wetlands on Property Wood Rot Active infestation of termites or other wood destroying insects (WDI) Previous treatment for termites or WDI Previous termite or WDI damage repaired Previous Fires Termite or WDI damage needing repair Single Blockable Main Drain in Pool/Hot Tub/Spa*  Page 2 of 6			Drone	n erbo		1						
Hazardous or Toxic Waste Improper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property Located in Historic District Historic Property Designation Previous Foundation Repairs Previous Other Structural Repairs  Previous Use of Premises for Manufacture of Methamphetamine  Intermitted Easements Unrea-formaldehyde Insulation Water Damage Not Due to a Flood Event Wetlands on Property Wetlands on Property Active infestation of termites or other wood destroying insects (WDI) Previous treatment for termites or WDI Previous termite or WDI damage repaired Previous Fires Termite or WDI damage needing repair Single Blockable Main Drain in Pool/Hot Tub/Spa*  Page 2 of 6		at OII	Flope	erty	+-	1						~
Improper Drainage Intermittent or Weather Springs Landfill Lead-Based Paint or Lead-Based Pt. Hazards Encroachments onto the Property Improvements encroaching on others' property Located in Historic District Historic Property Designation Previous Foundation Repairs Previous Roof Repairs Previous Other Structural Repairs  Previous Use of Premises for Manufacture of Methamphetamine  Intermittent or Weather Springs Urea-formaldehyde Insulation Water Damage Not Due to a Flood Event Wetlands on Property Wood Rot Active infestation of termites or other wood destroying insects (WDI) Previous treatment for termites or WDI Previous Ermite or WDI damage repaired Previous Other Structural Repairs  Termite or WDI damage needing repair Single Blockable Main Drain in Pool/Hot Tub/Spa*  Page 2 of 6				<del></del> -		<del>                                      </del>						
Intermittent or Weather Springs  Landfill  Lead-Based Paint or Lead-Based Pt. Hazards  Encroachments onto the Property  Improvements encroaching on others' property  Located in Historic District  Historic Property Designation  Previous Foundation Repairs  Previous Roof Repairs  Previous Other Structural Repairs  Previous Use of Premises for Manufacture of Methamphetamine  (TXR-1406) 09-01-19  Initialed by: Buyer:  Initialed by: Buyer:  Urea-formaldehyde Insulation  Water Damage Not Due to a Flood Event  Wetlands on Property  Active infestation of termites or other wood destroying insects (WDI)  Previous treatment for termites or WDI damage repaired  Previous Fires  Termite or WDI damage needing repair  Single Blockable Main Drain in Pool/Hot  Tub/Spa*  Page 2 of 6					-	1						
Lead-Based Paint or Lead-Based Pt. Hazards  Encroachments onto the Property  Encroachments encroaching on others' property  Located in Historic District  Historic Property Designation  Previous Foundation Repairs  Previous Roof Repairs  Previous Other Structural Repairs  Previous Use of Premises for Manufacture of Methamphetamine  (TXR-1406) 09-01-19  Initialed by: Buyer:  Water Damage Not Due to a Flood Event  Wetlands on Property  Wood Rot  Active infestation of termites or other wood destroying insects (WDI)  Previous treatment for termites or WDI damage repaired  Previous Fires  Termite or WDI damage needing repair  Single Blockable Main Drain in Pool/Hot  Tub/Spa*  Page 2 of 6		inge			+	1	**·					
Lead-Based Paint or Lead-Based Pt. Hazards  Encroachments onto the Property Improvements encroaching on others' property  Located in Historic District Historic Property Designation Previous Foundation Repairs Previous Roof Repairs Previous Other Structural Repairs  Previous Use of Premises for Manufacture of Methamphetamine  Wetlands on Property Wood Rot Active infestation of termites or other wood destroying insects (WDI) Previous treatment for termites or WDI Previous termite or WDI damage repaired Previous Fires Termite or WDI damage needing repair Single Blockable Main Drain in Pool/Hot Tub/Spa*  Page 2 of 6		iiiga			<del>- </del> -	+						
Improvements onto the Property Improvements encroaching on others' property  Located in Historic District Historic Property Designation Previous Foundation Repairs Previous Roof Repairs Previous Other Structural Repairs  Previous Use of Premises for Manufacture of Methamphetamine  (TXR-1406) 09-01-19  Initialed by: Buyer:  Wood Rot Active infestation of termites or other wood destroying insects (WDI) Previous treatment for termites or WDI Previous termite or WDI damage repaired Previous Fires Termite or WDI damage needing repair Single Blockable Main Drain in Pool/Hot Tub/Spa*  Page 2 of 6		Racoo	1 Dt L	Jazarda			water Da	ma	ge Not	Due to a Flood Event		V
Improvements encroaching on others' property  Located in Historic District Historic Property Designation Previous Foundation Repairs Previous Roof Repairs Previous Other Structural Repairs  Previous Use of Premises for Manufacture of Methamphetamine  (TXR-1406) 09-01-19  Active infestation of termites or other wood destroying insects (WDI)  Previous treatment for termites or WDI Previous termite or WDI damage repaired  Previous Fires  Termite or WDI damage needing repair  Single Blockable Main Drain in Pool/Hot Tub/Spa*  Page 2 of 6				lazaius		+-						
Located in Historic District Historic Property Designation Previous Foundation Repairs Previous Roof Repairs Previous Other Structural Repairs  Previous Use of Premises for Manufacture of Methamphetamine    Additional Company of Methamphetamine				property.	<b></b> _				4:			<u> </u>
Located in Historic District Historic Property Designation Previous Foundation Repairs Previous Roof Repairs Previous Other Structural Repairs Previous Use of Premises for Manufacture of Methamphetamine  Previous treatment for termites or WDI Previous termite or WDI damage repaired Previous Fires Termite or WDI damage needing repair Single Blockable Main Drain in Pool/Hot Tub/Spa*  Page 2 of 6	mpro remente entereuening	011 00	11613	property								1 ,
Historic Property Designation  Previous Foundation Repairs  Previous Roof Repairs  Previous Other Structural Repairs  Previous Use of Premises for Manufacture of Methamphetamine  (TXR-1406) 09-01-19  Initialed by: Buyer:  A Previous termite or WDI damage repaired  Previous Fires  Termite or WDI damage needing repair  Single Blockable Main Drain in Pool/Hot  Tub/Spa*  Page 2 of 6	Located in Historic District			<del></del>								
Previous Foundation Repairs  Previous Roof Repairs  Previous Other Structural Repairs  Previous Use of Premises for Manufacture of Methamphetamine  Previous Fires  Termite or WDI damage needing repair  Single Blockable Main Drain in Pool/Hot  Tub/Spa*  Page 2 of 6						1						V
Previous Roof Repairs  Previous Other Structural Repairs  Previous Use of Premises for Manufacture of Methamphetamine  (TXR-1406) 09-01-19  Initialed by: Buyer: and Seller:										WDI damage repaired		1
Previous Other Structural Repairs  Previous Use of Premises for Manufacture of Methamphetamine  (TXR-1406) 09-01-19  Initialed by: Buyer: and Seller: Page 2 of 6			<del></del>		+-							
Previous Use of Premises for Manufacture of Methamphetamine  (TXR-1406) 09-01-19 Initialed by: Buyer: and Seller: Page 2 of 6		enaire				~	Cincle O	r VV	UI dam	nage needing repair		<u>  '~</u>
Previous Use of Premises for Manufacture of Methamphetamine  (TXR-1406) 09-01-19 Initialed by: Buyer: and Seller: Page 2 of 6		opans	9					CKa	ible Ma	ain Drain in Pool/Hot		1. /
of Methamphetamine (TXR-1406) 09-01-19 Initialed by: Buyer: and Seller: Page 2 of 6	Previous Use of Premises for	or Ma	nufac	ture	+-	+	Tub/Spa		·			<u></u>
Page 2 of 6	of Methamphetamine	:VICI										
Page 2 of 6	(TVP 1406) 00 04 40		. 22			·				al		
	•							ller:	_ <u></u>	P	age 2	of 6

Concerni	ng the Property at	16007 CR 228 Bedias, TX 77831
If the ans	wer to any of the items in Se	ction 3 is yes, explain (attach additional sheets if necessary):
		use a suction entrapment hazard for an individual.
***************************************	a mar machi bigalandisia dis	f any item, equipment, or system in or on the Property that is in need of repactors of the closed in this notice?yesno If yes, explain (attach additional sheets
Section 5 wholly or	. Are you (Seller) aware o partly as applicable. Mark	f any of the following conditions?* (Mark Yes (Y) if you are aware and check No (N) if you are not aware.)
	Present flood insurance co	overage (if yes, attach TXR 1414).
		a failure or breach of a reservoir or a controlled or emergency release
	Previous flooding due to a	natural flood event (if yes, attach TXR 1414).
iZ	Previous water penetratio TXR 1414).	n into a structure on the Property due to a natural flood event (if yes, attac
_ ∠	Located wholly par AH, VE, or AR) (if yes, atta	tly in a 100-year floodplain (Special Flood Hazard Area-Zone A, V, A99, AE A0 ch TXR 1414).
_ <	Located wholly par	tly in a 500-year floodplain (Moderate Flood Hazard Area-Zone X (shaded)).
	Located wholly par	tly in a floodway (if yes, attach TXR 1414).
/	Located wholly par	
	Located wholly part	tly in a reservoir.
If the answ	er to any of the above is yes	, explain (attach additional sheets as necessary):
	rposes of this notice:	
************	acongriated as Eurie A. V. As	of land that: (A) is identified on the flood insurance rate map as a special flood hazard area 9, AE, AO, AH, VE, or AR on the map; (B) has a one percent annual chance of flooding flooding; and (C) may include a regulatory floodway, flood pool, or reservoir.
"500-ye area, w	ar floodplain" means any area	of land that: (A) is identified on the flood insurance rate map as a moderate flood hazar as Zone X (shaded): and (B), has a two-tenths of one percent appeal shapes of the dis-
"Flood <sub>l</sub> subject	oool" means the area adjacent to to controlled inundation under th	o a reservoir that lies above the normal maximum operating level of the reservoir and that in the management of the United States Army Corps of Engineers.
"Flood i under ti	nsurance rate map" means the ne National Flood Insurance Act	most recent flood hazard map published by the Federal Emergency Management Agenc of 1968 (42 U.S.C. Section 4001 et seq.).
as a 10	D-year flood, without cumulatively	ified on the flood insurance rate map as a regulatory floodway, which includes the channe adjacent land areas that must be reserved for the discharge of a base flood, also referred to y increasing the water surface elevation more than a designated height.
"Reserv		nt project operated by the United States Army Corps of Engineers that is intended to make
TXR-1406)		by: Buyer:, and Seller:,Page 3 of 6

Produced with Lone Wolf Transactions (zipForm Edition) 231 Shearson Cr. Cambridge, Ontario, Canada N1T 1J5 www.twolf.com

Rodriguez,

Concernin	ng the Property at
p ,	5. Have you (Seller) ever filed a claim for flood damage to the Property with any insurance including the National Flood Insurance Program (NFIP)?*yesno If yes, explain (attach addition necessary):
	es in high risk flood zones with mortgages from federally regulated or insured lenders are required to have flood insurance when not required, the Federal Emergency Management Agency (FEMA) encourages homeowners in high risk, modera and low risk flood zones to purchase flood insurance that covers the structure(s) and the personal property within the personal pro
Administr	. Have you (Seller) ever received assistance from FEMA or the U.S. Small Busines ration (SBA) for flood damage to the Property?yesno If yes, explain (attach additional sheets a /):
Section 8 not aware	. Are you (Seller) aware of any of the following? (Mark Yes (Y) if you are aware. Mark No (N) if you ar
<u>Y N</u>	Room additions, structural modifications, or other alterations or repairs made without necessary permits, with unresolved permits, or not in compliance with building codes in effect at the time.
	Homeowners' associations or maintenance fees or assessments. If yes, complete the following:  Name of association:
	Manager's name:
	Fees or assessments are: \$ per and are: mandatory voluntary
_	Manager's name: Phone: Fees or assessments are: \$ per and are: mandatory voluntary Any unpaid fees or assessment for the Property? yes (\$) no If the Property is in more than one association, provide information about the other associations below or attach information to this notice.
	Any common area (facilities such as pools, tennis courts, walkways, or other) co-owned in undivided interest with others. If yes, complete the following:  Any optional user fees for common facilities observed?
	Any optional user fees for common facilities charged?yesno If yes, describe:
	Any notices of violations of deed restrictions or governmental ordinances affecting the condition or use of the Property.
	Any lawsuits or other legal proceedings directly or indirectly affecting the Property. (Includes, but is not limited to: divorce, foreclosure, heirship, bankruptcy, and taxes.)
	Any death on the Property except for those deaths caused by: natural causes, suicide, or accident unrelated to the condition of the Property.
	Any condition on the Property which materially affects the health or safety of an individual.
	Any repairs or treatments, other than routine maintenance, made to the Property to remediate environmental hazards such as asbestos, radon, lead-based paint, urea-formaldehyde, or mold.  If yes, attach any certificates or other documentation identifying the extent of the remediation (for example, certificate of mold remediation or other remediation).
_ 🗹	Any rainwater harvesting system located on the Property that is larger than 500 gallons and that uses a public water supply as an auxiliary water source.
	The Property is located in a propane gas system service area owned by a propane distribution system retailer.
	Any portion of the Property that is located in a groundwater conservation district or a subsidence district.
f the answe	er to any of the items in Section 8 is yes, explain (attach additional sheets if necessary):

\_\_\_, \_\_\_\_ and Seller: <u>C</u>^\_

Produced with Lone Wolf Transactions (zipForm Edition) 231 Shearson Cr. Cambridge, Ontario, Canada N1T 1J5 www.lwolf.com

Page 4 of 6

(TXR-1406) 09-01-19

Initialed by: Buyer: \_\_\_

Concerning the Property at		16007 CR 228 Bedias, TX 77831	
Section 9. Seller has	nas not attached a surve	of the Property.	
Section 10. Within the last persons who regularly propermitted by law to perform in	VICIE INSPECTIONE SNA	Who are sither lissues of	
Inspection Date Type	Name of Inspe	ctor	No. of Pages
Note: A buyer should not re A buye	ely on the above-cited repo	rts as a reflection of the curren from inspectors chosen by the	t condition of the Property.
Section 11. Check any tax exe			
✓ Homestead	Senior Citizen	Disab	
<ul><li>Homestead</li><li>Wildlife Management</li><li>Other:</li></ul>	Agricultural	Disab	led Veteran
			24411
Section 12. Have you (Seller) insurance provider? yes <a href="Yes">Yes</a>			

Rodriguez,

## 16007 CR 228 Bedias, TX 77831

## **ADDITIONAL NOTICES TO BUYER:**

- (1) The Texas Department of Public Safety maintains a database that the public may search, at no cost, to determine if registered sex offenders are located in certain zip code areas. To search the database, visit <a href="https://publicsite.dps.texas.gov/SexOffenderRegistry">https://publicsite.dps.texas.gov/SexOffenderRegistry</a>. For information concerning past criminal activity in certain areas or neighborhoods, contact the local police department.
- (2) If the Property is located in a coastal area that is seaward of the Gulf Intracoastal Waterway or within 1,000 feet of the mean high tide bordering the Gulf of Mexico, the Property may be subject to the Open Beaches Act or the Dune Protection Act (Chapter 61 or 63, Natural Resources Code, respectively) and a beachfront construction certificate or dune protection permit may be required for repairs or improvements. Contact the local government with ordinance authority over construction adjacent to public beaches for more information.
- (3) If the Property is located in a seacoast territory of this state designated as a catastrophe area by the Commissioner of the Texas Department of Insurance, the Property may be subject to additional requirements to obtain or continue windstorm and hail insurance. A certificate of compliance may be required for repairs or improvements to the Property. For more information, please review *Information Regarding Windstorm and Hail Insurance for Certain Properties* (TXR 2518) and contact the Texas Department of Insurance or the Texas Windstorm Insurance Association.
- (4) This Property may be located near a military installation and may be affected by high noise or air installation compatible use zones or other operations. Information relating to high noise and compatible use zones is available in the most recent Air Installation Compatible Use Zone Study or Joint Land Use Study prepared for a military installation and may be accessed on the Internet website of the military installation and of the county and any municipality in which the military installation is located.
- (5) If you are basing your offers on square footage, measurements, or boundaries, you should have those items independently measured to verify any reported information.

(6) The following providers currently provide service to the Property:	
Electric: Blue Bonnet  Sewer: KB Septic  Water: Man Water Wall  Cable: Breet/  Trash: WIA  Natural Gas: MIA  Phone Company: MIN	phone #: <u>934 &amp; 25 5166</u> phone #: <u>934 324 2428</u> phone #: <u>934 348 5838</u> phone #:  phone #:  phone #:  phone #:
Propane: NIA	phone #:
Internet: Vic Set / Blee Branet leaving Seen	phone #:
(7) This Seller's Disclosure Notice was completed by Seller as of the date as true and correct and have no reason to believe it to be false or inac AN INSPECTOR OF YOUR CHOICE INSPECT THE PROPERTY.	signed. The brokers have relied on this notice courate. YOU ARE ENCOURAGED TO HAVE
The undersigned Buyer acknowledges receipt of the foregoing notice.	

Signature of Buyer Date

Printed Name:

Printed Name:

(TXR-1406) 09-01-19 Initialed by: Buyer: \_\_\_\_\_, and Seller: \_\_\_\_\_, Page 6 of 6

Produced with Lone Wolf Transactions (zipForm Edition) 231 Shearson Cr. Cambridge, Ontario, Canada N1T 1J5 www.lwolf.com



INFORMATION ABOUT ON-SITE SEWER FACILITY
USE OF THIS FORM BY PERSONS WHO ARE NOT MEMBERS OF THE TEXAS ASSOCIATION OF REALTORS®, INC. IS NOT AUTHORIZED.
©Texas Association of REALTORS®, Inc., 2004

C	CONCERNING THE PROPERTY AT	16007 CR 228 Bedias, TX 77831	
A	A. DESCRIPTION OF ON-SITE SEWER FAC		
	(1) Type of Treatment System: Septic	Tank Aerobic Treatment	Unknown
	(2) Type of Distribution System:		— ☐ Unknown
	(3) Approximate Location of Drain Field or	Distribution System:	
	(2) Septic on shop 100	Steptie Acrobic	<u> </u>
	(4) Installer: KB Septice S	ystem	Unknown
	(5) Approximate Age:		_ Unknown
В.			
	if yes, name of maintenance contractor:	intract in effect for the on-site sewer facility?	
	Phone:	ct to operate aerobic treatment and certain non	
	(2) Approximate date any tanks were last p	pumped? New System on the	اننجر
	(3) Is Seller aware of any defect or malfunc	ction in the on-site sewer facility?	
C.	(4) Does Seller have manufacturer or warra . PLANNING MATERIALS, PERMITS, AND		☑Yes □ No
	(1) The following items concerning the on-sing planning materials permit for original		SSF was installed
	(2) "Planning materials" are the supportin submitted to the permitting authority in o	ng materials that describe the on-site sewe order to obtain a permit to install the on-site se	r facility that are wer facility.
		to have the permit to operate an on-si	
(TX	XR-1407) 1-7-04 Initialed for Identification by	oy Buyer, and Seller <u>(</u> ←L,	Page 1 of 2
	zos Land Company, 116 S Main St Anderson TX 77830	Phone: 9795741857 Fax: 93687323 ipForm Edition) 231 Shearson Cr. Cambridge, Ontario, Canada N1T 1J5 www.lwoli	

D. INFORMATION FROM GOVERNMENTAL AGENCIES: Pamphlets describing on-site sewer facilities are available from the Texas Agricultural Extension Service. Information in the following table was obtained from Texas Commission on Environmental Quality (TCEQ) on 10/24/2002. The table estimates daily wastewater usage rates. Actual water usage data or other methods for calculating may be used if accurate and acceptable to TCEQ.

<u>Facility</u>	Usage (gal/day) without water- saving devices	Usage (gal/day) with water- saving devices
Single family dwelling (1-2 bedrooms; less than 1,500 sf)	225	400
Single family dwelling (3 bedrooms; less than 2,500 sf)	<del>-</del>	180
Single family divelling (4 but	300	240
Single family dwelling (4 bedrooms; less than 3,500 sf)	375	300
Single family dwelling (5 bedrooms; less than 4,500 sf)	450	360
Single family dwelling (6 bedrooms; less than 5,500 sf)	525	420
Mobile home, condo, or townhouse (1-2 bedroom)	225	180
Mobile home, condo, or townhouse (each add'l bedroom)	75	60

This document is not a substitute for any inspections or warranties. This document was completed to the best of Seller's knowledge and belief on the date signed. Seller and real estate agents are not experts about on-site sewer facilities. Buyer is encouraged to have the on-site sewer facility inspected by an inspector of Buyer's choice.

Signature of Seller Gabriel Rodriguez II	SIIE i ze य Date	Signature of Seller Carrie Rodriguez	05/18/2021 Date
Receipt acknowledged by:			
Signature of Buyer	Date	Signature of Buyer	Date

(TXR-1407) 1-7-04

Page 2 of 2