## Hampshire County Health Department HC 71, Box 9 Augusta, WV 26704

(304) 496-9640 Fax: (304) 496-9650

August 2,2006

Hampshire County Planning Commission P. O. Box 883 Romney, WV 26757

Dear sirs;

This office has reviewed a plat of survey for Robert Williams to approve a subdivision located on Dillons Run Road called Quaker Lake Section (I, and further referenced as Tax District 02, Tax Map 018, Parcel 003, Deed book 210, Page 420. This subdivision contains 63.237 acres and consists of 16 lots.. All lots require a percolation test and a sewage disposal area of 10,000 square feet where no development or structures other than the septic system shall be permitted. These lots are to be developed with individual wells and septic systems to serve a single family dwellings.

Percolation test results are within limits as set forth by West Virginia CSR 16-1. Six foot soil observation holes indicate no restrictions due to water table or shallow bedrock within the designated sewage disposal area except as noted on the Health Department subdivision application.

The plat of survey dated 06/01/2006 is hereby approved by the Hampshire County Health Department. Any changes or revisions to the Health Department stamped and signed plat, or subsequent final plats approved based upon the approved plat, will make this approval null and void.

This approval is not a permit for individual water systems or individual sewer systems. Applications for permits must be made separately to the Hampshire County Health Department.

Sincerely, Jim Kinder R.S.

cc: Robert Williams

## PERCOLATION AND SIX FOOT HOLE TESTING

Total N	umber 0	ne Quaker Lake Section  f Lots 12 Name of Applicant 1	tobe	county <u>Nan</u> NR L	Silliam.		*
Name o	f Certific	ed Installer Responsible for Testing Bo	D	11 /		· 18832 - Will	
	- 9	Installer Signatu	re /	y coo.	- fre	Haristu	Efi
ន	*	Address RRI,	Borz	9 1 ~ 2, As	gusto Li	26764	<i>V.</i>
/Puna	Lot		Average	Six Foot Hole Results		Date Conducted	
Type System	Number	Percolation Test Results (Minutes per Inch of Fall)	Results	Depth to Water	Depth to Rock	6-28-05	

						Average	Six Foot Hole Results		Date
Type	Lot Number	Dareniation	Test Results	Minutes per	nch of Fall)	Results	Depth to Water	Depth to Rock	Conducted
System	Numer	127	167	าร	42	19	6	61	6-38-0
an	2	-1.	118	90	120	223	6!	60	· (1
25	3	140	70	192	154	27.5	6	6'	11
<u> </u>	4	126	7.8	9)	143	182	6	61	· lı
		133	80	1/37	68	15.75	- b!	61	6-30-0
	- 5	-	120	95	183	194	6'	6'	. 10
	()	69	143	100	1172	73.R	6'	6'	5-26-6
	7	138	109	86	40	17.9	7	61	6-30-0
		145	168	103	114	23.5	61	6'	5-26-
<u>u</u>	100 To 100	128	83	76	64	13	Maria Contract	6'	7-5-
<u> I</u>	to	$\mathcal{M}_{-}$	5 10 35 ch 4 12 5	7)	90	14.9	41	6'	14.
<u> II</u> :	127 .	<u> </u>	68	3	724	เร	6'	b. 64.	и
LL.	12	96	D.I	10//	- CX - S			Virgin 2	
<u> </u>				14/0			There is executed		<b> -</b> :
		-	Hazingorf	-	West On	F (2.0.36)		ara -	
	<u></u>			+					<u> </u>
		ļ.,				(A)		1 1 1 1 1	
i.			<u> </u>	38-7			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
	*.	99.44		4-17-	-	17.	<u> </u>	+	<del>                                     </del>
		* 1			est to the second	<u> </u>		<b>-</b> ""	
		1	i		1 1 1 1	ें ।	J	<u> </u>	ــــــــــــــــــــــــــــــــــــــ

(Attach additional pages if needed)