

STATE OF TEXAS WELL REPORT for Tracking #437629

Owner: **Stephen Ochsner**

Owner Well #: **No Data**

Address: **522 Texas Point
San Antonio , TX 78260**

Grid #: **56-15-6**

Well Location: **1.2 Mi. N. of Old Pontotoc Rd. on Cow
Creek Rd.; .3 mi. E. in pasture
Mason, TX**

Latitude: **30° 47' 35" N**

Longitude: **099° 09' 31" W**

Well County: **Mason**

Elevation: **No Data**

Type of Work: **New Well**

Proposed Use: **Domestic**

Drilling Start Date: **11/18/2016** Drilling End Date: **11/18/2016**

	<i>Diameter (in.)</i>	<i>Top Depth (ft.)</i>	<i>Bottom Depth (ft.)</i>
Borehole:	9.75	0	22
	6.75	22	23
	6	23	120

Drilling Method: **Air Hammer**

Borehole Completion: **Open Hole**

	<i>Top Depth (ft.)</i>	<i>Bottom Depth (ft.)</i>	<i>Description (number of sacks & material)</i>
Annular Seal Data:	0	3	Cement 1 Bags/Sacks
	3	22	Bentonite 4 Bags/Sacks

Seal Method: **Poured**

Distance to Property Line (ft.): **No Data**

Sealed By: **Driller**

Distance to Septic Field or other
concentrated contamination (ft.): **No Data**

Distance to Septic Tank (ft.): **No Data**

Method of Verification: **No Data**

Surface Completion: **Surface Sleeve Installed**

Water Level: **44 ft. below land surface on 2016-11-18**

Packers: **No Data**

Type of Pump: **Submersible**

Pump Depth (ft.): **100**

Well Tests: **Jetted** **Yield: 10 GPM**

Water Quality:

<i>Strata Depth (ft.)</i>	<i>Water Type</i>
82	Good (400ppmTDS)
84	Good (400ppmTDS)

Chemical Analysis Made: **No**

Did the driller knowingly penetrate any strata which
contained injurious constituents?: **No**

Certification Data: The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the report(s) being returned for completion and resubmittal.

Company Information: **Virdell Drilling Inc.**

**111 E. Grayson St.
Llano, TX 78643**

Driller Name: **James Caleb Virdell**

License Number: **59342**

Comments: **Open Hole: 23 - 120**

Lithology:
DESCRIPTION & COLOR OF FORMATION MATERIAL

Casing:
BLANK PIPE & WELL SCREEN DATA

<i>Top (ft.)</i>	<i>Bottom (ft.)</i>	<i>Description</i>
0	1	Topsoil
1	9	Brown Clay & Gravel
9	120	Red & Black Metamorphic

<i>Dia (in.)</i>	<i>Type</i>	<i>Material</i>	<i>Sch./Gage</i>	<i>Top (ft.)</i>	<i>Bottom (ft.)</i>
6		New Plastic (PVC)	Sch40	-3	23

IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

**Texas Department of Licensing and Regulation
P.O. Box 12157
Austin, TX 78711
(512) 463-7880**