STATE OF TEXAS WELL REPORT for Tracking #578600					
Owner:	Scott Patterson	Owner Well #:	No Data		
Address:	200 FM 3023 Goldthwaite, TX  76844	Grid #:	41-36-5		
Well Location:	200 FM 3023	Latitude:	31° 25' 37" N		
	Goldthwaite, TX 76844	Longitude:	098° 34' 54" W		
Well County:	Mills	Elevation:	1450 ft. above sea level		
Type of Work:	New Well	Proposed Use:	Domestic		

Drilling Start Date: 6/28/2021 Drilling End Date: 6/28/2021

	Diameter (in.	) Top De	oth (ft.)	Bottom Depth (ft.)
Borehole:	8.75	C	I	12
	6.25	1:	2	205
Drilling Method:	Air Rotary			
Borehole Completion:	Straight Wall			
	Top Depth (ft.)	Bottom Depth (ft.) Description (number of sac		escription (number of sacks & material)
Annular Seal Data:	0	12	Cement 4 Bags/Sacks	
Seal Method: Po	oured	Dis	tance to P	roperty Line (ft.): 100+
Sealed By: D			tic Field or other ntamination (ft.): <b>NA</b>	
		C	istance to	Septic Tank (ft.): <b>NA</b>
			Metho	od of Verification: No Data
Surface Completion:	Surface Sleeve Installed		Surface Completion by Driller	
Water Level:	119 ft. below lan	d surface on <b>2021-06</b> -	28	
Packers:	Rubber at 12 ft. Rubber at 140 ft			
Type of Pump:	No Data			
Well Tests:	Jetted	Yield: 12 GPM		

	Strata Depth (ft.)	Water Type		
Water Quality:	No Data	No Data		
		Chemical Analysis	Made: No	
	Did the driller	knowingly penetrate any strata contained injurious constitu		
Certification Data:	driller's direct superv correct. The driller u	nat the driller drilled this well (or ision) and that each and all of th nderstood that failure to comple eturned for completion and resul	ne statements he ete the required i	erein are true and
Certification Data: Company Information:	driller's direct superv correct. The driller u the report(s) being re	ision) and that each and all of the nderstood that failure to complete	ne statements he ete the required i	erein are true and
	driller's direct superv correct. The driller u the report(s) being re	ision) and that each and all of the nderstood that failure to complete aturned for completion and resul	ne statements he ete the required i	erein are true and
	driller's direct superv correct. The driller u the report(s) being re ALDERSON WATE PO BOX 366	ision) and that each and all of th nderstood that failure to comple eturned for completion and resul ER WELL RESCUE, LLC	ne statements he ete the required i	erein are true and

## Lithology: DESCRIPTION & COLOR OF FORMATION MATERIAL

Top (ft.)	Bottom (ft.)	Description
0	24	Overburden
24	36	Brown Sandstone
36	48	Red Sandstone
48	76	Red Conglomerate
76	88	Red Sandstone
88	96	Red/Tan Sandstone
96	130	Pink Sandstone
130	144	Tan Sandstone
144	164	Brown/Pink Lime
164	198	Tan Limestone
198	205	Red Sandstone

## Casing: BLANK PIPE & WELL SCREEN DATA

Dla (in.)	Туре	Material	Sch./Gage	Top (ft.)	Bottom (ft.)
4.5	Blank	New Plastic (PVC)	SDR-17	0	145
4.5	Screen	New Plastic (PVC)	SDR-17 0.020	145	205

## IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

Texas Department of Licensing and Regulation P.O. Box 12157 Austin, TX 78711 (512) 334-5540