

STATE OF TEXAS WELL REPORT for Tracking #568941

Owner:	Aaron Knirr	Owner Well #:	No Data
Address:	14900 Copper Ridge Lane Austin, TX 78734	Grid #:	57-33-7
Well Location:	503 Ruger Road Fredericksburg, TX	Latitude:	30° 24' 27.28" N
Well County:	Gillespie	Longitude:	098° 57' 46.56" W
Number of Wells Drilled:	2	Elevation:	No Data

Type of Work:	New Well	Proposed Use:	Domestic
---------------	-----------------	---------------	-----------------

Drilling Start Date: **3/16/2021** Drilling End Date: **3/16/2021**

Borehole:	<i>Diameter (in.)</i>	<i>Top Depth (ft.)</i>	<i>Bottom Depth (ft.)</i>
	9	0	50
	6.75	50	160

Drilling Method: **Air Rotary**

Borehole Completion: **Straight Wall**

Annular Seal Data:	<i>Top Depth (ft.)</i>	<i>Bottom Depth (ft.)</i>	<i>Description (number of sacks & material)</i>
	-2	5	Cement 2 Bags/Sacks
	5	50	Bentonite 11 Bags/Sacks

Seal Method: **Pressure**

Sealed By: **Driller**

Distance to Property Line (ft.): **75+**

Distance to Septic Field or other
concentrated contamination (ft.): **No Data**

Distance to Septic Tank (ft.): **No Data**

Method of Verification: **No Data**

Surface Completion:	Surface Sleeve Installed	Surface Completion by Driller
---------------------	---------------------------------	--------------------------------------

Water Level: **103 ft. below land surface on 2021-03-16** Measurement Method: **Steel Tape**

Packers: **Rubber at 50 ft.**

Type of Pump: **No Data**

Well Tests: **Jetted** **Yield: 10 GPM**

Water Quality:

<i>Strata Depth (ft.)</i>	<i>Water Type</i>
118 - 122	No Data

Chemical Analysis Made: **No**

Did the driller knowingly penetrate any strata which
contained injurious constituents?: **No**

Certification Data: The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the report(s) being returned for completion and resubmittal.

Company Information: **Magill Drilling & Water Well Service, LLC**
PO Box 46
Castell, TX 76831

Driller Name: **Zane Magill**

License Number: **4168**

Comments: **No Data**

Lithology:
DESCRIPTION & COLOR OF FORMATION MATERIAL

<i>Top (ft.)</i>	<i>Bottom (ft.)</i>	<i>Description</i>
0	1	Topsoil
1	160	White Lime W/ Clay Streaks

Casing:
BLANK PIPE & WELL SCREEN DATA

<i>Dia (in.)</i>	<i>Type</i>	<i>Material</i>	<i>Sch./Gage</i>	<i>Top (ft.)</i>	<i>Bottom (ft.)</i>
4.5	Blank	New Plastic (PVC)	40	-2	140
4.5	Perforated or Slotted	New Plastic (PVC)	40 0.020	140	160

IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

Texas Department of Licensing and Regulation
P.O. Box 12157
Austin, TX 78711
(512) 334-5540