	TO:	Hardy County Health Department, Moorefield, W.V.
	FROM:	Name Hunter Co. of WV Phone 1-304 262-2770
		Address 1800 West King St. Mortins WU 25401
	RE:	Property Location Ashton Woods Sub.
	of the	Request is hereby made for a site investigation to determine the suitabili subject property as a site for the small sawage system indicated below:
	(+ se	ptic System ( ) Pit Privy ( ) Vault Privy ( ) Other Non 4
	requir	The results of a percolation test conducted in accordance with the ements of Design Standards for Small Septic Tank Systems follows:
		Depth of test holes: #124, #224, #324, #424 inches.
	t	Time for water to fall 6 inches in test hole $\#1$ /80 minutes $\#2$ /80 $\#3$ 210
My My	0	Lot 314 #3 210 #4 240 Minutes.
HOD 19	provid	A test hole bored or dug 6 feet deep ( ) has ( ) has not been ed to help determine the depth to bedrock and ground water table.
P	proper test ho	On the back of this form a plot layout has been sketched showing the ty lines and relative locations of buildings, water supplies, percolation ples, six ft. hole, and other pertinent features.
	of this	I (we), the undersigned, certify that the information contained herein is t and accurate to the best of my (our) knowledge. It is further understood his form is not an application for a permit, and subsequent acceptance is site by the designated health dept. does not constitute a permit to a sewage system.
	Owner's	s signature Aut Wilsu Date 7-16-04
		stion test conducted by: Name Billy G. HArt
		Address Rt 1 Box 163AZ Paw Paw WU 25
	Date	2-16-04 Signature Billy A. Hout
		FOR HEALTH DEPT. USE DNLY
	Basad o	This is to certify that the Hardy County Health Department reviewed tents of this form and conducted a site visit on subject property. In the information provided it is the opinion of the undersigned that te is ( ) is not suitable for the installation of the small sewage indicated.
	Signntu	re Wille Ow Date 8-13-04