Note: Survey is certified for this transaction only. The findings and opinions of Texas Professional Surveying, LLC, reflected herein are privileged, confidential and intended for the use of the individual or entity for whom the work was prepared. It is understood that the use of, reliance on, or reproduction of same, in whole or in part, by others without the express written consent of Texas Professional Surveying, LLC, is prohibited and without warranty, express or implied. Texas Professional Surveying, LLC, shall be held harmless against damages or expenses resulting from such unauthorized use, reliance or reproduction. Copyright 2016. All rights reserved.

CURVE	DELTA	RADIUS	LENGTH	CHORD BEARING	CHORD LENGTH
C1	11°08'12"	1972.41'	383.41'	S 14°45'32" E	382.79'
C2	11°08'12"	1972.41'	383.41'	S 14°45'32" E	382.79'
C3	11°08'12"	1972.41'	383.41'	S 14°45'32" E	382.79'