STATE OF TEXAS WELL REPORT for Tracking #659163					
Owner:	CamDu, LLC	Owner Well #:	No Data		
Address:	140 W South Loop Stephenville, TX 76401	Grid #:	31-38-4		
Well Location:	CR 121	Latitude:	32° 25' 39.89" N		
	Mingus, TX 76463	Longitude:	098° 20' 34.07" W		
Well County:	Erath	Elevation:	1209 ft. above sea level		
Type of Work:	New Well	Proposed Use:	Domestic		

Drilling Start Date: 11/7/2023 Drilling End Date: 11/7/2023

	Diameter	(in.)	Top Depth (ft.)	Bottom Depth	(ft.)
Borehole:	7.875		0	200	
Drilling Method:	Air Rotary				
Borehole Completion:	Filter Packed				
	Top Depth (ft.)	Bottom Depth (ft.)	Filter	Material	Size
Filter Pack Intervals:	12	200	Gra	avel	.25
	Top Depth (ft.)	Bottom Depth (i	ft.) De	escription (number of sacl	ks & material)
Annular Seal Data:	0	12	12 Cement 3 B		Sacks
Seal Method: Po	oured		Distance to P	roperty Line (ft.): 50	+
Sealed By: Dr		Distance to Septic Field or other concentrated contamination (ft.): 100+			
			Distance to	Septic Tank (ft.): 50	+
			Metho	od of Verification: WI	heel
Surface Completion:	Surface Sleeve	e Installed	S	urface Completion	by Driller
Water Level:	No Data				
Packers:	No Data				
Type of Pump:	Submersible		Ρι	ump Depth (ft.): 180)
Type of Fullip.					

_

	Strata Depth (ft.)	Water Type		
Water Quality:	15 - 180	Fresh	_	
		Chemical Analysis Mad	e: No	
	Did the driller kr	nowingly penetrate any strata whic contained injurious constituents		
Certification Data:	driller's direct supervisi correct. The driller und	the driller drilled this well (or the von) and that each and all of the states derstood that failure to complete the the states of the states the states of	atements he e required it	rein are true and
Certification Data:	driller's direct supervisi correct. The driller und the report(s) being retu	on) and that each and all of the sta lerstood that failure to complete th	atements he e required it	rein are true and
	driller's direct supervisi correct. The driller und the report(s) being retu	on) and that each and all of the sta lerstood that failure to complete th irned for completion and resubmitt	atements he e required it	rein are true and
	driller's direct supervisi correct. The driller und the report(s) being retu Moore's Water Well 3633 S HWY 281	on) and that each and all of the sta lerstood that failure to complete th irned for completion and resubmitt X 76067	atements he e required it	rein are true and
Company Information	driller's direct supervisi correct. The driller und the report(s) being retu Moore's Water Well 3633 S HWY 281 MINERAL WELLS, T	on) and that each and all of the sta lerstood that failure to complete th irned for completion and resubmitt X 76067	atements he e required it al.	rein are true and ems will result in

Lithology: DESCRIPTION & COLOR OF FORMATION MATERIAL

Top (ft.)	Bottom (ft.)	Description
0	5	Brown Clay
5	10	Red Clay
10	30	Sandy Multicolored Clay
30	35	Sandstone
35	45	Sand with Multicolored Clay
45	100	Sandstone with Clay Layers
100	180	Sand and Shale Layers
180	200	Shale

Casing: BLANK PIPE & WELL SCREEN DATA

Dla (in.)	Туре	Material	Sch./Gage	Top (ft.)	Bottom (ft.)
4	Blank	New Plastic (PVC)	40	0	140
4	Screen	New Plastic (PVC)	40 0.020	140	160
4	Blank	New Plastic (PVC)	40	160	180
4	Screen	New Plastic (PVC)	40 0.020	180	200

IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

Texas Department of Licensing and Regulation P.O. Box 12157 Austin, TX 78711 (512) 334-5540