## **STATE OF TEXAS WELL REPORT for Tracking #667974** Owner Well #: No Data Owner: **HSW LAND LLC** Grid #: Address: PO BOX 61341 56-28-1 SAN ANGELO, TX 76906 Latitude: 30° 36' 50.11" N Well Location: FM 385 & CR 133 INTERSECTION **TRACT 8** Longitude: 099° 35' 45.34" W London, TX 76854 Elevation: No Data Well County: Kimble Type of Work: New Well Proposed Use: Domestic Drilling Start Date: 6/4/2024 Drilling End Date: 6/4/2024

	Diameter (in.)		Top Depth (ft.)	Bottom Dept	th (ft.)		
Borehole:	8		0	75			
Drilling Method:	Air Rotary						
Borehole Completion:	Filter Packed						
	Top Depth (ft.) Bottom Depth (f		it.) Filter Material		Size		
Filter Pack Intervals:	15	75	G	ravel	3/8" Gravel		
	Top Depth (ft.)	Bottom Depth	n (ft.) D	Description (number of sacks & material)			
Annular Seal Data:	0	5		Cement 3 Bags/Sacks			
	5			Bentonite 3 Bag	ys/Sacks		
Seal Method: Gr	ravity		Distance to F	Property Line (ft.): 1	00+		
Sealed By: Dr	iller			otic Field or other ontamination (ft.):	V/A		
		Distance to	Distance to Septic Tank (ft.): <b>N/A</b>				
			Meth	od of Verification: E	STIMATED		
Surface Completion:	Surface Sleeve Installed			Surface Completion by Driller			
Water Level:	<b>30 ft.</b> below la	nd surface on <b>20</b>	<b>24-06-04</b> Mea	asurement Method:	Sonic/Radar		
Packers:	No Data						
Type of Pump:	No Data						
Well Tests:	Pump	Yield: 40	GPM with 0 ft. d	rawdown after 1 h	ours		

Matar Quality	Strata Depth (ft.)	Water Type				
Water Quality:	40 - 70	GOOD				
	Chemical Analysis Made:		ade: <b>No</b>	No		
	Did the driller	knowingly penetrate any strata wh contained injurious constituer				
Certification Data:	driller's direct superv correct. The driller u	hat the driller drilled this well (or the rision) and that each and all of the inderstood that failure to complete eturned for completion and resubm	statements her the required ite	rein are true and		
Certification Data: Company Information:	driller's direct superv correct. The driller u the report(s) being re	rision) and that each and all of the inderstood that failure to complete eturned for completion and resubm	statements her the required ite	rein are true and		
	driller's direct superv correct. The driller u the report(s) being re	rision) and that each and all of the inderstood that failure to complete eturned for completion and resubm	statements her the required ite	rein are true and		
	driller's direct superv correct. The driller u the report(s) being re PICKENS DRILLIN P.O. BOX 543	rision) and that each and all of the inderstood that failure to complete eturned for completion and resubm NG CO. 31	statements her the required ite	rein are true and		
Company Information:	driller's direct superv correct. The driller u the report(s) being re PICKENS DRILLIN P.O. BOX 543 HARPER, TX 7863	rision) and that each and all of the inderstood that failure to complete eturned for completion and resubm NG CO. 31	statements her the required ite hittal.	rein are true and ems will result in 54996		

## Lithology: DESCRIPTION & COLOR OF FORMATION MATERIAL

Casing: BLANK PIPE & WELL SCREEN DATA

Top (ft.)	Bottom (ft.)	Description	Dla (in.)	IVno	Material	Sch./Gage	Top (ft.)	Bottom (ft.)
0	15	SANDY TOPSOIL		Riser	New Steel		2	2
15	40	RED CLAY	4.5	4.5 Blank	New Plastic (PVC)	40	2	35
40	70	SANDSTONE AND SAND	4.5					
70	75	CLAY	4.5		New Plastic (PVC)	40	35	75

## IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

## Texas Department of Licensing and Regulation P.O. Box 12157 Austin, TX 78711 (512) 334-5540