

## STATE OF TEXAS WELL REPORT for Tracking #432446

Owner:	<b>Bob Quigley</b>	Owner Well #:	<b>No Data</b>
Address:	<b>Po Box 578 Llano, TX 78643</b>	Grid #:	<b>57-25-9</b>
Well Location:	<b>18 miles out of Llano on Hwy 2323 on right side of road Llano, TX 78643</b>	Latitude:	<b>30° 32' 14.34" N</b>
		Longitude:	<b>098° 53' 27.93" W</b>
Well County:	<b>Llano</b>	Elevation:	<b>No Data</b>

Type of Work:	<b>New Well</b>	Proposed Use:	<b>Domestic</b>
---------------	-----------------	---------------	-----------------

Drilling Start Date: **9/22/2016**      Drilling End Date: **9/22/2016**

Borehole:	<i>Diameter (in.)</i>	<i>Top Depth (ft.)</i>	<i>Bottom Depth (ft.)</i>
	<b>9</b>	<b>0</b>	<b>12</b>
	<b>6.25</b>	<b>12</b>	<b>140</b>

Drilling Method: **Air Hammer**

Borehole Completion: **Straight Wall**

Annular Seal Data:	<i>Top Depth (ft.)</i>	<i>Bottom Depth (ft.)</i>	<i>Description (number of sacks &amp; material)</i>
	<b>-2</b>	<b>12</b>	<b>Concrete 5 Bags/Sacks</b>

Seal Method: **Poured**

Sealed By: **Driller**

Distance to Property Line (ft.): **100+**

Distance to Septic Field or other  
concentrated contamination (ft.): **No Data**

Distance to Septic Tank (ft.): **No Data**

Method of Verification: **No Data**

Surface Completion:	<b>Surface Sleeve Installed</b>	<b>Surface Completion by Driller</b>
---------------------	---------------------------------	--------------------------------------

Water Level:	<b>81 ft. below land surface on 2016-09-22</b>	Measurement Method:	<b>Steel Tape</b>
--------------	--	---------------------	-------------------

Packers: **Rubber at 12 ft.**

Type of Pump: **No Data**

Well Tests: **Jetted**      **Yield: 3.5 GPM**

Water Quality:

Strata Depth (ft.)	Water Type
95 - 134	Fresh

Chemical Analysis Made: **No**

Did the driller knowingly penetrate any strata which  
contained injurious constituents?: **No**

Certification Data: The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the report(s) being returned for completion and resubmittal.

Company Information: **Magill Drilling**  
**PO Box 46**  
**Castell, TX 76831**

Driller Name: **Zane Magill**

License Number: **4168**

Comments: **No Data**

Lithology:  
DESCRIPTION & COLOR OF FORMATION MATERIAL

Top (ft.)	Bottom (ft.)	Description
0	2	Topsoil
2	8	Red Sandy Clay
8	134	Red & Tan Sandstone
134	140	Red Granite

Casing:  
BLANK PIPE & WELL SCREEN DATA

Dia (in.)	Type	Material	Sch./Gage	Top (ft.)	Bottom (ft.)
4.5	Blank	New Plastic (PVC)	sdr 17	-2	100
4.5	Screen	New Plastic (PVC)	sdr 17 0.020	100	140

**IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY**

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

**Texas Department of Licensing and Regulation**  
**P.O. Box 12157**  
**Austin, TX 78711**  
**(512) 334-5540**