

**Consolidated Testing, Inc.**710 S. Kaweah Avenue
Exeter, CA 93221-1833**Invoice**

Date	Invoice #
2/27/2020	17580

Bill ToCharlie Quinn
31161 Meadowlark
Springville, CA 93265**PAID**
03/09/2020

P.O. No.	Terms	Project
		9194-Pump Service ...

Qty	Description	Rate	Amount
	Pump Service at 31161 Meadowlark Ln, Springville, CA		
	2/14/2020		
2	Well Service Rig with 2-man crew. Set up at existing well and remove existing pump to determine well depth and static water level.	150.00	300.00
	Well Depth 188'		
	Static Water Level 40'		
	Conductor Casing Diameter 6 5/8" Steel (estimated depth 20' - 30')		
	Below conductor casing - the borehole is open without screen.		
	02/14/2020		
3	Well Service Rig with 2-man crew. Set up at existing well and install 1 1/4" steel air lift pipe inside well to develop, clean, and determine approximate well yield. CTL air lifted with 385 cfm x 200 psi portable air compressor. Well produced approximately 30 GPM during development and the water appeared clean within approximate 1 1/2 hours with the exception of small granules of weathered decomposed granite that was being loosened and extracted with the water. CTL recommends installing a PVC casing screen with gravel pack to stabilize borehole and eliminate decomposed granite from entering the well.	250.00	750.00

Total \$1,050.00**Payments/Credits** -\$1,050.00**Balance Due** \$0.00Credit Card payments over \$300.00 will be charged an additional 3% processing fee.
Please note, all invoices are Due on Receipt unless noted otherwise.
Accounting@consolidatedtesting.com

Office 559-592-3555 Fax 559-592-3553